

Routine Inspection Report

Date: 8/9/2017

Br No 607

VICTOR CREEK

Cloudy



52 F

INSPECTOR: Nick Murray

ASSISTANT: Diane Murph

Initials NMM

Initials _____



Apprh Rdwy Width (ft)	28.00
Est Camber (inch)	-0.50
Bridge Length (ft)	198.00
Bridge Width O-O (ft)	26.60
CDS Route	130000
CDS Mile	19.4

Left							
Type	BRIDGE RAIL	Ht (in)	Curb Height (in)	Transition Type	Ht (in)	Approach Type/Post	Leading End Treat
W or Thrie Beam w/ side mount & curb		30.50	9.00	W - Beam	30.50	W - Beam/Wood	BCT

Right							
Type	BRIDGE RAIL	Ht (in)	Curb Height (in)	Transition Type	Ht (in)	Approach Type/Post	Leading End Treat
W or Thrie Beam w/ side mount & curb		30.50	9.00	W - Beam	29.50	W - Beam/Wood	BCT

SIGNS			
Near End		Far End	
Lt.	Rt.	Lt.	Rt.
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Object Markers		Object Markers	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Restricted Width		Restricted Width	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Vertical Clear		Vertical Clear	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Load Limit		Load Limit	
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Name Place		Name Place	

Deck Material Thk(Inches) Concrete 5.50	Wear Surface Thk (Inches) Same	Drive Condition Satisfactory	
Location Measured Core hole	Wear Location _____	Locality Mi. 20 Seward Hwy	Route SEWARD HIGHWAY

Utilities

Kind	Size	Location	Owner
none			

Abbreviations: FE=Far End, NE=Near End, DS= Downstream, US=Upstream, LT=Left, RT=Right, P=Pier, FB=Floorbeam, G=Girder, S=Span

Bridge No. 0607, VICTOR CREEK

Work Candidates

Inspected on: 08/09/2017

<i>Priority</i>	<i>Description</i>	<i>Quantity</i>	<i>Work Needed</i>
High	Bridge-Replacement		Bridge programmed for replacement.
High	Joints-Repair (LF)	30	Replace joints. Install new Pier 3 nose armor. Patch soffit spalls adjacent to joints.
High	Paint-Structural (SF)	1	Sandblast and repaint bearings and girders near joints.
Medium	Deck-Patch spalls->Deck-Repair (Potholes) (SF)	1	Patch open core holes, spalls, and spalls patched with asphalt. Do not use asphalt for patch material.
Low	Misc-Install Sign (EA)	1	Install NE name place sign.

Bridge No. 0607, VICTOR CREEK

Element Inspection

Inspected on: 08/09/2017

<i>Element</i>	<i>Description</i>	<i>Observations</i>
12	Reinforced Concrete Deck	<p>Heavy abrasion. Deck Visual Inspection: Span 1 - 8SF patches, 1 SF spall, 2SF spall filled with asphalt. Two exposed transverse reinforcing bars at P2 Span 2 - 7SF patches Span 3 - 31SF patches, 2SF spalls Span 4 - none. Three 6 inch dia. open or partially patched core holes FE Pier 3.</p> <p>Soffit: Span 1, minor spalls along exterior girders (about 20SF). Span 2 US, two cracks with efflorescence (about 10SF). Pier 2 US and DS, 1SF spall at rail post with exposed angle. Span 3, three deck racks with efflorescence, one with rust staining (6SF each). Span 4 DS, spall at joint about 2 inches deep x 30 inches long x 4 inches wide. Exposed steel is perforated.</p>
107	Steel Open Girder/Beam	<p>Span 1 - Surface rust on bottom flanges and top flange edges. Heavy laminar rust on bottom flanges at Pier 2. Span 2 - Surface rust on top flanges and spotted surface rust on bottom flanges. Full paint loss, surface rust, and minor laminar rust near bearings. Span 3 - Surface rust on top and bottom flanges. Span 4 - Bottom flange surface rust throughout. Heavy surface rust, laminar rust, and pack rust at hinges.</p>
> 515	Steel Protective Coating	
210	Reinforced Concrete Pier Wall	<p>Pier 2 NE face multiple hairline cracks half height. One full height cracked measured at 0.040in. Pier 3 NE, two hairline cracks full-width about mid-height and 1 full-height hairline crack. Pier 3 NEDS, 2SF spall with exposed rebar at footing. Pier 3 FE, two cracks full width about mid-height. US side is 3/16 inch wide for about 6ft. Pier 3 FE, one full-height hairline crack. Pier 3 US footing exposed about 3ft deep and 4ft wide. Remaining length 1.5 feet deep. As-builts indicate footing is pile supported. Pier 4 NE, 1SF spall near mudline. Pier 4 FE, full-width hairline crack at construction joint. US side is about 0.3 inches wide for about 5ft.</p>
> 6000	Scour	
215	Reinforced Concrete Abutment	<p>NEDS, minor wingwall spall. 40 inch long x 5 inch high x 40 inch deep void under NE cap near centerline. NEDS and FEUS 8ft vertical banks for about 200ft starting at bridge.</p>
> 6000	Scour	
301	Pourable Joint Seal	<p>Various segments failed at each joint. Remaining sections are cracked. Pier 3 DS, angle armor missing for about 9ft. Attachments exposed but appear below deck surface.</p>

Bridge No. 0607, VICTOR CREEK

311	Movable Bearing	Span 2 bearings rocked toward NE; DS girder web is in contact with Pier 2 stemwall. Minor laminar rust on bearings. Moderate laminar rust on anchor rods.
> 515	<i>Steel Protective Coating</i>	
313	Fixed Bearing	Surface rust throughout.
> 515	<i>Steel Protective Coating</i>	
330	Metal Bridge Railing	100% w-beam surface rust on road face, 25% on back face. Minor coating loss on posts. NEDS, 6 inch dia. curb spall. Pier 2 DS, curb spalled with exposed rebar for about 4ft. Span 2 DS midspan rail damage. Post is bent outward but anchorages are intact. FEUS, minor exterior curb spall.
> 515	<i>Steel Protective Coating</i>	
600	Signs Smart Flag	NE name place sign is missing.
601	Brush Smart Flag	Brush encroaching approach rail and NEUS bridge rail.
607	Seismic Retrofit Smart Flag	Longitudinal restrainers in good conition. FE bearing plate gap about 1 inch.

Br No 607

VICTOR CREEK

Date: 8/9/2017

ID

07 Odd 2017 607

INSPECTOR: Nick Murray

ASSISTANT: Diane Murph

Weather
Cloudy

Temperature
52 F

HYDRAULICS REPORT

Inspection To Mudline At All Piers and Abuts?

Yes

Apparent HW

No

Stream
Bottom
Material

AHW Comments

Bank Erosion

Yes

Silt

Erosion Comments

8 ft vertical banks NE DS for 200+ feet
as well as FE US for 200+ ft.

Sand

Activities

Drift Comments

12" tree at US P3 has collected smaller
branches and debris.

Gravel

Drift

Medium

Riprap Condition

Minimal

Other Hydraulic
Comments

No soundings taken due to high traffic, limited sight
distance and impending bridge replacement.

SOUNDINGS

Measured At Surface

Location

Upstream

Structure Inventory and Appraisal Sheet (English Units)

Bridge Key: 0607

Agency ID: 0607

SR: 40.0

SD/FO: ND

IDENTIFICATION

State 1: 02 Alaska Struc Number 8: 0607
 Facility Carried 7: SEWARD HIGHWAY Location 9: MILE POINT 19.4
 Rte.(On/Under)5A: Route On Structure Rte Signing Prefix 5B: 3 State Hwy
 Level of Service 5C: 1 Mainline Rte. Number 5D: 00031
 Directional Suffix 5E: 0 N/A (NBI) % Responsibility:
 SHD District 2: 01 Central County Code 3: Kenai Peninsula Borough
 Place Code 4: Seward Mile Post 11: 19.435 mi
 Feature Intersected 6: VICTOR CREEK
 Latitude 16: 60d 21' 27.0 " Longitude 17: 149d 21' 6.0 "
 Border Bridge Code 98: Unknown (P)
 Border Bridge No. 99: NA

INSPECTION

Frequency 91: 24 months Inspection Date 90: 08/09/2017 Next Inspection: 08/09/2019
 FC Freq. 92A: NA FC Insp. Date 93A: NA Next FC Inspection: NA
 UW Freq. 92B: NA UW Insp. Date 93B: NA Next UW Inspection: NA
 SI Freq. 92C: NA SI Date 93C: NA Next SI: NA

CLASSIFICATION

Defense Highway 100: 1 STRAHNET hwy Parallel Structure 101: No || bridge exists
 Traffic Direction 102: 2 2-way traffic Temporary Structure 103: Unknown (NBI)
 Highway System 104: 1 On the NHS NBIS Length 112: Long Enough
 Toll Facility 20: 3 On free road Functional Class 26: 02 Rural Arterial-Other
 Natl. Network 110: 0 Not on truck network Historical Sig. 37: 5 Not eligible for NRHP
 Owner 22: 01 State Highway Agency
 Custodian 21: 01 State Highway Agency

STRUCTURE TYPE AND MATERIALS

Number of Approach Spans 46: 0 Number of Spans Main Unit 45: 4
 Main Span 43A/B: 3 Steel 2 Stringer/Girder
 Appr Span 44A/B: 0 Other 00 Other
 Deck Type 107: 1 Concrete Cast-in-Place
 Wearing Surface 108A: 1 Monolithic Concrete
 Membrane 108B: 0 None
 Deck Protection 108C: 0 None

CONDITION

Deck 58: 5 Fair Super 59: 5 Fair Sub 60: 5 Fair
 Channel/Ch. Protection 61: 6 Bank Slumping Culvert 62: N N/A (NBI)

LOAD RATING AND POSTING

Inventory Method 65: 1 LF Load Factor Operating Method 63: 1 LF Load Factor
 Inventory Rating 66: HS 12 Operating Rating 64: HS 25
 Design Load 31: 3 Posting 70: 5 At/Above legal loads
 Posting Status 41: A Open, no restriction

AGE AND SERVICE

Year Built 27: 1952 Year Reconstructed 106: Unknown
 Type of Service on 42A: 1 Highway
 Type of Service under 42B: 5 Waterway
 Lanes on 28A: 2 Lanes under 28B: 0 Detour Length 19: 124 mi
 ADT 29: 1,942 Truck ADT 109: 9% Year of ADT 30: 2015

APPRAISAL

Bridge Rail 36A: 0 Substandard Approach Rail 36C: 1 Meets Standards
 Transition 36B: 0 Substandard Approach Rail Ends 36D: 0 Substandard
 Str Evaluation 67: 5 Somewhat Better than Min Deck Geometry 68: 4 Min Tolerable
 Underclearance, Vertical and Horizontal 69: N Not applicable (NBI)
 Waterway Adequacy 71: 8 Equal Desirable Approach Alignment 72: 6 Equal Min Criteria
 Scour Critical 113: 3

GEOMETRIC DATA

Length Max Span 48: 70 ft Structure Length 49: 198 ft
 Curb/Sdwk Width L 50A: 1.0 ft Curb/Sidewalk Width R 50B: 1.0 ft
 Width Curb to Curb 51: 24.3 ft Width Out to Out 52: 26.6 ft
 Approach Roadway Width 32: 28 ft Median 33: 0 No median (w/ shoulders)
 Deck Area: 5,263.6 sq ft
 Skew 34: 45 Structure Flared 35: 0 No flare
 Vertical Clearance 10: 99.99 ft Horizontal Clearance 47: 23 95 ft
 Minimum Vertical Clearance Over Bridge 53: 100.0 ft
 Minimum Vertical Underclearance 54A: N Feature not hwy or RR
 Minimum Vertical Underclearance 54B: 0.0 ft
 Minimum Lateral Underclearance 55A: N Feature not hwy or RR
 Minimum Lateral Underclearance R 55A: 99.9 ft
 Minimum Lateral Underclearance L 56: 0.0 ft

PROPOSED IMPROVEMENTS

Bridge Cost 94: \$0 Type of Work 75: Unknown (P)
 Roadway Cost 95: \$0 Length of Improvement 76: 0.0 ft
 Total Cost 96: \$0 Future ADT 114: 2 200
 Year of Cost Estimate 97: Unknown Year of Future ADT 115: 2035

NAVIGATION DATA

Navigation Control 38: 0 Permit Not Required
 Vertical Clearance 39: 0.0 ft Horizontal Clearance 40: 0.0 ft
 Pier Protection 111: 1 Not required Lift Bridge Vertical Clearance 116: 0.0 ft



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	1
	Ahead at bridge				



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	2
	Back at bridge				



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	3
	Looking US				



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	4
	Looking DS				



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **5**
Looking NE US



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **6**
Looking NE DS



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **7**
Looking FE DS



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **8**
Looking FE US



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **9**
US NE elevation



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **10**
US FE elevation



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **11**
DS elevation



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **12**
DS NE undercutting along bank



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	13
			FE US undercutting along bank		



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	14
			DS NE rail spall		



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	15
			DS NE expansion joint		



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	16
			DS Pier 2 expansion joint		



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	17	
Expansion joint 2 exposed rebar at centerline					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	18	
DS Pier 3 expansion joint					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	19	
DS Pier 4 expansion joint					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	20	
DS FE expansion joint					



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **21**
DS Abutment 1



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **22**
Bearing, typ.



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **23**
DS pier 2 concrete and girder contact



Bridge No. **0607** Br. Name **Victor Creek** Date **08/09/17**
 Inspector **Murray / Murph** Frame **24**
NE underside, typ.



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	25	
Connection joint, typ.					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	26	
US NE spalling along expansion joint					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	27	
NE face Pier 2					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	28	
NE face Pier 2 cracks					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	29	
NE face Pier 2 crack 10' from DS					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	30	
DS FE face Pier 2					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	31	
NE face Pier 3					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector	Murray / Murph		Frame	32	
DS NE face pier 3 spall with exposed rebar					



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	33
			FE face pier 3		



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	34
			NE face pier 4		



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	35
			FE face pier 4		



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	36
			Abutment 5		



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	37
	Span 4 DS joint failure				



Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	38
	FE underside, typ.				

Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	39

Bridge No.	0607	Br. Name	Victor Creek	Date	08/09/17
Inspector			Murray / Murph	Frame	40