



Alaska DOT&PF

Data Modernization and Innovation Office

Pavement Management and Preservation

5800 East Tudor Road, Anchorage AK 99507-1286

Pavement Inspection Report Akutan Airport




Airport Name	IATA	ICAO	Latitude	Longitude	Elevation (ft)
Akutan Airport	7AK	PAUT	54° 8' 40.6" N	165° 36' 14.79" W	129.3


Please refer all questions or for further information about this report, please contact the AKDOT&PF Pavement Management and Preservation Office as follows:


Point of Contact	Phone	Email	Date Inspected	Date Published
Mr. Andrew Pavey, Pavement Management Engineer	(907) 269 6213	andrew.pavey@alaska.gov	June 2024	June 2025


TABLE OF CONTENTS

- Airport Maps
 - Pavement Condition Index (PCI)
 - Sample Unit PCI
 - 5-Year Predicted PCI
 - 10-Year Predicted PCI
 - Pavement Age at Inspection
 - Pavement Crack Seal Condition
- Airport Pavement Inspection Notes by Branch
- Branch Condition Report
- Branch Use Condition Report
- Section Condition Report
- Section Condition Report (Summary by Age Category)
- Work History Report
- Physical Property Data Table
- Pavement Classification Rating (PCR)
- References










Map image is the intellectual property of Esri and is used herein under license. Copyright © 2020 Esri and its licensors. All rights reserved




Akutan Airport

Airport Code: 7AK
Site Number: 50022.1*A

Pavement Age at Inspection



2024 Pavement Inspection Results



Map Created by Duval Engineering
for AK DOT&PF



Crack Seal Condition (CSC)

No CS - New Surface

Has CS - Good

Has CS - Touch Up



No CS - Recommend CS

Has CS - Replace



No CS - Below Repair

PCC - Concrete

AIRPORT PAVEMENT INSPECTION NOTES BY BRANCH

Branch ID	Branch Name	Branch Use	No. of Sections	Area (sf)	Weighted Average PCI
0100	Taxiway	Taxiway	1	25,148	80
					

The taxiway was initially constructed in 2012 and has not undergone major work since. The most common distresses observed are low to high severity raveling and low severity weathering. Field observations include further deterioration of the top layer of asphalt which is contributing to higher quantity and severity raveling throughout the branch. In contrast, it is noteworthy that no cracking was recorded during the inspection, suggesting that while the surface layer is deteriorating, the underlying structural layers are in relatively good condition.

Branch ID	Branch Name	Branch Use	No. of Sections	Area (sf)	Weighted Average PCI
4100	Apron	Apron	1	83,300	82
					

The apron was initially constructed in 2012 and has not undergone major work since. The most common distresses observed are low severity raveling and low to medium severity weathering. Field observations include further deterioration of the top layer of asphalt which is contributing to higher quantity and severity raveling and weathering throughout the branch. In contrast, it is noteworthy that no cracking was recorded during the inspection, suggesting that while the surface layer is deteriorating, the underlying structural layers are in relatively good condition.

Branch ID	Branch Name	Branch Use	No. of Sections	Area (sf)	Weighted Average PCI
6100	Runway 09/27	Runway	1	337,500	90
					
			 		

Runway 09/27 was initially constructed in 2012 and has not undergone any major work since. The most common distresses observed are low to high severity raveling and low severity weathering. Field observations include further deterioration of the top layer of asphalt which is contributing to higher quantity and severity raveling throughout the branch. Additionally, the paving joints are beginning to open, leading to the formation of linear cracks. Crack sealing may be warranted to mitigate the risk of Foreign Object Debris (FOD), which could pose a hazard to aircraft operations.

BRANCH CONDITION REPORT

Branch ID	No. of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (Sq Ft)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
0100	1	617	35	25,148	TAXIWAY	80.00	0.00	80.00
4100	1	340	245	83,300	APRON	82.00	0.00	82.00
6100	1	4,500	75	337,500	RUNWAY	90.00	0.00	90.00

Note: the dimensions in the Branch Condition Report are derived from area calculations and may not reflect actual dimensions of individual sections. Refer to the maps for actual section dimensions.

BRANCH USE CONDITION REPORT

Use Category	No. of Sections	Total Area (Sq Ft)	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
APRON	1	83,300	82.00	0.00	82.00
RUNWAY	1	337,500	90.00	0.00	90.00
TAXIWAY	1	25,148	80.00	0.00	80.00
ALL	3	445,948	84.00	4.32	87.94

SECTION CONDITION REPORT

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	True Area (Sq Ft)	Last Inspection Date	Age At Inspection	PCI
0100	0100-01	8/31/2012	AC	TAXIWAY	T	25,148	6/10/2024	12	80
4100	4100-01	8/31/2012	AC	APRON	T	83,300	6/10/2024	12	82
6100	6100-01	8/31/2012	AC	RUNWAY	T	337,500	6/10/2024	12	90

SECTION CONDITION REPORT (SUMMARY BY AGE CATEGORY)

Age Category	Average Age at Inspection	Total Area (Sq Ft)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
11-15	12	445,948	3	84.00	4.32	87.94
ALL	12	445,948	3	84.00	4.32	87.94

Work History Report <i>Pavement Database: Alaska</i>	Page 1 of 2
--	--------------------

Network: Akutan Airport		Branch: 0100		Taxiway		Section: 0100-01		Surface: AC	
L.C.D. 8/31/2012		Use: TAXIWAY		Rank: T		Length: 617.00 (Ft)		Width: 35.00 (Ft) True Area: 25148 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
8/31/2012	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" HMA, 7" Base, 12" Subbase (Fund			

Network: Akutan Airport		Branch: 4100		Apron		Section: 4100-01		Surface: AC	
L.C.D. 8/31/2012		Use: APRON		Rank: T		Length: 340.00 (Ft)		Width: 245.00 (Ft) True Area: 83300 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
8/31/2012	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" HMA, 7" Base, 12" Subbase (Fund			

Network: Akutan Airport		Branch: 6100		09/27		Section: 6100-01		Surface: AC	
L.C.D. 8/31/2012		Use: RUNWAY		Rank: T		Length: 4,500.00 (Ft)		Width: 75.00 (Ft) True Area: 337500 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
8/31/2012	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" HMA, 7" Base, 12" Subbase (Fund			

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
New Construction - Initial	3	445,948.00	0.00	0.00

PHYSICAL PROPERTY DATA

		Pavement		Base		Subbase		Subgrade	
Branch ID	Section ID	Thick (in)	Type	Thick (in)	Type	Thick (in)	Type	Type	CBR
Taxiway 100	0100-01	4	P-401	7	P-209	6	P-154	Shot Rock	26
Apron 4100	4100-01	4	P-401	7	P-209	6	P-154	Shot Rock	26
Runway 9/27 6100	6100-01	4	P-401	7	P-209	6	P-154	Shot Rock	26

Notes: Alaska DOT&PF construction records show that the shot rock layer is 24 inches thick. Information about underlying layers was not available, so the shot rock layer is reported as subgrade.

AIRCRAFT FLEET MIX

No.	Aircraft	Gross Wt (lb)	% Gross Wt on Main Gear	Tire Pressure (psi)	Annual Departures	20 Yr Coverages
1	PA-31-325 Navajo C/R	6,536	95.0	66	778	6,273
2	D-15	17,120	95.0	63	24	264
3	Beech King Air B200	12,590	95.0	98	170	1,801
4	C-130	155,000	95.0	105	12	264

PAVEMENT CLASSIFICATION RATINGS

Runway	Critical Aircraft	Max Allowable Wt (lb)	Subgrade Mr (psi)	Evaluation Thickness (in)	Pass to Traffic Cycle Ratio	PCR
9-27	C-130	1,662,270	39,000	23.0	1.0	253/F/A/X/T

PCR CALCULATION NOTES

- 1% traffic growth assumed
- Subgrade strength reduction for frost applied
- D-15 refers to “generic” dual gear aircraft as modeled in FAARFIELD
- Computed PCR using FAARFIELD deemed excessive. PCR reduced to ACR of C-130 based on Using Aircraft Method (see FAA AC 150/5335-5D, para. 4.3).

REFERENCES

Year	Project No.	Document Title
2010	3-02-005-02, 51196	Design-Build