



















General Information

- Maximum heating temperature is 400F
- Most polymers will start to break down over 400F
- If the material is not going to be used then reduce heat
- The polymer must be listed on the MSDS for the product.



