



Scale 1"=50'

Major repairs done to 10' float under the gangway after gangway skid plate kicked out & gangway went thru deck - as tide came in, gangway broke float in half

Minor repairs were also taken care of wherever encountered

All new decking & bullrail is 0.5\* penta treated

Approx. 250 yds. of 12" minus riprap placed along shoulders of boat launching ramp

AS BUILT

SKAGWAY FLOAT RECONSTRUCTION  
C.O. to PROJ. NO. 6-77157  
DEC. 1976

SKAGWAY HARBOR LAYOUT