Yakutat Airport

Age of Pavement at 2001 Inspection



Yakutat Airport

Age of Pavement

- 0 - 5
- 6 - 10
- 11 - 15
- 16 - 20
- 21 - 25
- 26 - 30
- > 30

Age of Pavement in Years

Minimum PCI for Runway = 70
Minimum PCI for Taxiway and Aprons = 60

[ ] Branch Identifier
Airport Code: YAK
Site No. 50825.1*A