



ANC TAXIWAY M,L,E,  
AND E2 SEAL COAT

OTHER PROJECTS NOT SHOWN

- R 7 & 8 JOINT REPAIR
- HORIZONTAL INFRASTRUCTURE EARTHQUAKE REPAIRS
- ANC PERIMETER FENCE REPAIR
- ANC ELECTRONIC TERMINAL GUIDANCE SIGNS
- GATE N10 ACCESS CONTROL IMPROVEMENTS

RUNWAY 25R EAST RSA  
DRAINAGE IMPROVEMENTS

## 2020 PROPOSED AIRPORT CONSTRUCTION PROJECTS\*

\*DRAFT CONSTRUCTION SCHEDULE - SUBJECT TO CHANGE

## **2020 ANC CONSTRUCTION PROJECTS**

### ***ANC Runway 25R East Safety Improvements***

#### *Project Description*

Remove ground obstructions in Runway 25R primary and transitional CFR Part 77 surfaces. Regrade turfed area east of Runway 25R to eliminate storm water ponding. Replace approximately 1,500 feet of perimeter fence along Jewel Lake.

### ***Taxiways M, L, E and E2 Surface Seal***

#### *Project Description*

Apply surface sealant rejuvenator to Taxiways M, L, E and E2.

### ***ANC Horizontal Infrastructure 2018 Earthquake Repairs***

#### *Project Description*

Repair roadways, pathways, and drainage structures damaged by the 2018 earthquake.

### ***ANC Electronic Terminal Guidance Signs***

#### *Project Description*

Remove four existing terminal guidance signs along International Airport Road and replace with two electronic terminal guidance signs.

### ***Gate N10 Access Control Improvements***

Project Description

Install additional security fencing and automated inbound and outbound vehicle gates. Re-align existing fencing between N10 and the Taxiway V gate.

***ANC RON 7 & 8 Joint Repairs***

Project Description

Remove and replace approximately 15,300 feet of liquid joint seal and perform approximately 130 square feet of elastomeric concrete repairs on RON 7 & 8 aircraft parking hardstands.