

Alaska Airport Needs Directory

**Department of Transportation
&
Public Facilities**

As of: February 1, 2015



ADAK ISLAND (ADK)

Runway(s): 05/23 - 7790' x 200'
18/36 - 7605' x 200' **Surface:** Asphalt/Grooved **Lighting:** BCN/HIRL/REIL/PAPI
NAVAIDS: TACAN/DME/NDB

Classification: Community	# Enplanements: 2023	Borough: Aleutians West
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 3,318
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 0
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement:

Airfield Manager: VINCE TUTIAKOFF, 907-592-8026

NEEDS:

Surfaces:

- Major pavement repair/rehabilitation needed
- Vehicle gates with electronic swipe capability
- Terminal ramp fencing repairs/replacement
- Water pump automation is not working and is on manual by Rwy 36W approach

Dimensional:

- Extend RSA on both runways

Facilities:

- SRE building upgrades
- Traffic control gates
- Installation of FAA weather cameras

Equipment:

- loader, sweeper, plow with attachments, new radios (9) for SRE equipment
- Badging computer, software upgrade and printer
- ARFF bunker gear
- Skid steer with attachments

Comments:

- Crosswind runway will be shut down sometime in 2015.
- Adak Runway Safety Improvements (54972) is in Design Status to improve RSA for both runways to conform to FAA standards by end of 2015.

AKHIOK (AKK)

Runway(s): 04/22 - 3120' x 50'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 955

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 15,438

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1985

Airfield Manager: ROBERT GREENE, 907-487-4952

NEEDS:

Surfaces:

Runway, taxiway, and apron pavement rehabilitation

Improve runway to accommodate additional use

Rehabilitate/resurface access road (GF)

Lower access road profile to mitigate airspace obstructions

Relocate taxiway and apron

Construct and relocate new apron to provide offsets for non-precision approaches

Dimensional:

Expand the existing runway to 3,300' x 60'

Remove OFA/OFZ penetrations

Facilities:

Demolish existing SREB

Relocate new 2-bay SREB

Equipment:

Loader

Comments:

Install taxiway edge lighting

Install PAPI, REIL, and navigation lighting aids

Acquire 21 acres of property to control expanded airspace

AKIACHAK (Z13)

Runway(s): 01/19 - 3300' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/MIRL

NAVAIDS: N/A

Classification: Community

Enplanements: 2928

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 100

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 36,980

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Scarify, reshape and recompact surfacing material runway and apply dust palliative

Dimensional:

Facilities:

Equipment:

Comments:

AKIAK (AKI)

Runway(s): 03/21 - 3196' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2104

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 15,680

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1998

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Runway, taxiway, and apron pavement rehabilitation

Scarify, reshape and recompact surfacing material runway and apply dust palliative

Dimensional:

Facilities:

Provide a new SREB

Equipment:

Loader and grader with attachments

Comments:

AKUN / AKUTAN (7AK)

Runway(s): 09/27 - 4500' x 75'

Surface: Asphalt

Lighting: BCN/App_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 340

Borough: Aleutians East

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 55

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 706,984

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2012

Airfield Manager: DALE RUCKMAN, 907-581-1786

NEEDS:

Surfaces:

Sand seal taxiway and apron

Maintain pavement markings and crack seal

Dimensional:

Facilities:

Power generator controllers (UPS)

Employee quarters

Equipment:

4x4 utility truck

Comments:

Obstruction removal (GF)

ALAKANUK (AUK)

Runway(s): 16/34 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 3152

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 113,277

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2011

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Loader Wheeled 1.5 CY -- \$350,000

U-Blade Loader 5 CY -- \$350,000

Comments:

ALEKNAGIK (5A8)

Runway(s): 15/33 - 2040' x 80'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 25

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 28,269

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Brush removal (per ALP)

Dimensional:

Extend current runway to 3,000'

Facilities:

Construct a new SREB

Equipment:

Rural grader

Comments:

Intent to close or transfer airport to community once Aleknagik wood river bridge is constructed connecting Aleknagik to Dillingham

Construct a new float plane dock

Install runway lighting system

Non-standard conditions must be corrected per ALP

Runway 15/33 NSTD markings need improvement (per ALP)

ALLAKAKET (6A8)

Runway(s): 05/23 - 4000' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1801

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 2,821

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 127,414

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dust Palliative -- \$250,000

Dimensional:

Facilities:

Allakaket SRE Building Replacement -- \$2,000,000

Lighted Supplemental Windcone -- \$70,000

PAPI and WX Reporting Needed -- FAA

Survey , Clear Obstructions & Mark Property Boundary -- \$100,000

Equipment:

Snowplow Grader -- \$350,000

Dozer Crawler 10-15T -- \$350,000

Compactor -- \$40,000

Comments:

SREB - Gravel floor, poor lighting and heating systems, substandard fuel system, and inefficient building.

AMBLER (AFM)

Runway(s): 18/36 - 3000' x 60'
09/27 - 2400' x 60'

Surface: Gravel
NAVAIDS: NDB

Lighting: BCN/VASI/Rwy_Lts

Classification: Community

Enplanements: 1971

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 2,068

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 97,301

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1989

Airfield Manager: ALVIN WERNEKE, 907-442-3147

NEEDS:

Surfaces:

Ambler Airport Improvements -- \$15,200,000

Dimensional:

Facilities:

Ambler SRE Building Replacement -- \$2,000,000

Ambler Access Road Improvements -- \$5,500,000

Equipment:

Snowplow Grader -- \$350,000

Dozer Crawler 10-15T -- \$350,000

Comments:

Extend the main and crosswind runway, rehab the operational surfaces and safety area and upgrade the lighting.

ANCHORAGE (ANC) - Ted Stevens Anchorage Intl

Runway(s): 7R/25L - 12400' x 200'
7L/25R - 10600' x 150'
15/33 - 11584' x 150'

Surface: Conc/Asph/Grvd
NAVAIDS: ILS/DME/VOR

Lighting: BCN/App-Rwy_Lts/HIRL/
REIL/PAPI

Classification: International	# Enplanements: 2325030	Borough: Anchorage
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 113,433,532
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$ 62,437,178
Part 139 Cert: Yes	On/Off Road: On	Last Major Improvement: 2014

Airfield Manager: JOHN PARROTT, 907-266-2525

NEEDS:

Surfaces:

Pavement maintenance including runway and taxiway rehab

Dimensional:

Additional runway widening and taxiway widening to meet DGVI standards

Facilities:

Equipment:

Regular planned vehicle fleet replacement

Comments:

ANCHORAGE (Z41) - Lake Hood Strip

Runway(s): 14/32 - 2200' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Anchorage

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 0

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2006

Airfield Manager: JOHN PARROTT, 907-266-2525

NEEDS:

Surfaces:

Separation of aircraft and auto traffic on Floatplane Drive

Dimensional:

None

Facilities:

Equipment:

Comments:

ANCHORAGE SPB (LHD) - Lake Hood SPB

Runway(s): N/S, E/W, NW/SE - 4540'
Surface: Water
NAVAIDS: N/A

Lighting: BCN

Classification: Local	# Enplanements: 24026	Borough: Anchorage
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 832,490
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 4,700,123
Part 139 Cert: No	On/Off Road: On	Last Major Improvement: 2011

Airfield Manager: JOHN PARROTT, 907-266-2525

NEEDS:

Surfaces:

Additional bank stabilization

Dimensional:

Facilities:

Equipment:

Comments:

ANGOON SPB (AGN)

Runway(s): NW/SE - 10000' x 900'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 1734

Borough: Hoonah-Angoon

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 550

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 3,120

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1987

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

ANIAC (ANI)

Runway(s): 10/28 - 6000' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/VASI/Seq
NAVAIDS: ILS/DME/NDB Flshr

Classification: Regional **# Enplanements:** 14334 **Borough:** Bethel
Air Carrier Hub: Yes **Medical Facility:** Yes **Annual Revenue:** \$ 74,429
USPS Hub: Yes **School Facility:** Yes **Ops Cost/Yr:** \$ 410,020
Part 139 Cert: No **On/Off Road:** Off **Last Major Improvement:** 1995

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

- Pavement rehab/improvement
- Crack sealing on runway, taxiways, & apron
- Correct pavement markings on runway, taxiways, & apron
- Improve RSA
- Construct helipad, floatplane ramp, and crosswind runway
- Vehicle gates with push button electric
- Perimeter fencing repairs/replacement

Dimensional:

- Remove 20:1 penetrations
- Expand apron

Facilities:

Equipment:

- grader, sweeper, snow plow, snow blower

Comments:

ANVIK (ANV)

Runway(s): 17/35 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: NDB

Classification: Community

Enplanements: 962

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 1,370

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 83,595

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2004

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Anvik Airport Improvements -- \$8,000,000

Dimensional:

Facilities:

Anvik SRE Building Replaceemnt -- \$2,000,000

Equipment:

U-Blade Loader 5CY -- \$350,000

Loader Wheeled 2CY -- \$350,000

Comments:

Resurface runway, apron and taxiway, and upgrade lighting.

ATKA (AKA)

Runway(s): 16/34 - 4500' x 100' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/REIL
NAVAIDS: N/A

Classification: Community	# Enplanements: 131	Borough: Aleutians West
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 34,188
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2008

Airfield Manager: DALE RUCKMAN, 907-581-1786

NEEDS:

Surfaces:

- Maintain pavement markings (M&O SPM)
- Sand seal taxiway and apron
- Maintain crack seal

Dimensional:

Facilities:

- Installation of FAA weather cameras

Equipment:

Comments:

- Install REIL and PAPI lighting

ATMAUTLUAK (4A2)

Runway(s): 15/33 - 3000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 2500

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 12,882

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2002

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Place E-1 to reshape crown and compact with vibratory roller

Apply dust palliative

Dimensional:

Facilities:

Construct a 1-bay heated SREB with floor

Equipment:

Grader with attachments

Comments:

BARANOF SPB (BNF) - Warm Spring Bay

Runway(s): E/W - 10000' x 1000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Wrangell

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

BARROW (BRW) - Wiley Posts/Will Rogers Memorial

Runway(s): 07/25 - 7100' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN, HIRL, REIL, MALSR
NAVAIDS: ILS/DME/NDB/VOR

Classification: Regional	# Enplanements: 51568	Borough: North Slope
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 162,577
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$ 1,662,525
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2010

Airfield Manager: JOHN OLSEN, 907-852-6199

NEEDS:

Surfaces:

Barrow Apron Expansion -- \$12,000,000
Barrow Airport Runway Surface Repairs -- \$3,600,000 Barrow Airport Stormwater
Management Plan -- \$100,000 Barrow Airport South Side Parallel Taxiway -- \$40,000,000
Barrow Airport Runway Surface Repairs -- \$3,600,000

Dimensional:

Facilities:

Barrow SREB/ARFF Building Replacement -- \$13,500,000
Barrow Deicing Chemical Storage Building -- \$3,000,000
Barrow Airport Security Upgrades -- \$2,500,000
Barrow Ahkovak Road Improvements (FHWA Funding) -- \$7,700,000

Equipment:

Broom Runway Towed (22'+ width) -- \$800,000
Blower 7,500 Ton Per Hour -- \$800,000
Deice Chemical Applicator Truck - \$400,000
Runway Light Cleaning Plow -- \$130,000
Airport Operations Vehicle - \$80,000

Comments:

Apron Exp-Construct apron and aviation support area expansion. Runway Surface Repairs-Complete surface repairs to address dips on the west end of the runway and longitudinal cracking.

BASIN CREEK

Runway(s): 16/34 - 2000' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Nome

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Acquire 110 acres of land at the Basin Creek Airport.

BEAVER (WBQ)

Runway(s): 05/23 - 3934' x 75'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 943

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 1,639

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 101,431

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1988

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Beaver Airport Improvements ---\$9,000,000

Dimensional:

Facilities:

Beaver SRE Building Replacement -- \$2,000,000

Lighted Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

PAPI and WX Reporting Needed -- FAA

Equipment:

Rural Airport Grader -- \$350,000

Brush Cutter -- \$130,000

Compactor -- \$40,000

Comments:

Resurface runway and taxiway, expand the apron, apply a dust palliative, and install new lighting.

BETTLES (BTT)

Runway(s): 01/19 - 5190' x 150'

Surface: Turf/Gravel

Lighting: BCN/MIRL/MALSR/VASI

NAVAIDS: VOR/ILS/DME

Classification: Local

Enplanements: 2079

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 46,296

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 127,873

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1988

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Bettles Airport Rehabilitation -- \$2,000,000

Bettles Airport Paving -- \$4,000,000

Dimensional:

Facilities:

Equipment:

Loader Mounted Snow Blower -- \$150,000

Brush cutter -- \$130,000

Comments:

Resurface the runway, apron and taxiway, upgrade the lighting, remove obstructions and complete grading and drainage improvements. Expand apron, designate a helicopter operations area, increase transient parking availability and remove aircraft parking spaces within the OFA.

BETTLES SPB (2A4)

Runway(s): 14/32 - 4100' x 200'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Bettles VOR Lake SPB Improvements -- \$3,000,000

Dimensional:

Facilities:

Equipment:

Boom Mower Attachment for Road ROW Clearing -- \$70,000

Comments:

Refurbish the water lane, lease lots and access road to accommodate additional aviation operations, including lease lot development, apron and access road improvements and water lane dredging.

BIG LAKE (BGQ)

Runway(s): 07/25 - 2435' x 70'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: VORTAC

Classification: Local

Enplanements:

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 43,275

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 20,057

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: STEVE BANSE, 907-745-2159

NEEDS:

Surfaces:

Runway paving

Construct a GA apron with gravel surface adjacent to airport

Construct taxiways between apron and runway

Minor gravel resurface and dust control (M&O SPM)

Dimensional:

Extend taxiway to the east

Expand apron, Shift R/W to east and south, increase number of lease lots, new Design Survey datums

Facilities:

Construct a 2-bay heated SREB, Replace lighting system,

Equipment:

Loader and 16' snow blade

Comments:

Install fencing (GF)

Improve drainage (GF)

Extend lease lot access road (GF)

Install 2,000' of ditch to improve drainage

Remove obstructions in the RPZ to the west end of the runway

Flood mitigation

Airport planning study underway in 2015

BIRCH CREEK (Z91)

Runway(s): 16/34 - 4000' x 75'

Surface: Gravel

Lighting: BCN/MIRL

NAVAIDS: N/A

Classification: Local

Enplanements: 290

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 57,009

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Birch Creek Airport Improvements -- \$12,000,000

Dimensional:

Facilities:

Birch Creek SRE Building Replacement -- \$2,000,000

Lighted Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

PAPI, WX Reporting and WX Cameras Needed - FAA

Equipment:

Compactor -- \$40,000

Brush cutter -- \$130,000

Comments:

Resurface runway and taxiway, expand apron, apply a dust palliative and install new lighting.

BIRCHWOOD (BCV)

Runway(s): 2L/20R - 4010' x 100'
2R/20L - 2200' x 50' **Surface:** Asphalt **Lighting:** BCN/Rwy_Lts/VASI
NAVAIDS: N/A

Classification: Local	# Enplanements:	Borough: Anchorage
Air Carrier Hub: No	Medical Facility: No	Annual Revenue: \$ 197,682
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 50,578
Part 139 Cert: No	On/Off Road: On	Last Major Improvement: 2012

Airfield Manager: ED CARESS, 907-338-1426

NEEDS:

Surfaces:

- Expand northwest apron, rehabilitate apron and taxiway
- Construct new gravel runway 02S/20S and new ultralight runway
- Relocate taxiway A, construct taxiway D
- Rehabilitate northeast apron and taxiway pavement
- Repair/replace fencing and gates; Maintain pavement markings and crack seal

Dimensional:

- Remove Part 77 obstructions

Facilities:

Equipment:

Comments:

- Right of Way & lease lot acquisition(GF)
- Improve lease lot access (GF)
- Brush cutting, tree removal, fence/gate repair
- Acquire property for RPZs and land use compatibility
- Relocate security fencing on southern end of RPZ for runway 02
- Install/replace security fencing around expanded northwest apron
- Airport roadway pavement rehabilitation
- Development of new lease lots, security gate installation
- Update the airport master plan
- Obstruction removal

BOUNDARY (BYA)

Runway(s): 05/23 - 2325' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 1

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 0

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1989

Airfield Manager: DENNIS BISHOP, 907-883-5128

NEEDS:

Surfaces:

Boundary Airport Improvements -- \$4,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Resurface runway, apron, and taxiway, apply a dust palliative, and replace airport signage.

BREVIK MISSION (KTS)

Runway(s): 11/29 - 2990' x 100' 04/22 - 2110' x 75'	Surface: Gravel NAVAIDS: N/A	Lighting: BCN/Rwy_Lts/PAPI
Classification: Community	# Enplanements: 1722	Borough: Nome
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 56,248
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1997

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Brevik Mission Airport Improvements -- \$10,000,000

Dimensional:

Facilities:

Brevik Mission SRE Building Replacement -- \$2,000,000

Equipment:

U/V Plow Grader/Loader -- \$350,000

Comments:

Resurface runway, apron, and taxiway, extend Runway 11/29 to 3,400', apply a dust palliative, and upgrade airport lighting.

BUCKLAND (BVK)

Runway(s): 11/29 - 3200' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: N/A

Classification: Community

Enplanements: 3138

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 320

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 91,044

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1996

Airfield Manager: ALVIN WERNEKE, 907-442-3147

NEEDS:

Surfaces:

Buckland Airport Improvements -- \$7,500,000

Dimensional:

Facilities:

Buckland SRE Building Replacement -- \$2,000,000

Equipment:

Grader 34,000# -- \$350,000

Dozer Crawler 8-10T-- \$350,000

Comments:

Resurface existing runway and taxiway, extend Runway 11/29 to 3,400', expand the apron, apply a dust palliative, and upgrade airport lighting.

CENTRAL (CEM)

Runway(s): 07/25 - 2782' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 36

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 540

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 12,412

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1989

Airfield Manager: DANIEL SCHACHER, 907-451-5276

NEEDS:

Surfaces:

Central Airport Improvements -- \$5,500,000

Dimensional:

Facilities:

Central SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface runway, apron, and taxiway, apply a dust palliative, and upgrade the airport lighting.

CHALKYITSIK (CIK)

Runway(s): 03/21 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 770

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 91,985

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1993

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Chalkyitsik Airport Improvements -- \$10,400,000

Dimensional:

Facilities:

Chalkyitsik SRE Building Replacement -- \$2,000,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

PAPI and WX Reporting Needed -- FAA

Equipment:

Loader, Wheeled 1.5CY -- \$350,000

Rural Airport Grader -- \$350,000

Compactor -- \$40,000

Brush Cutter -- \$130,000

Comments:

Resurface runway and taxiway, apply a dust palliative, relocate the apron and access road, and rehabilitate the airport lighting system and correct drainage problems at the end of the runway. SRE building is in extremely poor condition, is too small, has a gravel floor and is very inefficient.

CHANDALAR CAMP (5CD) - Chandalar Shelf

Runway(s): 01/19 - 2529' x 70'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 960

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 176

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2004

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Chandalar Camp Runway Rehabilitation -- \$2,500,000

Dimensional:

Facilities:

Equipment:

Comments:

Resurface all operational surfaces, develop lease lots, upgrade signage/markings, and prepare an airport layout plan.

CHANDALAR LAKE (WCR) - Chandalar Lake

Runway(s): 04/22 - 3000' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 28

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 650

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 7,687

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1994

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

CHEFORNAK (CFK)

Runway(s): 16/34 - 3230' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 4414

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 39,722

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Loader & grader with attachments

Comments:

CHENEGA BAY (C05)

Runway(s): 16/34 - 3000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 109,763

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2004

Airfield Manager: SEAN MONTGOMERY, 907-262-1187

NEEDS:

Surfaces:

Dimensional:

Extend runway to 3,300'

Expand RSA to 150' x 3,900'

Facilities:

Equipment:

Dozer

Comments:

Install PAPI

Install REILS

Install lighted wind cone at 16 runway end

CHEVAK (VAK)

Runway(s): 02/20 - 3200' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 5203

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 100

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 35,261

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Resurface runway, taxiways and apron

Place E-1 to reshape crown and compact with vibratory roller

Apply dust palliative

Dimensional:

Facilities:

Construct a 1-bay SREB

Relocate a 1-bay SREB

Equipment:

Snow blower, loader, and grader

Comments:

Airport needs fencing, obstacles/penetrations mitigated, erosion study, lease-lot development, Master Plan developed, improved access, and more.

CHICKEN (CKX)

Runway(s): 13/31 - 2500' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 22

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 14,829

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1987

Airfield Manager: DENNIS BISHOP, 907-883-5128

NEEDS:

Surfaces:

Chicken Airport Improvements -- \$4,500,000

Dimensional:

Facilities:

Chicken SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface runway, apron, and taxiway, apply a dust palliative, and upgrade the airport lighting.

CHIGNIK (AJC)

Runway(s): 02/20 - 2600' x 60'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 298

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 1,998

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 26,243

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Resurface runway, taxiway, and apron with 9" of new gravel

Dimensional:

Facilities:

Expand SREB to include an additional bay, heat, and insulation

Install concrete pad at SREB entrance

Equipment:

Grader and loader wheel

Comments:

Runway cannot be lengthened and is in good condition.

Lighting is not necessary as no planes fly at night due to terrain penetrations.

Culvert replacement (GF)

CHIGNIK LAGOON (KCL)

Runway(s): 04/22 - 1810' x 60'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 330

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 650

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 15,481

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Resurface existing gravel runway

Add surface course aggregate to the runway. Currently at 3".

Dimensional:

Replace windsock, poles and markers

Facilities:

Construct a SREB

Equipment:

Snow removal equipment

Comments:

Runway was lengthened from 1,600' to 2,200' x 60'.

No RSA at this airport.

Airport cannot be improved to FAA standards without severe impacts to the community.

Construct 10' of gravel access road

Install runway lighting

Determine potential runway realignments

CHIGNIK LAKE (A79)

Runway(s): 08/26 - 2800' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 64

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 1,200

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 12,671

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1985

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Resurface runway

Dimensional:

Lengthen/widen runway to community class standards

Expand RSAs and expand apron

Remove OFA penetrations, brush clearing (per ALP)

Facilities:

Construct a replacement SREB

Equipment:

Grader and snow removal equipment

Comments:

Lighting is not recommended due to terrain penetrations.

Install medium runway lighting (GF)

Install REILs

Install PAPIs

Identify future pad for weather reporting system

Update ALP

RPZ land acquisition

CHISANA (CZN)

Runway(s): 12/30 - 3000' x 50'

Surface: Turf/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 88

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 939

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Chisana Airport Improvements -- \$3,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Improve airport for all-season operations, including runway surface repairs, brushing, tree clearing and stockpiling surfacing material for future maintenance.

CHISTOCHINA (CZO)

Runway(s): 02/20 - 2060' x 90'

Surface: Turf/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 1,241

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Chistochina Airport Relocation -- \$10,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Relocate the existing airport, construct a new runway, apron, taxiway, aviation support area, SREB, apply a dust palliative and construct a new airport access road.

CHITINA (CXC)

Runway(s): 13/31 - 2850' x 75'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 16

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 2,360

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 1,638

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1991

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Chitina Airport Paving -- \$900,000

Dimensional:

Facilities:

Chitina SRE Building Upgrade -- \$300,000

Equipment:

Comments:

Pave all operational surfaces and apply airport markings.

CHUATHBALUK (9A3)

Runway(s): 09/27 - 3401' x 60'

Surface: Gravel

Lighting: BCN/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 327

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 22,103

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2002

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader and bulldozer

Comments:

Rehabilitate access road (GF)

CIRCLE (CRC)

Runway(s): 15/33 - 2979' x 60'

Surface: Turf

Lighting: BCN/MIRL

NAVAIDS: N/A

Classification: Community

Enplanements: 483

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 55,525

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1986

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Circle Airport Taxiway and Apron Rehabilitation -- \$1,500,000

Dimensional:

Facilities:

Circle SRE Building -- \$2,000,000

Lighted Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

PAPI Needed - FAA

Equipment:

Loader, Wheeled 1.5 CY -- \$350,000

Rural Airport Grader -- \$350,000

Comments:

This airport is always a candidate for closure during budget cuts - however it has EAS service and grant assurances. No SREB, equipment or fuel storage. Presently use contractor provided equipment, fuel etc.

CIRCLE HOT SPRINGS (CHP)

Runway(s): 09/27 - 3650' x 80'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements: 8

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 320

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 18,263

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: DANIEL SCHACHER, 907-451-5276

NEEDS:

Surfaces:

Circle Airport Taxiway and Apron Rehabilitation -- \$1,500,000

Dimensional:

Facilities:

Circle SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

CLARKS POINT (CLP)

Runway(s): 18/36 - 3200' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 339

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 18,698

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2004

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Reshaping embankment (per ALP narrative)

Resurfacing gravel runway (per ALP narrative)

Dimensional:

Brush Cutting

Facilities:

Equipment:

Comments:

Install medium intensity runway lighting

Install PAPIs

CLEAR (Z84)

Runway(s): 01/19 - 3997' x 100'

Surface: Asphalt

Lighting: BCN/MIRL

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 1,260

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 62,194

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1993

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Lighted Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

PAPI and WX Reporting Needed -- FAA

Equipment:

Comments:

Operating costs are understated due to Denali district performing work (cracksealing, etc). This airport is always a candidate for closure during budget cuts - however it does have grant assurances. No SREB, equipment or fuel storage. Presently use contractor provided equipment, fuel etc.

COFFMAN COVE SPB (KCC)

Runway(s): N/S - 5000' x 2000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 155

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 377

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2006

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

COLD BAY (CDB)

Runway(s): 15/33 - 10180' x 150'
08/26 - 6235' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/VASI
NAVAIDS: VORTAC/ILS/DME

Classification: Regional	# Enplanements: 8665	Borough: Aleutians East
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 85,723
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$ 998,342
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2011

Airfield Manager: HAROLD KREMER, 907-532-5000

NEEDS:

Surfaces:

Lenthen runway 08/26 at 8 end, Reconstruct taxiway A and B, Realign and pave St. Louis Road
Overlay south apron and resurface ARFF apron, Rehabilitate runway 15/33 and construct RSA
Construct new AEB apron and taxiway, Additional perimeter fencing
Maintain pavement markings (M&O SPM), Perimeter fencing repairs/replacement
Sand seal north/south apron areas to include RW15 elephant ear turn around & Rwy 8/26 turn around

Dimensional:

Regrade and compact RSAs, Add 40' of crosswind runway pavement, 300' of crosswind RSA
Expand the terminal apron and RSA, Extend runway 8/26 and reconfigure CW runway
Replace World War II era culverts at Trout Creek

Facilities:

Provide additional SRE storage as needed, Construct a 2-bay addition to the existing ARFF
Construct a stand by generator building

Equipment:

ARFF vehicle, dump truck, minivan, loader, Badging computer, software upgrade and printer
ARFF bunker gear

Comments:

Relocate & repair fencing (in design), Culvert replacements (roadways) (GF)
Runway lighting electrical repairs, Replace lighting on runway 15/33 and taxiway C
Install necessary storm drainage, signage; Update ALP after aeronautical survey completion
MALSR relocation at 33 end (in design) - May '15; Main runway rehab (in design) - est May '16
ARFF building expansion (in design) - est Jun '15
Crosswind runway improvements (in design) - est May '16

COLDFOOT (CXF)

Runway(s): 01/19 - 4001' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements: 4067

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 17,615

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 45,221

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1993

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Coldfoot Airport Improvements -- \$11,300,000

Dimensional:

Facilities:

Coldfoot SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface all airport operational surfaces, install permanent erosion control, remove obstructions, install new lighting and erosion protection.

COOPER LANDING (JLA) - Quartz Creek

Runway(s): 04/22 - 2200' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 13,985

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: SEAN MONTGOMERY, 907-262-1187

NEEDS:

Surfaces:

Clear brush

Dimensional:

Clear surface penetrations (per ALP)

Facilities:

Equipment:

Comments:

Multiple items needed including ROW expansion, property acquisition, lease-lot development, security fencing, geotechnical analysis, and Master Plan update.

This airport is a non-NPIAS airport and ineligible for AIP funding.

Tree removal around windsock and approach ends

Add 6 tiedowns if new apron area developed

COPPER CENTER (Z93) - Copper Center 2

Runway(s): 13/30 - 2200' x 55'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 1,537

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

CORDOVA (CDV) - Merle K. Smith

Runway(s): 09/27 - 7500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/VASI
NAVAIDS: NDB/ILS/DME

Classification: Regional	# Enplanements: 15772	Borough: Valdez-Cordova
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 63,335
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 845,736
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2008

Airfield Manager: ROBERT MATTSON, 907-424-3202

NEEDS:

Surfaces:

Cordova Airport Apron, Taxiway and GA Improvements Stage 2 -- \$8,500,000
Cordova Airport RSA Improvements (Drainage) -- \$5,500,000

Dimensional:

Facilities:

Cordova SREB/ARFF Building Replacement -- \$5,900,000
Cordova Airport Security Upgrades -- \$2,500,000

Equipment:

Blower 7,500 ton per hour -- \$800,000
Towed Broom 22' or wider -- \$700,000
Deice Truck 75' Boom -- \$400,000
Runway Light Plow Cleaner -- \$130,000
Airport Operations Vehicle -- \$80,000

Comments:

Construct transient air parking, general aviation parking, access roads, heliport pad, aviation support areas, complete obstruction removal, expand existing apron area, resolve drainage problems and construct partial parallel and connecting taxiways. Rehabilitate the runway safety areas, including grading and drainage improvements, clearing and grubbing.

CORDOVA (CKU) - Cordova Municipal

Runway(s): 06/24 - 1800' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 4

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 7,660

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 406

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ROBERT MATTSON, 907-424-3202

NEEDS:

Surfaces:

Dimensional:

Facilities:

Cordova Eyak Lake SRE Building -- \$2,000,000

Equipment:

Snowplow Rollerover-- \$350,000

Blade Belly-- \$350,000

Truck Plow Airport 4x4-- \$350,000

Utility Wagon Mid 4x4-- \$350,000

Handicap Pass Loader-- \$350,000

Comments:

COUNCIL (K29)

Runway(s): 10/28 - 3000' x 60'

Surface: Gravel

Lighting: BCN/App_Lts

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Nome

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 0

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1987

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

CROOKED CREEK (CJX)

Runway(s): 13/31 - 1997' x 60'

Surface: Earth/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 386

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 9,807

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1991

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Reshape runway crown, shoulders, and RSA, and compact

Add >3000 CY of surface course

Dimensional:

Facilities:

Construct a new heated 2-bay SREB

Equipment:

Comments:

Design is complete for AIP funded airport rehabilitation and extension improvements, but ROW acquisition is dependent upon the condemnation of one Native Allotment, which is being considered

Terrain penetrations removal

Install MIRL, PAPI, REIL, and AWOS

Acquire property

Master plan update

DAHL CREEK (DCK)

Runway(s): 08/26 - 4780' x 75'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 109

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 14,158

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 494

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1986

Airfield Manager: ALVIN WERNEKE, 907-442-3147

NEEDS:

Surfaces:

Dahl Creek Airport improvements -- \$8,000,000

Dimensional:

Facilities:

Dahl Creek Airport Lease Lot Development -- \$2,000,000

Equipment:

Comments:

Develop lease lots and expand the apron, including surveying airport lease lots, placing fill material, installing fencing and developing an updated land occupancy drawing.

DEADHORSE (SCC)

Runway(s): 05/23 - 6500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App-Rwy/HIRL/VASI/Ctr
NAVAIDS: VOR/ILS/DME Lts

Classification: Regional	# Enplanements: 48588	Borough: North Slope
Air Carrier Hub: No	Medical Facility: No	Annual Revenue: \$ 2,069,955
USPS Hub: No	School Facility: No	Ops Cost/Yr: \$ 1,822,039
Part 139 Cert: Yes	On/Off Road: On	Last Major Improvement: 2012

Airfield Manager: TIM PARAULT, 907-659-2553

NEEDS:

Surfaces:

Dimensional:

Deadhorse Airport Apron Expansiopn -- \$5,000,000

Facilities:

Deadhorse SREB/ARFF Building Replacement -- \$13,500,000

Deadhorse Airport Security Upgrades -- \$2,500,000

Equipment:

Friction Measure Trailer -- \$350,000

Snow-wing Grader -- \$350,000

Airport Operations Vehicle -- \$80,000

Handicap Pass Loader -- \$350,000

Blower 7,500 ton per hour -- \$800,000

Towed Broom Runway Plow (22' + width) -- \$800,000

Runway Light Cleaning Plow \$1

Comments:

Expand the existing apron to accommodate larger aircraft. Deadhorse SREB/ARFF Building Addition-Add two double equipment bays and a sand storage bay to the existing facility.

DEERING (DEE)

Runway(s): 02/20 - 3320' x 75'
11/29 - 2660' x 75'

Surface: Gravel
NAVAIDS: N/A

Lighting: BCN/Rwy_Lts/REIL/PAPI

Classification: Community

Enplanements: 1341

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 94,420

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: ALVIN WERNEKE, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Facilities:

Deering Snow Fence -- \$500,000

Equipment:

Rural Airport Grader 34,000#-- \$350,000

Comments:

DILLINGHAM (DLG)

Runway(s): 01/19 - 6400' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/VASI/PAPI
NAVAIDS: VOR/ILS/DME

Classification: Regional	# Enplanements: 26632	Borough: Dillingham
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 102,414
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$ 1,913,999
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2014

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

- Reconstruct and pave public parking area; Pave/rehabilitate GA apron and taxiway
- Pave vehicle parking area; Construct a parallel taxiway, RSA, and 2000' crosswind runway
- Shift runway away from cemetery
- Maintain pavement markings (M&O SPM)
- Vehicle gates with electronic swipe capability
- Perimeter fencing repairs/replacement
- Main apron redesign drainage issues full length - water does not drain and freezes - water runs to last lease lot and through the lot. manholes on apron are higher than the designed flow

Dimensional:

- Construct an FAA-compliant RSA
- Expand main terminal apron, vehicle parking area, and RSA

Facilities:

- Install public toilets

Equipment:

- SUV; 5,000 gal water tanker and 4,000 gal deicer truck
- Badging computer, software upgrade and printers
- ARFF SCBA compressor; ARFF bunker gear

Comments:

- Fence and gate repair; Install MALSR; Master plan update
- FAA navigation equipment improvements

EAGLE (EAA)

Runway(s): 06/24 - 3600' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: N/A

Classification: Community

Enplanements: 551

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 5,154

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 29,021

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1984

Airfield Manager: DENNIS BISHOP, 907-883-5128

NEEDS:

Surfaces:

Eagle Airport improvements -- \$2,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Resurface runway and taxiway, relocate the apron and access road to meet standards, improve sub-grade and drainage, and install new lighting.

EEK (EEK)

Runway(s): 17/35 - 3242' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 3913

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 32,351

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2002

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

- Construct a 2,400' x 60' gravel crosswind runway w/ RSA
- Construct a 100,000 sqft apron and aviation support area
- Construct a segmented circle

Dimensional:

Facilities:

- Construct a new SREB

Equipment:

- Grader and loader

Comments:

- Install MIREL and airport lighting
- Construct a 2,150' x 12' airport access road
- Purchase 225 acres of land

EKWOK (KEK)

Runway(s): 02/20 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 202

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 550

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 17,353

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2008

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Resurface and apply dust palliative to runway, taxiway, and apron

Install wildlife/security fencing

Dimensional:

Construct taxiway B

Construct apron and lease lots off taxiway B

Construct approaches from access road to ultimate apron

Facilities:

Equipment:

Comments:

Install REILs, PAPIs, and AWOS

Install new culverts

ELFIN COVE SPB (ELV)

Runway(s): NW/SE - 10000' x 1500' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Local	# Enplanements: 453	Borough: Hoonah-Angoon
Air Carrier Hub: No	Medical Facility: No	Annual Revenue: \$
USPS Hub: No	School Facility: No	Ops Cost/Yr: \$
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Float to be replaced with harbor rehab project in 2015

ELIM (ELI)

Runway(s): 01/19 - 3401' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2030

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 121,097

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2008

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Elim Airport Improvements -- \$8,000,000

Dimensional:

Facilities:

Elim SRE Building Replacement -- \$2,000,000,

Elim Airport Access Road Realignment -- \$7,000,000

Equipment:

Dozer Crwlr 8-10T-- \$350,000

Comments:

Resurface runway, apron and taxiway, improve drainage, and install new lighting.

EMMONAK (ENM)

Runway(s): 16/34 - 4601' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts/VASI/REIL

NAVAIDS: VOR/DME

Classification: Regional

Enplanements: 8268

Borough: Wade Hampton

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue: \$ 6,483

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$ 154,742

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Dimensional:

Emmonak Airport Runway Extension -- \$18,400,000

Emmonak Airport RSA Improvements -- \$1,000,000

Facilities:

Emmonak Airport SRE Building -- \$2,100,000

Equipment:

U-Blade Loader 5CY -- \$350,000

Dozer Crawler 8-10T -- \$350,000

Loader, Wheeled 1.5 CY -- \$350,000

Comments:

Extend the runway to 6,000' and the existing safety area to 7,200' x 300', acquire land for extension, and install new lighting.

EXCURSION INLET SPB (EXI)

Runway(s): NW/SE - 10000' x 1000' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Local	# Enplanements: 65	Borough: Haines
Air Carrier Hub: No	Medical Facility: No	Annual Revenue: \$
USPS Hub: No	School Facility: No	Ops Cost/Yr: \$
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'20 Replace Seaplane Float -- \$1,250,000

Dimensional:

Facilities:

Equipment:

Comments:

FAIRBANKS (FAI) - Fairbanks Intl

Runway(s): 2L/20R - 11800' x 150'
2R/20L - 6501' x 100'

Surface: Asphalt/Grooved

Lighting: BCN/App-Rwy_Lts/HIRL/
REIL/PAPI

NAVAIDS: VORTAC/ILS/DME

Classification: International

Enplanements: 457372

Borough: Fairbanks/North Star

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue: \$ 9,629,957

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$ 17,553,083

Part 139 Cert: Yes

On/Off Road: On

Last Major Improvement: 2012

Airfield Manager: JESSE VANDERZANDEN, 907-474-2500

NEEDS:

Surfaces:

Tie down apron areas, various roadways

Dimensional:

Facilities:

ARFF Facility remodel 9/13 thru 12/14

Equipment:

Regular planned vehicle fleet replacement

Comments:

FAIRBANKS SPB (FAI)

Runway(s): 02/20 - 5400' x 100'

Surface: Water

Lighting: BCN

NAVAIDS: N/A

Classification: International

Enplanements:

Borough: Fairbanks/North Star

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: JESSE VANDERZANDEN, 907-474-2500

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

FALSE PASS (KFP)

Runway(s): 14/32 - 2150' x 60'

Surface: Gravel

Lighting: REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 371

Borough: Aleutians East

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 825

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 12,597

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2014

Airfield Manager: HAROLD KREMER, 907-532-5000

NEEDS:

Surfaces:

Relocate apron, construct lease lots on apron with tie downs

Resurface runway and reconstruct taxiway

Place riprap along the Roundtop Creek bank to protect the runway from erosion

Raise runway profile to match the height of the proposed extension into Isanotski Strait

Dimensional:

Increase runway length to 3,100' and width to 60'; Extend taxiway to 35'x220'

Increase RSA to 120' x 3,580', RPZ to 500' x 700' x 1,000'

Increase OFA to 400' x 3,580', and OFZ to 400' x 3,500

Resurface RSA and grade to drain; Clear brush and gravel berms in

Facilities:

Construction of 2-bay heated SREB with rotating beacon, fuel tanks, and electrical enclosure building

Equipment:

SNOWPLOW GRADER; Cat 140M grader

Comments:

Due to the low population, 26 in 2012, the cost to reconstruct the airport will be extremely high.

Extend edge lighting

Install MIRL and taxiway lighting

Relocate REILs

Install lighted windsock and segmented circle

Additional ROW acquisition

FLAT (FLT)

Runway(s): 08/26 - 4045' x 90'

Surface: Turf/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 11

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 222

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: STEFFEN STRICK, 907-524-3241

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

FORT YUKON (FYU)

Runway(s): 04/22 - 5000' x 100'

Surface: Gravel

Lighting: BCN/MALSR/MIRL/VASI

NAVAIDS: VORTAC/NDB

Classification: Regional

Enplanements: 7441

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 27,080

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$ 67,623

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Application of dust palliative.

Dimensional:

Facilities:

Lighted Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

Equipment:

Snow-wing Grader-- \$350,000

Airport Operations Vehicle -- \$80,000

Handicap Pass Loader-- \$350,000

Tow Broom (22'+ width) - \$800,000

Blower 7,500 ton per hour -- \$800,000

Runway Light Cleaner -- \$130,000

Comments:

Recently reconstructed airport is still in excellent condition, need additional equipment to properly maintain it.

FUNTER BAY SPB (FNR)

Runway(s): NE/SW - 10500' x 500' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Local	# Enplanements:	Borough: Hoonah-Angoon
Air Carrier Hub: No	Medical Facility: No	Annual Revenue: \$
USPS Hub: No	School Facility: No	Ops Cost/Yr: \$
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'23 Replace Seaplane Float -- \$500,000

Dimensional:

Facilities:

Equipment:

Comments:

GALBRAITH LAKE (GBH)

Runway(s): 13/31 - 5182' x 150'

Surface: Gravel

Lighting: BCN/App-Rwy_Lts/PAPI

NAVAIDS: NDB

Classification: Local

Enplanements: 582

Borough: North Slope

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 4,302

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 0

Part 139 Cert: Yes

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Extend the land lease with the BLM. M&O provided by Alyeska Pipeline Service Co.

GALENA (GAL) - Edward G. Pitka Sr.

Runway(s): 07/25 - 7249' x 150' **Surface:** Concrete/Asphalt **Lighting:** BCN/HIRL/REIL
NAVAIDS: VOR/DME **VASI is out of service permanently -
**VOR/DME OTS since 2013 FAA PAPI install required but
flood unfunded

Classification: Regional **# Enplanements:** 14141 **Borough:** Yukon-Koyukuk
Air Carrier Hub: Yes **Medical Facility:** Yes **Annual Revenue:** \$ 58,235
USPS Hub: Yes **School Facility:** Yes **Ops Cost/Yr:** \$ 569,936
Part 139 Cert: No **On/Off Road:** Off **Last Major Improvement:** 2009

Airfield Manager: MARVIN THURMOND, 907-656-1236

NEEDS:

Surfaces:

Galena Airport Improvements -- \$16,300,000

Dimensional:

Facilities:

Galena Airport Lighting Replacement -- \$2,200,000

Sand Storage -- \$1,500,000

PAPI Needed -- FAA

Equipment:

Blower 5 ton per hour -- \$600,000

Towed Broom 22' or wider -- \$700,000

Deice Truck 75' Boom -- \$400,000

Loader, Wheeled 4.5-5 CY -- \$350,000

Brush Cutter -- \$130,000

Compactor -- \$40,000

Paint Truck -- \$100,000

Comments:

Shorten and resurface Runway 7/25 and Taxiway "B" at the Galena Airport, repair the general aviation (GA) apron.

GAMBELL (GAM)

Runway(s): 16/34 - 4499' x 96' **Surface:** Concrete/Asphalt **Lighting:** BCN/App-Rwy_Lts/VASI/REIL
NAVAIDS: NDB/DME

Classification: Community	# Enplanements: 3312	Borough: Nome
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 134,051
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1997

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Resurface RWY and TWY

Dimensional:

Facilities:

Equipment:

U/V Plow Grader/Loader -- \$350,000

Comments:

GIRDWOOD (AQY)

Runway(s): 02/20 - 2088' x 73'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Anchorage

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 25,127

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 14,710

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2002

Airfield Manager: PAUL BERTHOLL, 907-783-2232

NEEDS:

Surfaces:

Relocate both thresholds

Provide 3,500 linear feet of erosion protection for runway embankment

Apply dust palliative

Cap the road going from the north gate to north end of the airport property

Dimensional:

Extend parallel taxiway to the north

Expand the southern RSA 116' southward

Extend the RSA embankment 116' south

Expand apron and runway

Brush cutting

Facilities:

Equipment:

Comments:

Install erosion control rip rap (GF); Improve drainage, add threshold markers (GF)

Brush cutting and dust control

Lower the power and telephone lines

Remove trees within the obstruction navigable airspace

Pave airport access road

Create additional lease lots to the north of existing lease lots

Create a maintenance building reserve north of the existing lease lots

GLENALLEN/GULKANA (GKN)

Runway(s): 15/33 - 5001' x 100'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: N/A

Classification: Community

Enplanements: 22

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 21,386

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 74,839

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Gulkana Airport Apron and Taxiway Repaving -- \$3,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Reconstruct the pavement on the apron and taxiway, remove obstacles and install airport markings/signage.

GOLD KING CREEK (AK7)

Runway(s): 09/27 - 2500'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Fairbanks/North Star

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 100

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 0

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Gold King Airport Improvements -- \$2,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Improve airport for all-season operations, including runway surface repairs, brushing, tree clearing and stockpiling surfacing material for future maintenance.

GOLOVIN (GLV)

Runway(s): 02/20 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1606

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 61,126

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Golovin Airport Runway and Apron Improvements -- \$14,300,000

Dimensional:

Facilities:

Equipment:

Grader 34,000# -- \$350,000

Comments:

Resurface and rehabilitate the runway, construct a new taxiway, apron and access road, and replace the existing airport lighting

GOODNEWS (GNU)

Runway(s): 06/24 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1540

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 33,255

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2011

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

GOOSE BAY (Z40)

Runway(s): 08/26 - 3000' x 75'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 9,160

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1987

Airfield Manager: STEVE BANSE, 907-745-2159

NEEDS:

Surfaces:

Runway resurfacing

Dimensional:

Facilities:

Equipment:

Comments:

GRAYLING (KGX)

Runway(s): 17/35 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 920

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 70,534

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2008

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Dimensional:

Facilities:

Grayling SRE Building Replacement -- \$2,000,000

Equipment:

Snow Wing Grader -- \$350,000

Dozer Crawler 8-10T -- \$350,000

Comments:

GUSTAVUS (GST)

Runway(s): 11/29 - 6721' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/VASI/REIL
NAVAIDS: NDB

Classification: Regional	# Enplanements: 10076	Borough: Hoonah-Angoon
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 54,421
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 191,932
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2011

Airfield Manager: MIKE PEDERSEN, 907-697-2251

NEEDS:

Surfaces:

FY'16 RWY/TWY/Apron Rehab -- \$12,000,000

Dimensional:

FY'15 Aeronautical Survey in conjunction with Pavement project design -- \$250,000

Facilities:

FY'16 Sand and Chem Building -- \$1,700,000

FY'16 ARFF/SRE Building -- \$1,200,000

Equipment:

FY'14 ARFF Truck -- \$1,000,000

Comments:

FY'16 WHA/WHMP Update -- \$140,000

Resolved with FY14 site visit and update

HAINES (HNS)

Runway(s): 08/26 - 4000' x 100'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: NDB

Classification: Community

Enplanements: 10106

Borough: Haines

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 14,924

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 26,290

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1990

Airfield Manager: MATT BORON, 907-766-2340

NEEDS:

Surfaces:

FY'14 TWY & Apron Drainage improvement, rehab -- \$10,000,000

FY'16 RWY Rehab -- \$6,000,000

Dimensional:

FY'19 Apron Expansion -- \$1,300,000

Facilities:

FY'16 Sand and Chem/SRE Building -- \$2,000,000

Hard stands to support increasing business jet traffic

Equipment:

Comments:

FY'16 WHA Update/New WHMP -- \$200,000

HEALY (HRR)

Runway(s): 15/33 - 2912' x 60'

Surface: Asphalt

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 24

Borough: Denali

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 13,860

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 4,723

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1995

Airfield Manager: TOM WILLIAMS, 907-451-5280

NEEDS:

Surfaces:

Healy River Airport Resurfacing -- \$4,500,000

Dimensional:

Facilities:

Healy River Airport Lighting Replacement -- \$1,700,000

Healy River Airport Land Lease Extension -- \$800,000

Equipment:

Comments:

Resurface all operational surfaces. Healy River Airport Lighting Rep-Replace the airport lighting system.

HOLLIS SPB (HYL) - Clark Bay SPB

Runway(s): E/W - 10000' x 500'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 1360

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2006

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

HOLY CROSS (HCA)

Runway(s): 01/19 - 4000' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1513

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 54,971

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Holy Cross Airport Improvements -- \$7,500,000

Dimensional:

Facilities:

Holy Cross SRE Building Replacement -- \$2,000,000

Equipment:

U-Blade Loader 5CY -- \$350,000

Loader Wheeled 1.5CY -- \$350,000

Comments:

Raise the grade, clear obstructions, resurface all operational surfaces and install new airport lighting.

HOMER (HOM)

Runway(s): 04/22 - 6701' x 150' **Surface:** Asphalt **Lighting:** BCN/App_Lts/HIRL/VASI
NAVAIDS: VOR/ILS/DME

Classification: Regional	# Enplanements: 37705	Borough: Kenai Peninsula
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 155,482
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 707,194
Part 139 Cert: Yes	On/Off Road: On	Last Major Improvement: 2011

Airfield Manager: KEVIN JONES, 907-235-5217

NEEDS:

Surfaces:

Rehabilitate runway, taxiway, and apron; Construct 30-space vehicle parking lot
Address Part 139 RSA issues along runway 04/22; Perimeter fencing repairs/replacement
Construct a full-length parallel taxiway on north side of runway 04/22
Construct multiple connective taxiways, heliport, and access ramp
Remove trees between elephant ear and Lampert Lake (M&O OR)
Repave Elephant Ear apron (M&O SPM); Safety Areas and Drainage improvements
Maintain pavement markings (M&O SPM); Apply dust palliative on GA and Beacon areas
Replace surface course; Vehicle gates with electronic swipe capability

Dimensional:

Extend taxiways, south apron, and GA apron toward Lampert Lake
Address Part 139 issues on runway 04/22 by filling, regrading, and leveling the RSA
Remove berm from Elephant Ear to RWY 22 approach.
Remove trees between elephant ear and Lampert Lake (M&O OR)

Facilities:

Demo existing SREB and construct new 5-bay facility w/ FSS; Build a new multi-bay ARFF building
Chemical and deicing material storage facility

Equipment:

SUV, grader; 4,000 gal deicer truck; ARFF bunker gear

Comments:

Acquire Lot 2, Block 400 lease lot; Replace/relocate rotating beacon

Construct new access road to the GA apron; Construct access road to the dock
Install rot bcn/floating transient floatplane dock at Beluga Lake; Acquire lease lots, SREB lot
Install PAPI lighting system; Conduct master plan update

HOMER SPB (5BL) - Homer-Beluga Lake

Runway(s): NE/SW - 3000' x 600'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: KEVIN JONES, 907-235-5217

NEEDS:

Surfaces:

Construct access road

Construct ramp access and turnaround

Construct floatplane slips

Dimensional:

Facilities:

Construct Access Road and Ramp

Construct a rescue boat house and lake side floats

Equipment:

Comments:

Study Complete

HOONAH (HNN)

Runway(s): 06/24 - 2997' x 75'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 10468

Borough: Hoonah-Angoon

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 12,658

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 151,754

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2012

Airfield Manager: KEN MESERVE, 907-945-3426

NEEDS:

Surfaces:

FY'18 Apron/TWY Rehab -- \$3,000,000

Dimensional:

FY'19 Obstruction Removal -- \$500,000

Facilities:

Equipment:

Comments:

HOONAH SPB (OOH)

Runway(s): E/W - 9000' x 5000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Hoonah-Angoon

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KEN MESERVE, 907-945-3426

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

HOOPER BAY (HPB)

Runway(s): 13/31 - 3300' x 75' **Surface:** Asphalt/Grooved **Lighting:** BCN/App-Rwy_Lts/VASI
NAVAIDS: VOR/DME

Classification: Community	# Enplanements: 4783	Borough: Wade Hampton
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 920
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 41,195
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2005

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

- Rehabilitate runway pavement
- Relocate apron

Dimensional:

- Expand apron and runway to 4,500'

Facilities:

- Construct a new 3-Bay SREB

Equipment:

- Loader & D6 dozer

Comments:

- Needs access road, lighting and land acquisition

HOPE (5HO)

Runway(s): 16/34 - 2000' x 90'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 5,056

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 28,007

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: DREW MOTSINGER, 907-269-5672

NEEDS:

Surfaces:

Construct a GA apron and taxiway

Reconstruct the runway to A2 standards

Vegetation control on runway

Apply dust palliative

Dimensional:

Facilities:

Equipment:

Comments:

HUGHES (HUS)

Runway(s): 17/35 - 3380' x 100'

Surface: Gravel

Lighting: BCN/MIRL

NAVAIDS: N/A

Classification: Community

Enplanements: 1092

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 87,357

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1990

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Hughes Airport Improvements -- \$3,800,000

Dimensional:

Facilities:

Hughes SRE Building Replacement -- \$2,000,000

Light Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

Equipment:

Loader, Wheeled 1.5 CY-- \$350,000

Compactor -- \$40,000

Brush Cutter -- \$130,000

Comments:

Raise the grade of the airport, relocate the apron, and apply dust palliative on operational surfaces.

HUSLIA (HLA)

Runway(s): 03/21 - 4000' x 75'

Surface: Gravel

Lighting: BCN/MIRL/REIL/PAPI

NAVAIDS: VOR/DME

Classification: Community

Enplanements: 3012

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 81,546

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Huslia SRE Building Replacement -- \$2,000,000

Light Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

Equipment:

Compactor -- \$40,000

Brush Cutter -- \$130,000

Comments:

HYDABURG SPB (HYG)

Runway(s): E/W - 5000' x 2000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 24

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 864

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1994

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

HYDER SPB (4Z7)

Runway(s): N/S - 10000' x 1000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 154

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2002

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

IGIUGIG (IGG)

Runway(s): 05/23 - 3000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 320

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 3,415

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 32,890

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1993

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

Resurface runway, approaches, and apron resurface

Reinstall tie downs on apron

Dimensional:

Extend runway 05/23 to 3,300'

Expand apron

Evalute and expand the property boundary at the terminal for land interest

Brush cutting needed

Facilities:

Construct heated 1-bay SREB

Equipment:

Grader, loader, snow removal equipment

Comments:

Replace and extend existing MIRL

Future airport development will require an ALP update

Acquire additional ROW

Install apron concrete parking pads (2) and additional tie downs

ILIAMNA (ILI)

Runway(s): 07/25 - 5086' x 100'
17/35 - 4800' x 100' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/REIL/PAPI
NAVAIDS: NDB/DME

Classification: Regional **# Enplanements:** 5688 **Borough:** Lake & Peninsula
Air Carrier Hub: Yes **Medical Facility:** Yes **Annual Revenue:** \$ 72,225
USPS Hub: Yes **School Facility:** Yes **Ops Cost/Yr:** \$ 609,482
Part 139 Cert: No **On/Off Road:** Off **Last Major Improvement:** 2002

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

Construct GA taxiway (parallel to runway 17/35)
Expand GA apron to 300' x 1,000'
Construct 200' x 600' light jet apron and taxiway; Construct runway 35 parallel taxiway (Proj. III-1)
Construct helicopter ops area, aircraft parking reserve; Construct parallel taxiway reserve
Construct new air carrier taxiway from existing apron
Construct 2 gravel tundra tire and ski rwys 1,800' x 60'; Construct connecting taxiway
Maintain pavement markings & crack seal (M&O SPM); Perimeter fencing repairs/replacement
Vehicle gates with push button electric

Dimensional:

Remove RVZ encroachments; Remove obstructions (brush) (M&O OR)

Facilities:

Expand the existing 5-bay M&O building
Demolish/relocate hotel on airport property (lease expires in 2020)

Equipment:

Minivan, compactor, loader, brush cutter loader attachment or skid steer

Comments:

Fence and gate repair; Lease lot development; Pave west side of airport access road
Road realignment for Iliamna Village Road; Site clean-up after hotel demolish/relocate
Install security fencing and improve seaplane facilities
Airport Improvements Project (in design) - est Mar '19

ILIAMNA (ILI) - Iliamna Pike Lake

Runway(s): N/S - 2892' x 400'
E/W - 2998' x 400'

Surface: Water
NAVAIDS: N/A

Lighting: N/A

Classification: Regional

Enplanements:

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

- Construct access road
- Construct lease lots
- Construct 4,400' x 200' north/south waterway

Dimensional:

Facilities:

Equipment:

Comments:

- Runway cannot be lengthened and is in good condition.
- Lighting is not necessary as no planes fly at night due to terrain penetrations.
- Culvert replacement
- Acquire land parcels

KAKE (KAE)

Runway(s): 11/29 - 4000' x 100' **Surface:** Asphalt **Lighting:** Rwy_Lts/REIL/PAPI
NAVAIDS: NDB

Classification: Community **# Enplanements:** 1723 **Borough:** Wrangell
Air Carrier Hub: No **Medical Facility:** Yes **Annual Revenue:** \$ 550
USPS Hub: No **School Facility:** Yes **Ops Cost/Yr:** \$ 70,312
Part 139 Cert: No **On/Off Road:** Off **Last Major Improvement:** 1989

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'16 -- RWY Rehab -- \$5,000,000

Dimensional:

FY'22 Obstruction Removal and RWY Extension -- \$12,000,000

FY'23 Apron Expansion -- \$2,000,000

Facilities:

FY'18 SRE Building & Parking Lot -- \$2,500,000

Hard stand to support occassional business jet traffic

Equipment:

Comments:

KALSKAG (KLG)

Runway(s): 06/24 - 3172' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 3127

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 2,952

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 22,930

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1999

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Dimensional:

Brush Cutting (M&O OR)

Facilities:

Equipment:

Grader

Comments:

Runway was lengthened from 1,600' to 2,200' x 60'. No RSA at this airport. Airport cannot be improved to FAA standards without severe impacts to the community. Needs 10' of gravel access road.

Obstruction removal

KALTAG (KAL)

Runway(s): 03/21 - 3986' x 100'

Surface: Gravel

Lighting: BCN/MIRL

NAVAIDS: N/A

Classification: Community

Enplanements: 1645

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 1,423

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 106,550

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1991

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Kaltag Airport Improvements -- \$5,000,000

Dimensional:

Facilities:

Kaltag SRE Building Replacement -- \$2,000,000

Lighted Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

PAPI Needed - FAA

Equipment:

Compactor -- \$40,000

Brush Cutter -- \$130,000

Comments:

Rehabilitate all operational surfaces, replace the lighting system, and apply a dust palliative.

KANTISHNA (5Z5)

Runway(s): 10/28 - 1950' x 45'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 21,472

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: TOM WILLIAMS, 907-451-5280

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KARLUK (KYK)

Runway(s): 10/28 - 2000' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 287

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 16,098

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ROBERT GREENE, 907-487-4952

NEEDS:

Surfaces:

Airport surface rehabilitation

Clear brush around segmented circle (M&O OR)

Rehabilitate runway, taxiway and apron; aggregate needed

Dimensional:

Apron extension by 200'

Extend runway to 3,000'

Stabilize RSA embankment

Brush cutting (M&O OR)

Facilities:

Construct new maintenance building

Equipment:

30,000 LB GRADER

Comments:

Village has Native Sovereignty Issues

Leasehold interest extended in 2012

Wind cone replacement (M&O DM)

Improve the access road

Install MIRL

KASAAN SPB (KXA)

Runway(s): N/S - 2000' x 2000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 139

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 1,324

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1989

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KASIGLUK (Z09)

Runway(s): 17/35 - 3000' x 60'

Surface: Gravel

Lighting: Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 5089

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 33,347

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1997

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Scarify, reshape and recompact surfacing material runway (M&O SPM)

Apply dust palliative

Sinking safety area needs to be rehabilitated

Dimensional:

Brush Cutting (M&O OR)

Facilities:

Construct a 2-bay heated SREB with floor

Equipment:

Loader and grader

Comments:

KASILOF (5KS)

Runway(s): 01/19 - 2165' x 40'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 1,943

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: SEAN MONTGOMERY, 907-262-1187

NEEDS:

Surfaces:

Clear brush and terrain (per ALP)

Dimensional:

Clear surface penetrations (per ALP)

Facilities:

Equipment:

Comments:

Tree removal around windsock and approach ends

RPZ area is not part of airport ownership on either runway end.

KETCHIKAN (KTN) - Ketchikan Intl

Runway(s): 11/29 - 7500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/PAPI
NAVAIDS: ILS/DME/NDB

Classification: Regional	# Enplanements: 109433	Borough: Ketchikan Gateway
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$ 517,642
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2007

Airfield Manager: MIKE CARNEY, 907-225-6800

NEEDS:

Surfaces:

Dimensional:

FY'16 Construct Seaplane Haulout Ramp -- \$600,000

Facilities:

FY'15 Expand/Rehab ARFF Building -- \$1,000,000

FY'23 Second Airport Ferry Berth -- \$2,000,000

Equipment:

FY'14 30' Trap Plow -- \$35,000

FY'14 Multi-purpose carrier, \$675,000

FY'17 Deicing Truck -- \$350,000

FY'16 Replacement Friction Tester w/ Tow Vehicle

Comments:

KETCHIKAN AIRPORT SPB (KTN)

Runway(s): NW/SE - 9500' x 1500'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Regional

Enplanements:

Borough: Ketchikan Gateway

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue: \$

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: MIKE CARNEY, 907-225-6800

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KETCHIKAN SPB (9C0) - Peninsula Point Pullout

Runway(s): NE/SW - 9000' x 2000' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Local	# Enplanements:	Borough: Ketchikan Gateway
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KIANA (IAN) - Bob Baker Memorial

Runway(s): 06/24 - 3400' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 3463

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 2,557

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 82,470

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1996

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Extend the runway, rehabilitate the operational surfaces, expand the apron, improve the aircraft parking setback, acquire land, replace the lighting system, and apply a dust palliative.

KING COVE (KVC)

Runway(s): 07/25 - 3500' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 2829

Borough: Aleutians East

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 2,772

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 31,770

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: HAROLD KREMER, 907-532-5000

NEEDS:

Surfaces:

- Repave runway, taxiway, and apron
- Maintain drainage systems along runway
- Grading and digouts for shoulders, RSA and apron areas
- Vehicle gates with push button electric

Dimensional:

- Expand RSA to 4,200' x 150'
- Expand runway to 3,600' x 100'
- Widen taxiway to 79'
- Work on runway gravel shoulders/RSA and soft apron areas

Facilities:

- Construct 2 heated SREB
- Construct 8' x 10' heated passenger shelter

Equipment:

- Loader and grader

Comments:

- Update ALP

KING SALMON (AKN)

Runway(s): 12/30 - 8901' x 150' **Surface:** Asphalt **Lighting:** BCN/App_Lts/REIL/PAPI
NAVAIDS: ILS/DME/VORTAC

Classification: Regional	# Enplanements: 35450	Borough: Bristol Bay
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 138,690
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$ 1,119,709
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2014

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Resurface runway 11/29; Construct parallel taxiway (in design)
Realign and pave Main Street (in design); Realign and Pave Jensen Road (in design)
Expand long term vehicle parking area (in design); Expand terminal apron
Resurface vehicle parking area, GA apron, and taxiway G
Rehabilitate runway 18/36 and 18 overrun; Maintain pavement markings (M&O SPM)
Vehicle gates with electronic swipe capability; Perimeter fencing repairs/replacement

Dimensional:

Regrade and compact RSA; Brush cutting (M&O OR)

Facilities:

Install new public toilets and transit apron shelter; Construct a new sand storage building

Equipment:

Loader, grader, ARFF truck, bulldozer; Minivan, friction measuring trailer
Badging computer, software upgrade and printers; ARFF SCBA compressor
ARFF bunker gear

Comments:

Purchase an RPZ; Replace wind cones; Chart and remove obstructions
Replace edge lighting for both runways
Airport Main Runway Pavement Rehab (in design) - est Aug '17
Aiprort Taxiway (in design) - est Aug '15
Sand and Chemical Storage Building (in design)

KING SALMON SPB (AKN)

Runway(s): NW/SE - 4000' x 500'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Regional

Enplanements:

Borough: Bristol Bay

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Dimensional:

Complete RSA

Facilities:

Install new public toilets (GF)

Equipment:

Comments:

Purchase an RPZ

Replace wind cones

Chart and remove obstructions

Replace edge lighting for both runways

KIPNUK (IIK)

Runway(s): 17/35 - 3200' x 60'

Surface: Gravel

Lighting: Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 6114

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 550

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 40,965

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2014

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Dimensional:

Facilities:

Construct two SREBs

Equipment:

30,000 LB GRADER, loader

Comments:

KIVALINA (KVL)

Runway(s): 12/30 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2975

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 100

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 62,296

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Kivalina Airport Erosion Control -- \$7,200,000

Dimensional:

Facilities:

Kivalina SRE Building Replacement -- \$2,000,000

Equipment:

U-Blade Loader 10CY -- \$350,000

Loader Wheeled 1.5CY -- \$350,000

Comments:

Permanently repair erosion damage and install permanent beach erosion control.

KLAWOCK (AKW)

Runway(s): 02/20 - 5000' x 100'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: NDB

Classification: Community

Enplanements: 1550

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 23,452

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 70,732

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: TIM LACOUR, 907-755-2229

NEEDS:

Surfaces:

FY'16 Apron Expansion and Rehab -- \$5,000,000

Dimensional:

FY'18 New TWY to Lease Lots -- \$2,750,000

FY'20 Obstruction Removal -- \$5,000,000

Facilities:

FY'23 Airport Seaplane Float and Haul Out -- \$3,500,000

Equipment:

Comments:

ASOS wind sensor needs to be relocated for better readings

ASOS needs to be connected to emergency generator

KOBUK (OBU)

Runway(s): 09/27 - 4020' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1575

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 100

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 64,513

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: ALVIN WERNEKE, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Dozer Crawler 8-10T -- \$350,000

Grader Rural Arpt -- \$350,000

Comments:

KODIAK (ADQ)

Runway(s): 07/25 - 7550' x 150'
11/29 - 5400' x 150'
18/36 - 5010' x 150'

Surface: Asphalt/Grooved
NAVAIDS: VOR/ILS/DME

Lighting: BCN/HIRL/VASI/REIL

Classification: Regional	# Enplanements: 79930	Borough: Kodiak Island
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 188,484
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$ 1,238,991
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2011

Airfield Manager: ROBERT GREENE, 907-487-4952

NEEDS:

Surfaces:

- Tree/brush cutting around airport (M&O DM & OR)
- Maintain pavement markings and crack seal (M&O SPM)
- Sand seal aprons A & C (M&O SPM)
- Surface & drainage between rwys 7 & 11 (M&O SPM)
- Vehicle gates with electronic swipe capability; Perimeter fencing repairs/replacement
- Replace fencing around Commercial Apron perimeter
- 11/29 rehabilitate pavement

Dimensional:

- Extend runway 18/36 and 07/25 RSAs; Remove Part 77 tree obstructions (M&O OR)
- Expand RSA - EIS

Facilities:

- Construct new 3-bay ARFF building

Equipment:

- 3,000 gal ARFF vehicle (need to replace current one); 4X4 minivan
- Upgrade the ARFF vehicle from 1,500 to 3,000 gallons; ARFF bunker gear
- Badging computer, software upgrade and printers

Comments:

- Replace electric gate A; Replace fence/gates around perimeter of ramp
- Replace Devils Creek culvert

KOKHANOK (9K2)

Runway(s): 06/24 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 881

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 2,204

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 21,012

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

Resurface gravel runway, taxiway, and apron

Dimensional:

Expand runway to 4,200' x 75'

Expand RSAs

Facilities:

Construct a new SREB

Equipment:

Grader & loader with attachments

Comments:

Install PAPIs and REILs

Install one or two apron concrete parking pads

Local pilots request an AWOS at this airport

KOLIGANEK (JZZ)

Runway(s): 09/27 - 3000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 405

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 2,900

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 28,996

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1994

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Reconstruct the runway 3,300'

Expand and resurface apron

Rehabilitate airport and taxiway

Remediate existing airport embankments and realign access road

Dimensional:

Extend RSA to 3,900'

Facilities:

Construct a new heated, 2-bay SREB

Equipment:

Grader & loader with attachments

Comments:

Replace runway lighting and lighted windsock

Construct PAPI pads

Install PAPIs and REILs

Install tie downs

KONGIGANAK (DUY)

Runway(s): 01/19 - 2400' x 75'	Surface: Dirt/Gravel	Lighting: BCN/Rwy_Lts
	NAVAIDS: N/A	
Classification: Community	# Enplanements: 3904	Borough: Bethel
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 24,471
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2010

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

- Construct a new apron and segmented circle
- Scarify, reshape and recompact surfacing material runway (M&O SPM)
- Add surface course to runway surface
- Resurface south half of existing runway

Dimensional:

- Extend runway in accordance to B-1 standards, but not to exceed 3,300'

Facilities:

- Construct new SREB

Equipment:

- Grader, loader

Comments:

- Airport needs culvert replacements, lighting system, fence/gate repairs, striping, signage, storm drainage, and updated Master Plan.

KOTLIK (2A9)

Runway(s): 02/20 - 4400' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 3622

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 68,044

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Dozer Crawler 8-10T -- \$350,000

U/V Plow Grader/Loader -- \$350,000

Comments:

KOTZEBUE SPB (K36)

Runway(s): N/S

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification:

Enplanements:

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road:

Last Major Improvement:

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KOYUK (KKA) - Koyuk Alfred Adams

Runway(s): 01/19 - 3000' x 60' **Surface:** Gravel **Lighting:** BCN/Rwy_Lts/VASI
NAVAIDS: NDB/DME

Classification: Community	# Enplanements: 2118	Borough: Nome
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 69,385
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1991

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Koyuk Airport Improvements -- \$13,500,000

Dimensional:

Facilities:

Koyuk SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Lengthen the runway to 3,400', grade and resurface the existing runway, taxiway and apron, apply a dust palliative, remove existing obstructions and upgrade the lighting system.

KOYUKUK (KYU)

Runway(s): 06/24 - 4000' x 75' **Surface:** Gravel **Lighting:** BCN/MIRL/PAPI/REIL (Rwy 6 Only)
NAVAIDS: N/A

Classification: Community	# Enplanements: 847	Borough: Yukon-Koyukuk
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 118,399
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2003

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

- Koyukuk SRE Building Replacement -- \$2,000,000
- Lighted Supplemental Windcone -- \$70,000
- Survey, Clear Obstructions & Mark Property Boundary --\$100,000
- PAPI Needed (RWY 24) -- FAA

Equipment:

- Loader, Wheeled 1.5 CY -- \$350,000
- Rural Airport Grader -- \$350,000
- Compactor -- \$40,000
- Brush Cutter -- \$130,000

Comments:

KWETHLUK (KWT)

Runway(s): 18/36 - 3199' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 3871

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 14,664

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Construct a new 2,400' x 60' gravel crosswind runway

Construct a new 2,980' x 120' RSA

Correct/reconstruct safety area to include ruts, humps, depressions and ponding

Apply dust palliative

Reshape, re-crown and compact runway surface

Dimensional:

RSA maintenance (M&O)

Brush cutting (M&O OR)

Facilities:

Construct a 1-bay heated SREB with floor

Equipment:

30,000 LB GRADER

Purchase a new CAT D-4 dozer, loader is preferred over dozer

Comments:

KWIGILLINGOK (GGV)

Runway(s): 15/33 - 1835' x 40'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 3602

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 20,866

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2011

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Rehabilitate runway, taxiway, and apron surfaces

Scarify, reshape, and recompact runway, taxiway, and apron surface

Dimensional:

Expand existing runway to 3,300' x 60'

Facilities:

Construct two 1-bay SREBs

Equipment:

Grader, snow plow and wing attachments, loader

Comments:

Native Allotments and Tribal property need to be acquired.

AIP Surface Improvements funded in FFY'11 for Runway repair

Runway reduced to 1840 x 30 on 6-27-11 in message to FAA from the previous 2,472'.

Install an airport lighting system and nav aids

Install erosion projection for rwy embankment along tidal slough

Possible stream realignment

LAKE LOUISE (Z55)

Runway(s): 3/31 - 3000' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 2,779

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2010

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

LARSEN BAY (2A3)

Runway(s): 04/22 - 2690' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2336

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 19,345

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1993

Airfield Manager: ROBERT GREENE, 907-487-4952

NEEDS:

Surfaces:

Dimensional:

Regrade RSA

Facilities:

Construct a new 1-bay SREB

Equipment:

Grader, loader, snow removal equipment

Comments:

LAWING (9Z9)

Runway(s): 15/33 - 2200' x 50'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 0

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: SEAN MONTGOMERY, 907-262-1187

NEEDS:

Surfaces:

Clear brush along runway (per ALP)

Rehabilitate with new surface course

Replace windcone pole & threshold markers (M&O DM)

Dimensional:

Extend runway 240' beyond runway ends

Remove OFA/OFZ penetrations (per ALP)

Brush cutting

Facilities:

Equipment:

Comments:

LEVELOCK (9Z8)

Runway(s): 01/19 - 3281' x 59'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 292

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 23,067

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Place E-1 on apron, shoulders, and RSA and compact (M&O SPM)

Rehabilitate airfield with new aggregate on runway, taxiway, apron, shoulders, and RSA

Construct crosswind 07/25 runway (60'x2198')

Dimensional:

Extend RSA to 120' x 3761'

Facilities:

Equipment:

Grader, snow plow, loader wheel

Comments:

LIME VILLAGE (2AK)

Runway(s): 10/28 - 1500' x 55'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 10

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 630

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 42,936

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: STEFFEN STRICK, 907-524-3241

NEEDS:

Surfaces:

Construct new community class airport

Construct runway (4000' x 75'), taxiway, apron (60,000 sqft)

Construct RSA (4800' x 75')

Resurface eroded material on west end of runway

Dimensional:

Remove brush and trees from approaches

Facilities:

Construct SREB with rotating beacon (GF); Construct a second SREB

Equipment:

Grader and loader

Comments:

Install lighting, MIRL, taxiway lights, and 180 of fencing

Reestablish airport Right of Way (GF)

Embankment repair and obstruction removal (GF)

Airport is subject to river erosion and ice jam flooding.

Runway cannot be lengthened without expensive relocation

Bypass trail at the airport for access around the airport

Extend electric power lines to airport and acquire 50 acres of land

Remove trees from primary surface

Remove trees from approach and transitional surfaces

LITTLE DIOMEDE ISLAND / IGNALUK (DM2)

Runway(s): Heliport - 64' x 64' **Surface:** Concrete **Lighting:** BCN/Boundary Lts
NAVAIDS: N/A

Classification: Community	# Enplanements: 15	Borough: Nome
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 60,615
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement:

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Little Diomed Helipad Improvements -- \$1,800,000

Dimensional:

Facilities:

Little Diomed SRE Building Construction -- \$1,250,000

Equipment:

Dozer -- acquired, awaiting delivery due to lack of SREB.

Comments:

Repair ice scour damage to helipad embankment, replace riprap and upgrade the lighting system.

LIVENGOOD (4AK) - Livengood Camp

Runway(s): 15/33 - 1415' x 50'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 5

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 722

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 27,679

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Extend Runway to 3,400'

Facilities:

Equipment:

Comments:

Extend and widen the Livengood Airport runway to 3,400 feet by 75 feet.

MANLEY HOT SPRINGS (MLY)

Runway(s): 02/20 - 2850' x 20'

Surface: Turf/Dirt

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 116

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 17,153

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2012

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Construct SRE Building -- \$1,100,000 (AIP Portion of Funding)

Equipment:

Comments:

Construct a combined SRE and Highway M&O building at the Manley Airport. Awaiting state GF for the highway portin of the building.

MANOKOTAK (MBA)

Runway(s): 03/21 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 11903

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 3,008

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 39,420

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2007

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Extend runway to 4,000'

Extend apron additional 400' x 300'

Extend access road by apron

Construct additional taxiway

Dust palliative (M&O DM)

Dimensional:

Extend RSA to 4,600'

Facilities:

Equipment:

Comments:

Install PAPI, REILs

Construct additional lease lots

Install wind cone and segmented circle

MARSHALL (MDM) - Marshall Don Hunter Sr.

Runway(s): 07/25 - 3200' x 100' **Surface:** Gravel **Lighting:** BCN/Rwy_Lts/REIL
NAVAIDS: N/A

Classification: Community	# Enplanements: 2786	Borough: Wade Hampton
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 36,703
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1999

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

U/V Plow Grader/Loader -- \$350,000

Dozer Crawler 8-10T -- \$350,000

Comments:

MAY CREEK (MYK)

Runway(s): 13/31 - 2700' x 100'

Surface: Turf/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 939

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

MCCARTHY (I5Z)

Runway(s): 01/19 - 3500' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 7,010

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 26,217

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1999

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

MCGRATH (MCG)

Runway(s): 16/34 - 5936' x 100'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/VASI/REIL

NAVAIDS: LOC/DME/VORTAC

Classification: Regional

Enplanements: 10

Borough: Yukon-Koyukuk

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue: \$ 67,564

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$ 251,119

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2006

Airfield Manager: STEFFEN STRICK, 907-524-3241

NEEDS:

Surfaces:

- Rehabilitate runway, taxiway, and apron pavement
- Maintain pavement markings and crack seal (M&O SPM)
- Vehicle gates with push button electric
- Perimeter fencing repairs/replacement

Dimensional:

Facilities:

Equipment:

- Snow plow, snow blower, dump truck, snow attachments

Comments:

- Obstruction removal (GF)
- Abandon east GA apron and the GA "elephant ear" apron

MEKORYUK (MYU)

Runway(s): 05/23 - 3070' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/VASI/REIL

NAVAIDS: NDB/DME

Classification: Community

Enplanements: 1365

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 70,146

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1984

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Construct a new segment circle

Resurface runway and build crosswind runway

Dimensional:

Extend the existing runway to 4,000' and expand RSA accordingly

Facilities:

Construct new three bay SREB - current equipment - grader, snowblower/loader, dozer

Upgrade or construct heated SREB (current building may be past its useful life)

Equipment:

Loader wheel, grader, bulldozer, snow attachments, snow blower

Comments:

Design is complete for AIP funded airport rehabilitation and extension improvements, but ROW acquisition is dependent upon the condemnation of one Native Allotment, which is being considered. Also needs lighting installed and Master Plan update.

METLAKATLA SPB (MTM)

Runway(s): E/W, N/S - 5000' x 5000' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Community	# Enplanements: 4243	Borough: Prince of Wales
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2004

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'18 Seaplane Float Rehab/Reconfiguration -- \$1,000,000

Dimensional:

Facilities:

Equipment:

Comments:

MINCHUMINA (MHM)

Runway(s): 03/31 - 4184' x 100'

Surface: Gravel

Lighting: BCN/MIRL/PAPI (Rwy 3 Only)

NAVAIDS: NDB

Classification: Local

Enplanements: 284

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 1,732

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 115,436

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Minchumina Airport Improvements -- \$5,000,000

Dimensional:

Facilities:

Minchumina SRE Building Replacement -- \$2,000,000

Lighted Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary --\$100,000

PAPI Needed (RWY 21) -- FAA

Equipment:

Rural Airport Grader -- \$350,000

Compactor -- \$40,000

Brush Cutter -- \$130,000

Comments:

Resurface runway, apron and taxiway, remove obstructions, apply a dust palliative and install new lighting.

MINTO (51Z) - Minto Al Wright

Runway(s): 02/20 - 3400' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 192

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 11,362

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2007

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

MOUNTAIN VILLAGE (MOU)

Runway(s): 02/20 - 3501' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 4571

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 1,449

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 61,851

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2004

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Dozer Crawler 8-10T -- \$350,000

Comments:

NAKNEK (5NK)

Runway(s): 08/26 - 1950' x 50' 14/32 - 1850' x 45'	Surface: Gravel NAVAIDS: N/A	Lighting: BCN/Rwy_Lts
Classification: Local	# Enplanements: 40	Borough: Bristol Bay
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 60,206
Part 139 Cert: No	On/Off Road: On	Last Major Improvement:

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

- Resurface airport access road
- Construct new access road to apron/aviation support area
- Fix road and runway separation (GF)
- Construct a new 3,200' x 60' primary rwy, and 3,680' x 120' RSA
- Construct two aprons - 80 parking spaces
- Relocate runway 14/32 to correct safety, structural problems
- Construct new apron
- Replace the airport lighting

Dimensional:

Facilities:

- Construct a new regulator building; Construct new SREB

Equipment:

- Grader, snow blower, loader, snow removal attachments

Comments:

- Replace MIREL system (both runways); Improve drainage (GF)
- Replace all lighting cans on the airfield; Replace all hardware on the airfield
- Electrical vault replacement; Transformer replacement
- Floatplane base study for Nornek Lake

NANWALEK (KEB) - English Bay

Runway(s): 01/19 - 1850' x 50'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 2138

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 13,370

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KEVIN JONES, 907-235-5217

NEEDS:

Surfaces:

- Provide shore protection
- Construct airport parking apron
- Shape and compact runway and taxiway

Dimensional:

Facilities:

- Construct new SREB

Equipment:

Comments:

- Most substandard airport in the state system that serves a community with a significant population.
- Resolving Native Allotments will be very difficult and time consuming.
- Construct 2-mile access road connecting Port Graham & Nanwalek
- Study alternative locations for constructing a new airport
- Airport master plan - EA, geotech, and property analysis

NAPAKIAK (WNA)

Runway(s): 16/34 - 3248' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 1815

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 32,000

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Place E-1 on runway crown and compact

Apply dust palliative

Dimensional:

Brush Cutting (M&O OR)

Facilities:

Equipment:

Grader, loader, snow plow attachments

Comments:

Airport relocation study needed

NAPASKIAK (PKA)

Runway(s): 02/20 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1764

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 16,693

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1991

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Place E-1 on runway crown and compact

Apply dust palliative

Dimensional:

Facilities:

Construct a 1-bay heated SREB with floor

Equipment:

Grader, loader, snow plow attachments

Comments:

Electrical vault replacement

Transformer replacement

NELSON LAGOON (OUL)

Runway(s): 08/26 - 4003' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 305

Borough: Aleutians East

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 15,643

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1996

Airfield Manager: HAROLD KREMER, 907-532-5000

NEEDS:

Surfaces:

Grade taxiway, TSA, and apron (M&O SPM)

Place E-1 on runway crown, shoulders, and RSA, and compact

Dimensional:

Facilities:

Construct a new 1-bay SREB

Equipment:

Grader, loader, snow plow, motor grader

Comments:

Replacement runway lighting

Electrical vault replacement

Transformer replacement

NEW STUYAHOK (KNW)

Runway(s): 14/32 - 3281' x 98'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 672

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 550

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 28,563

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2006

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Construct crosswind 04/22 runway (3,300' x 60')

Construct ultimate taxiway

Resurface and apply dust palliative to runway, taxiway, and apron

Dimensional:

Expand the runway to 5,000' x 100'

Expand the RSAs

Facilities:

Equipment:

Grader, snow removal attachments

Comments:

Install PAPIs for 04/22 runway

NEWTOK (EWU)

Runway(s): 15/33 - 2202' x 35'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 2744

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 33,991

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1994

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Construct a new airport at Mertarvik (currently village is impacted by river erosion)

Construct 3,300' x 100' runway

Apply dust palliative

Dimensional:

Facilities:

1 heated SREB building

1 unheated SREB building

Equipment:

Dozer, prefer loader over dozer

Grader

Comments:

The Village and airport are threatened by river erosion. Village relocation proposed to Mertarvik. GF funding will probably be required for initial airport development. Use of AIP funding will likely trigger an EIS if the Village has not already moved. The FAA is hesitant to initiate an EIS for a Village relocation.

Construct lighting, 1.5-mile access road

Develop airport site alternatives upon relocation of community

Airport master plan

NIGHTMUTE (IGT)

Runway(s): 03/21 - 3180' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 1942

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 21,907

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2007

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Loader

Comments:

NIKOLAI (FSP)

Runway(s): 04/32 - 4003' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 306

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 34,355

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: STEFFEN STRICK, 907-524-3241

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader, loader, and snow removal attachments

Comments:

NINILCHIK (NIN)

Runway(s): 10/28 - 2400' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 4,500

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 520

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: SEAN MONTGOMERY, 907-262-1187

NEEDS:

Surfaces:

Safety Area grading

Runway grading

Resurface the gravel runway

Access Road rehabilitation

Dimensional:

Facilities:

Equipment:

U blade for loader

Comments:

Update ALP

NOATAK (WTK)

Runway(s): 01/19 - 3992' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 4088

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 7,403

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 100,284

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: ALVIN WERNEKE, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Noatak Airport Relocation -- \$13,000,000

Facilities:

Equipment:

Rural Airport Grader -- \$350,000

Loader, Wheeled 1.5 CY-- \$350,000

Comments:

Relocate the existing 4,000' x 60' airport, construct a new runway, apron, taxiway, aviation support area, SREB, apply a dust palliative and construct a new airport access road.

NOME (94Z) - Nome City Field

Runway(s): 03/21 - 1950' x 110'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 9,627

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 623

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ROBERT MADDEN, 907-443-3431

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

NONDALTON (5NN)

Runway(s): 02/20 - 2800' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 384

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 42,756

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

Dust palliative

Dimensional:

Remove obstructions (brush) (M&O OR)

Facilities:

Replace a 1-Bay SREB

Equipment:

Comments:

Install one or two apron concrete parking pads

NOORVIK (D76) - Robert/Bob/Curtis Memorial

Runway(s): 06/24 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 4188

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 64,579

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: ALVIN WERNEKE, 907-442-3147

NEEDS:

Surfaces:

Noorvik Airport Rehabilitation -- \$9,000,000

Dimensional:

Facilities:

Noorvik SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Repair runway shoulders, repair all airport operating surfaces and apply dust palliative.

NORTHWAY (ORT)

Runway(s): 05/23 - 5100' x 100' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/REIL/PAPI
NAVAIDS: VORTAC/NDB

Classification: Community	# Enplanements:	Borough: Fairbanks/North Star
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 2,908
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 54,256
Part 139 Cert: No	On/Off Road: On	Last Major Improvement:

Airfield Manager: DENNIS BISHOP, 907-883-5128

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Snowwing Grader -- \$350,000

Comments:

NULATO (NUL)

Runway(s): 02/20 - 4000' x 100'

Surface: Gravel

Lighting: BCN/MIRL

NAVAIDS: N/A

Classification: Community

Enplanements: 2442

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 94,149

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Lighted Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

PAPI & Wx Reporting Needed (RWY 21) -- FAA

Equipment:

Compactor -- \$40,000

Brush Cutter -- \$130,000

Comments:

NUNAM IQUA (SXP) - Sheldon Point

Runway(s): 01/19 - 3015' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1199

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 100,196

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Nunam Iqua Airport Runway Rehabilitation -- \$14,000,000

Dimensional:

Facilities:

Nunam Iqua Airport Access Road and Causeway Construction -- \$3,000,000

Equipment:

Comments:

Widen and extend the runway at Sheldon Point to at least 3,400' x 100' and lighting and grading improvements.

NUNAPITCHUK (16A)

Runway(s): 18/36 - 2420' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 3652

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 20,509

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2007

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Dimensional:

Facilities:

Construct 2 each 24' x 48' SREB (1heated/1unheated)

Installed 2 fuel storage tanks on the aviation support area

Reconstruct SREB

Equipment:

Grader, loader

Comments:

OLD HARBOR (6R7) - Sven Haakanson, Sr., Airport

Runway(s): 03/21 - 2750' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 2870

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 825

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 11,024

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: ROBERT GREENE, 907-487-4952

NEEDS:

Surfaces:

Resurface runway

Add security/wildlife fencing

Dimensional:

Extend the runway to 4,700'

Widen the runway to 75'

Remove ROFA obstructions (per ALP)

Brush cutting (M&O OR)

Facilities:

Construct a new 1-bay SREB (may need to look into 2-bay after extension project is completed)

Equipment:

Grader, loader, snow removal attachments

Comments:

OPHIR (Z17)

Runway(s): 11/29 - 2520' x 100'

Surface: Turf/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 11

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: STEFFEN STRICK, 907-524-3241

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

OUZINKIE (4K5)

Runway(s): 08/26 - 3300' x 60'

Surface: Gravel

Lighting: BCN

NAVAIDS: N/A

Classification: Community

Enplanements: 1862

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 25,696

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2011

Airfield Manager: ROBERT GREENE, 907-487-4952

NEEDS:

Surfaces:

Dust control (M&O SPM)

Dimensional:

Facilities:

Equipment:

Comments:

Develop a master plan

PEDRO BAY (4K0)

Runway(s): 09/27 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 90

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 36,314

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

Dimensional:

Conduct aeronautical study

Remove Part 77 penetrations

Remove obstructions (brush) (M&O OR)

Facilities:

Repair existing SREB building

Replace 1-Bay SREB

Equipment:

Grader, loader, snow removal attachments

Comments:

Install one or two apron concrete parking pads

PERRYVILLE (PEV)

Runway(s): 02/20 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 421

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 17,180

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader, aviation radio

Comments:

PETERSBURG (PSG) - Petersburg James A. Johnson

Runway(s): 05/23 - 6400' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/REIL/PAPI
NAVAIDS: LDA/DME/NDB

Classification: Regional	# Enplanements: 20046	Borough: Wrangell
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 55,995
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 451,467
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2009

Airfield Manager: MIKE ETCHER, 907-772-4624

NEEDS:

Surfaces:

FY'15 Apron/TWY Rehab -- \$3,000,000
FY'15 RSA Edges and Blast Pad Repair

Dimensional:

Facilities:

FY'22 Access Road Realignment, Parking, ROW -- \$3,200,000

Equipment:

FY'14 ARFF Truck -- \$1,000,000

Comments:

FY'15 Apron/TWY Rehab -- \$3,000,000
FY'15 RSA Edges and Blast Pad Repair

PETERSBURG SPB (63A) - Lloyd R. Roundtree Seaplane Facility

Runway(s): NE/SW - 9000' x 1100'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 404

Borough: Wrangell

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 6,425

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 14,937

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: MIKE ETCHER, 907-772-4624

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

PILOT POINT (PNP)

Runway(s): 07/25 - 3280' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 644

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 100

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 20,474

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Expand apron

Construct 49' taxiway

Extend existing access road

Dimensional:

Expand the runway to 5,050' x 100'

Expand the RSAs

Facilities:

Equipment:

Grader, loader wheel, snow plow, snow removal attachments

Comments:

PILOT STATION (OAK)

Runway(s): 07/25 - 2541' x 55'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 3123

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 53,846

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1996

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Pilot Station Airport Relocation -- \$15,700,000

Dimensional:

Facilities:

Equipment:

Loader, Wheeled 1.5 CY -- \$350,000

Comments:

Relocate the airport at Pilot Station away from the community.

PLATINUM (PTU)

Runway(s): 14/32 - 5000' x 75'

Surface: Gravel

Lighting: BCN

NAVAIDS: N/A

Classification: Community

Enplanements: 961

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 37,495

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2014

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Develop lease lots

Install airport lighting (in design)

POINT BAKER SPB (63A)

Runway(s): N/S - 4000' x 250'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 16

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 2,766

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 0

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1994

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Float rehab

Dimensional:

Facilities:

Equipment:

Comments:

POINT HOPE (PHO)

Runway(s): 01/19 - 3992' x 75'	Surface: Asphalt	Lighting: BCN/Rwy_Lts/VASI
	NAVAIDS: NDB	
Classification: Community	# Enplanements: 4735	Borough: North Slope
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 1,023
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 121,994
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1992

Airfield Manager: ALVIN WERNEKE, 907-442-3147

NEEDS:

Surfaces:

Point Hope Airport Runway Realignment -- \$18,500,000

Dimensional:

Realign the runway and increase the length by 8 feet to 4,000 feet.

Increase the RSA to meet the current design standards.

Upgrade the NAVAIDS from VASI to PAPI

Facilities:

Equipment:

Comments:

Realign runway to avoid runway shortening due to coastal erosion. Expand the RSA to meet design standards.

PORT ALEXANDER SPB (AHP)

Runway(s): N/S - 3000' x 300'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 16

Borough: Wrangell

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

PORT GRAHAM (PGM)

Runway(s): 12/30 - 1875' x 45'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 1806

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 18,215

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KEVIN JONES, 907-235-5217

NEEDS:

Surfaces:

Construct airport parking apron

Airport relocation

Dimensional:

Facilities:

Construct new SREB

Equipment:

30,000 LB GRADER

Comments:

PORT HEIDEN (PTH)

Runway(s): 05/23 - 5000' x 100'
13/31 - 4000' x 100'

Surface: Gravel
NAVAIDS: NDB/DME

Lighting: BCN/Rwy_Lts/VASI/
REIL/PAPI

Classification: Community

Enplanements: 730

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 1,575

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$ 68,016

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Loader wheel, aviation radio

Comments:

Airport has known contamination issues from DOD activities from WWII.

Construct additional lease lots

Update ALP

PORT LIONS (ORI)

Runway(s): 07/25 - 2200' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1860

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 27,140

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2011

Airfield Manager: ROBERT GREENE, 907-487-4952

NEEDS:

Surfaces:

- Construct apron and taxiway
- Reconstruct or relocate airport
- Reconstruct or relocate airport access road
- Erosion control, improved drainage, brush cutting
- Dust control (M&O SPM)

Dimensional:

- Obstruction removal; Rotate the airport; Extend runway to 3,300'
- Brush cutting (M&O OR)
- Remove 20:1 ground penetrations and tree obstructions on RWY 7 approach

Facilities:

- Construct a new, heated 2-bay SREB

Equipment:

- Loader, grader

Comments:

- Community also served by the AMHS and is a short boat ride from accessing a road to the City of Kodiak.
- Install new lighting system, rotating beacon, PAPIs, and REILs
- Install wind cones, modify utilities, and update lease lots
- Land acquisition (5 parcels)
- Develop a master plan

PORT PROTECTION SPB (19P)

Runway(s): NW/SE

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 97

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'19 Replace seaplane float -- \$600,000

Dimensional:

Facilities:

Equipment:

Comments:

PORTAGE CREEK (A14)

Runway(s): 10/28 - 1920' x 60'
01/19 - 1470' x 60'

Surface: Dirt/Gravel
NAVAIDS: N/A

Lighting: N/A

Classification: Local

Enplanements: 12

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 17,212

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1984

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Repair erosion on both runway edges

Resurface and apply dust palliative to runway, taxiway, and apron

Dimensional:

Remove RSA, OFZ, OFA, threshold siting surface obstructions (per ALP)

Facilities:

Reclaim existing 1-bay SREB

Construct a new 2-bay heated SREB

Equipment:

Grader & loader with attachments

Purchase an aviation radios

Comments:

Obstruction removal (GF)

PROSPECT CREEK (PPC)

Runway(s): 01/19 - 4968' x 150'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: NDB

Classification: Local

Enplanements: 631

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 320

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 0

Part 139 Cert: Yes

On/Off Road:

Last Major Improvement:

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Extend the land lease with the BLM. M&O provided by Alyeska Pipeline Service Co.

QUARTZ CREEK (5QC) - Kougarak

Runway(s): 12/30 - 2960' x 64'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Nome

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 752

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 729

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Quartz Creek Airport Improvements -- \$500,000

Dimensional:

Facilities:

Equipment:

Comments:

Rehabilitate airport for all-season operations, including runway surface repairs and vegetation clearing.

RAMPART (RMP)

Runway(s): 11/29 - 3520' x 75' **Surface:** Gravel **Lighting:** BCN/MIRL/REIL/PAPI (Rwy 11 Only)
NAVAIDS: N/A

Classification: Local **# Enplanements:** 248 **Borough:** Yukon-Koyukuk
Air Carrier Hub: No **Medical Facility:** Yes **Annual Revenue:** \$ 0
USPS Hub: No **School Facility:** No **Ops Cost/Yr:** \$ 119,715
Part 139 Cert: No **On/Off Road:** Off **Last Major Improvement:** 2001

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

SRE Building Replacement -- \$2,000,000
Lighted Supplemental Windcone -- \$70,000
Survey, Clear Obstructions and Mark Property Boundary -- \$100,000
PAPI, WX Reporting & WX Cameras Needed -- FAA

Equipment:

Rural Airport Grader -- \$350,000
Loader, Wheeled 1.5 CY -- \$350,000
Compactor -- \$40,000
Brush Cutter -- \$130,000

Comments:

RED DEVIL (RDV)

Runway(s): 10/28 - 4820' x 75'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 40

Borough: Bethel

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 650

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 25,765

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Construct a new taxiway and apron

Apply dust palliative

Dimensional:

Brush Cutting

Facilities:

Equipment:

Grader, bulldozer

Comments:

Prepare an ALP

RUBY (RBY)

Runway(s): 03/21 - 4000' x 100' **Surface:** Gravel **Lighting:** BCN/MIRL/REIL/PAPI (Rwy 21 Only)
NAVAIDS: N/A

Classification: Community **# Enplanements:** 2388 **Borough:** Yukon-Koyukuk
Air Carrier Hub: No **Medical Facility:** Yes **Annual Revenue:** \$ 320
USPS Hub: No **School Facility:** Yes **Ops Cost/Yr:** \$ 137,885
Part 139 Cert: No **On/Off Road:** Off **Last Major Improvement:** 1992

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Ruby Aiport Improvements -- \$6,000,000

Dimensional:

Facilities:

Lighted Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

PAPI Needed (RWY 21) -- FAA

Equipment:

Compactor -- \$40,000

Brush Cutter -- \$130,000

Comments:

Airport Imp-Resurface runway, apron and taxiway, apply a dust palliative, upgrade the lighting system, reroute road and remove terrain obstruction.

RUSSIAN MISSION (RSH)

Runway(s): 17/35 - 3620' x 100'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 2272

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 104,373

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2000

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader 34,000# -- \$350,000

U/V Plow Grader/Loader -- \$350,000

Comments:

SAINT GEORGE (PBV)

Runway(s): 11/29 - 4982' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/REIL/PAPI
NAVAIDS: ILS/NDB

Classification: Community	# Enplanements: 372	Borough: Aleutians West
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 1,070
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 169,239
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2005

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

- Maintain pavement markings and crack seal
- Vehicle gates with push button electric
- Perimeter wildlife fencing

Dimensional:

Facilities:

- Installation of FAA weather cameras

Equipment:

- Loader mounted snow blower

Comments:

- Update current ALP

SAINT MICHAEL (SMK)

Runway(s): 02/20 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2233

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 62,960

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Saint Michael Airport Improvements -- \$8,300,000

Dimensional:

Facilities:

SRE Building Upgrade -- \$825,000

Equipment:

Snowwing Grader -- \$350,000

U-Blade Loader 10CY -- \$350,000

Loader Wheeled 1.5CY -- \$350,000

Comments:

Rehabilitate the runway, taxiway, apron and airport lighting, stabilize slopes, rehabilitate shoulders, apply dust palliative, and repair and resurface the airport access road.

SAINT PAUL ISLAND (SNP)

Runway(s): 18/36 - 6500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/VASI
NAVAIDS: ILS/DME/NDB

Classification: Community	# Enplanements: 2676	Borough: Aleutians West
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 1,425
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 156,939
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2004

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

- Maintain pavement markings and crack seal
- Vehicle gates with push button electric
- Perimeter fencing repairs/replacement

Dimensional:

Facilities:

Equipment:

- Snow blower

Comments:

SALMON LAKE (Z81)

Runway(s): 15/33 - 1860' x 55'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Nome

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 0

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

SAND POINT (SDP)

Runway(s): 13/31 - 5213' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/REIL/PAPI
NAVAIDS: NDB

Classification: Community	# Enplanements: 3976	Borough: Aleutians East
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 14,467
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 88,169
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2005

Airfield Manager: HAROLD KREMER, 907-532-5000

NEEDS:

Surfaces:

- Maintain pavement markings and crack seal
- Vehicle gates with push button electric
- Perimeter fencing repairs/replacement

Dimensional:

- Place a fabric type barrier on riprap on the bayside to prevent rock topping runway
- Fines wash away from RSA on the bay side due to overtopping

Facilities:

- Demolish existing sand storage building and attach freight office build
- Construct new heated sand storage building with concrete floor, 400 cubic yard capacity
- Construct a new 2-bay SRE/ARFF building w/ 16' wide doors, an office/training room, a restroom/

Equipment:

- Loader wheel, snow blower

Comments:

- Install water and sewer for SRE/ARFF building
- Obstruction removal

SAVOONGA (SVA)

Runway(s): 05/23 - 4400' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: VOR/DME

Classification: Community

Enplanements: 3099

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$ 135,727

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

SCAMMON BAY (SCM)

Runway(s): 10/28 - 3000' x 75'

Surface: Dirt

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 4178

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 31,771

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Scarify, reshape and recompact surfacing material. Needs 1000 CY of surface course aggregate

Dimensional:

Facilities:

Construct a new SREB

Equipment:

grader, snow blower, loader wheel, bulldozer, snow attachments

Comments:

Lighting upgrades

Repair existing 48" culvert

SELAWIK (WLK)

Runway(s): 04/22 - 3002' x 60'
09/27 - 2659' x 60'

Surface: Gravel
NAVAIDS: VOR/DME

Lighting: BCN/Rwy_Lts/VASI/PAPI

Classification: Community

Enplanements: 4336

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 86,914

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1998

Airfield Manager: ALVIN WERNEKE, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Selawik Airport Runway Extension -- \$12,000,000

Facilities:

Selawik SRE Building Upgrade -- \$500,000

Equipment:

Comments:

Expand the existing Runway 04/22 at Selawik to at least 3,400' x 75' and complete electrical and grading improvements.

SELDOVIA (SOV)

Runway(s): 16/34 - 1845' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 3774

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 11,908

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 51,100

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: GEORGE OLIVEIRA, 907-234-7818

NEEDS:

Surfaces:

Improve drainage (M&O SPM)

Pave runway and apron

Reconstruct or relocate the airport

Rehabilitate access road (GF)

Remove runway obstructions

Dimensional:

Expand RSA on approach end of runway 16 to 300'

Facilities:

Equipment:

Comments:

Runway cannot be significantly extended. More research to determine if gravel or pavement is safer for this airport.

Lighting not recommended due to extreme terrain hazards

Community served by the AMHS and water taxis.

Extend city water and sewer to the new SREB

Provide a master plan

SEWARD (SWD)

Runway(s): 13/31 - 4533' x 100'
16/34 - 2289' x 75' **Surface:** Asphalt **Lighting:** BCN/Rwy_Lts/VASI
NAVAIDS: N/A

Classification: Community	# Enplanements:	Borough: Kenai Peninsula
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 10,831
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 24,605
Part 139 Cert: No	On/Off Road: On	Last Major Improvement: 1991

Airfield Manager: SEAN MONTGOMERY, 907-262-1187

NEEDS:

Surfaces:

- Reconstruct both runways at higher elevation
- Increase erosion protection entire length of 13/31
- Repave taxiways and apron; Construct helipad; Construct public parking
- Maintain pavement markings (M&O SPM); Security signage and lighting repairs
- Replace airport lighting system

Dimensional:

- Displace threshold of runway 30 to 100' north; Widen taxiway A

Facilities:

- Construct a 4-bay SREB

Equipment:

- Dump truck, deicing truck, loader, snow removal attachments

Comments:

- Security signage; Lighting repairs; Drainage work
- Replace airfield lighting
- Repair or replace nav aids
- Repair/replace markings and install security fencing
- Water and sewer service for SREB
- Update and revise the existing ALP
- Acquire property interest to contain runway 16 RPZ

SHAGELUK (SHX)

Runway(s): 16/34 - 3400' x 75'

Surface: Gravel

Lighting: BCN/App-Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 921

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 109,695

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2000

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Dimensional:

Facilities:

Shageluk SRE Building Replacement -- \$2,000,000

Equipment:

U/V Plow Grader/ Loader -- \$350,000

Dozer Crwlr 8-10T -- \$350,000

Comments:

Reconstruct the 4-mile airport access road to include embankment stabilization, minor realignment and resurfacing.

SHAKTOOLIK (2C7)

Runway(s): 14/32 - 4001' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 2022

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 60,614

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1998

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

SHEEP MOUNTAIN (SMU)

Runway(s): 05/23 - 2270' x 10'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 640

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 318

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: STEVE BANSE, 907-745-5116

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

SHISHMAREF (SHH)

Runway(s): 05/23 - 4997' x 75'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: NDB

Classification: Community

Enplanements: 2490

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 2,621

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 162,984

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Resurface the runway, taxiway, and apron at the Shishmaref Airport.

SHUNGNAK (SHG)

Runway(s): 09/27 - 4001' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 2151

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 2,438

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 75,855

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1996

Airfield Manager: ALVIN WERNEKE, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Facilities:

Shungnak SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

SITKA (SIT) - Sitka Rocky Gutierrez

Runway(s): 11/29- 6500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/HIRL/VASI/REIL
NAVAIDS: LDA/DMA/VORTAC

Classification: Regional	# Enplanements: 67989	Borough: Sitka
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 66,773
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 1,156,482
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2011

Airfield Manager: DAVE LUCHINETTI, 907-966-2960

NEEDS:

Surfaces:

Dimensional:

FY'16 GA Apron Development (Charcoal Island)-- \$3,000,000

FY'18 Construct Partial Parallel TWY -- \$32,600,000

FY'18 Expand GA Apron and Lease Lots -- \$5,000,000

Facilities:

FY'16 Property Acquisition -- \$1,100,000

Equipment:

FY'14 ARFF Truck -- \$1,000,000

Comments:

SKAGWAY (SGY)

Runway(s): 02/20 - 3500' x 75'

Surface: Asphalt

Lighting: Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 8050

Borough: Skagway

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 24,689

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 58,261

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1999

Airfield Manager: MISSY TYSON, 907-983-2323

NEEDS:

Surfaces:

Dimensional:

Facilities:

FY'15 Property Acquisition -- \$200,000

FY'16 Replace REILs & turn over to FAA

Equipment:

Comments:

SKWENTNA (SKW)

Runway(s): 10/28 - 3400' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements: 170

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 1,823

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 142,114

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1987

Airfield Manager: STEVE BANSE, 907-745-2159

NEEDS:

Surfaces:

Embankment protection needed

Dimensional:

Tree removal (M&O OR)

Upgrade airport lighting

Facilities:

Move the existing maintenance shop and generator

Construct a new two-bay SREB

Provide a 10k generator for lighting

Equipment:

Grader, loader wheel, snow blower

Comments:

Upgrade the lighting system (GF)

SLEETMUTE (SLQ)

Runway(s): 14/32 - 3100' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 313

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 32,710

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Resurface runway

Construct new apron and taxiway

Dimensional:

Brush Cutting (M&O OR)

Facilities:

Demolish existing 1-bay SREB

Construct a new 2-bay heater SREB with floor

Equipment:

Grader, bulldozer, loader, snow attachments

Comments:

Obstruction removal (GF)

Airport has not been federally obligated. The department's airport property interest is nearing expiration

Construct new access road

Repair and extend lighting system

SOUTH NAKNEK (WSN)

Runway(s): 12/30 - 3314' x 60' 04/22 - 2264' x 60'	Surface: Dirt/Gravel NAVAIDS: N/A	Lighting: BCN/HIRL/VASI
Classification: Local	# Enplanements: 79	Borough: Dillingham
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: No	Ops Cost/Yr: \$ 22,506
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1996

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

- Rehabilitate runway, crosswind runway, and apron
- Correct RSAs
- Reconfigure displaced threshold
- Correct Rwy 04/22 sinking - "Rwy 04-22 sinking east 1400' CLOSED indef."

Dimensional:

- Upgrade airport lighting

Facilities:

Equipment:

- Grader

Comments:

- Replace MIRL on runway 30 end

STEBBINS (WBB)

Runway(s): 05/23 - 2999' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2244

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 1,584

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 83,234

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Dimensional:

Stebbins Airport Runway Extension -- \$3,000,000

Facilities:

Stebbins SRE Building Replacement -- \$2,000,000

Equipment:

U/V Plow Grader/ Loader -- \$350,000

Comments:

Expand and widen the runway to 3,400' x 75', expand apron and taxiway, reduce obstructions, and apply dust palliative to the operational surfaces.

STEVENS VILLAGE (SVS)

Runway(s): 05/23 - 4000' x 75'

Surface: Gravel

Lighting: BCN/MIRL/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 578

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 77,326

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Lighted Supplemental Windcone -- \$70,000

Survey, Clear Obstructions & Mark Property Boundary -- \$100,000

WX Reporting Needed - FAA

Equipment:

Rural Airport Grader -- \$350,000

Compactor -- \$40,000

Brush Cutter -- \$130,000

Comments:

STONY RIVER (SRV)

Runway(s): 18/36 - 2601' x 40'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 67

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 41,939

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Runway resurface

Construct a seperated apron and taxiway

Improve drainage by runway

Dimensional:

Expand runway to 3,200' x 75'

Facilities:

Construct a temporary equipment building

Equipment:

Purchase a grader and dozer

Comments:

Airport requires lease lot acquisition, lighting improvements, floatplane dock, Master Plan update, removal of tree obstructions on rwy 21, and new access road to GA apron. Minor repair of the existing RWY with AIP Surface maintenance funding in 2012

SUMMIT (UMM)

Runway(s): 03/21 - 3840' x 80'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 320

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 11,497

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: TOM WILLIAMS, 907-451-5280

NEEDS:

Surfaces:

Summit Airport Improvements -- \$5,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Rehabilitate and resurface runways, taxiways, and apron, apply a dust palliative and replace airport lighting.

TAKOTNA (TCT)

Runway(s): 04/22 - 3300' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 380

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 83,795

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2013

Airfield Manager: STEFFEN STRICK, 907-524-3241

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

TALKEETNA (TKA)

Runway(s): 18/36 ' 3500' x 75'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: VOR/DME

Classification: Community

Enplanements: 3

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 65,296

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 142,242

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1996

Airfield Manager: STEPHEN HANSON, 907-733-2278

NEEDS:

Surfaces:

- Maintain pavement markings and crack seal (M&O SPM)
- Rehabilitate pavement on runway 18/36, taxiways, and apron
- Construct transient apron/embankment for future GA and lease lot development
- Expand the commercial and transient apron
- Construct a helipad, associated apron, and FSS parking
- Vehicle gates with push button electric
- Perimeter fencing repairs/replacement

Dimensional:

- Expand commercial, GA and transient aircraft parking
- Apply herbicide in area between Taxiways A and C

Facilities:

Equipment:

- Snow blower, grader, loader wheel

Comments:

- Construct fencing to partially enclose airport perimeter; Install signage
- Construct pedestrian pathway to encourage tourists to keep away from operational surfaces
- Evaluate flood mitigation measures through hydrologic studies
- Allow for additional lease lot development
- Construct a fence to partially enclose airport
- Acquire property for a new access road

TANANA (TAL) - Ralph M. Calhoun Memorial

Runway(s): 07/25 - 4400' x 100' **Surface:** Gravel **Lighting:** BCN/Boundary Lts/VASI (RWY 7 Only)
NAVAIDS: VOR/DME/NDB

Classification: Community	# Enplanements: 2811	Borough: Yukon-Koyukuk
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 1,962
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 97,588
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2004

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

SRE Building Replacement -- \$2,000,000, Lighted Supplemental Windcone -- \$70,000
Survey, Clear obstructions and Mark Property Boundary -- \$100,000
PAPI (RWY 25 only) needed -- FAA

Equipment:

Loader, Wheeled 1.5 CY -- \$350,000
Compactor -- \$40,000
Brush Cutter -- \$130,000

Comments:

TATITLEK (7KA)

Runway(s): 13/31 - 3701' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 82,338

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: STEVE SEARLES, 907-835-5658

NEEDS:

Surfaces:

Dimensional:

Facilities:

Tatitlek SRE Building Replacement -- \$2,000,000

Equipment:

Snowwing Grader -- \$350,000

Comments:

TAZLINA (Z14)

Runway(s): 13/31 - 1200' x 40'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 3,498

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

TELLER (TER)

Runway(s): 07/25 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 927

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 85,594

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1999

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Dimensional:

Teller Airport Runway Extension and Crosswind Runway Construction -- \$5,000,000

Facilities:

Teller SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Lengthen and widen the existing runway, construct a crosswind runway and install new lighting.

TENAKEE SPRINGS SPB (TKE)

Runway(s): E/W - 10000' x 7000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 798

Borough: Hoonah-Angoon

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 0

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

TETLIN (3T4)

Runway(s): 08/26 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements: 26

Borough: Fairbanks/North Star

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 5,818

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2003

Airfield Manager: DENNIS BISHOP, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

TOGIAK VILLAGE (TOG)

Runway(s): 03/21 - 4400' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/VASI/PAPI

NAVAIDS: NDB/DME

Classification: Community

Enplanements: 943

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 5,432

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 29,665

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1982

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

- Construct a new crosswind runway
- Resurface gravel runways, taxiways, and apron
- Place E-1 on runway crown and compact
- Apply dust pallitive
- Replace the airport lighting (upgrade to HIRL)
- Expand the runway to minimum 100' x 5500' paved
- Pave taxiways and aprons
- Install security fencing around perimeter

Dimensional:

Facilities:

- Replace the existing 2-bay SREB with a heated 2-bay SREB with 20' wide doors, a pole mounted rotating beacon, concrete floors with an oil-water separator system (in design)
- Construct a separate electrical enclosure
- Add two 3,000 gallon double wall fire ra

Equipment:

- 3 CY LOADER WHEEL; SNOW BLOWER
- Purchase a replacement loader with mounted snow blower

Comments:

Togiak Airport Snow Removal Equipment Building (52582) is in Design Phase. Construction estimated to being April 2015.

TOK (6K8) - Tok Junction

Runway(s): 07/25 - 2509' x 50'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: N/A

Classification: Community

Enplanements: 462

Borough: Valdez-Cordova

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue: \$ 13,411

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 6,234

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1999

Airfield Manager: DENNIS BISHOP, 907-883-5128

NEEDS:

Surfaces:

Dimensional:

Runway Extension -- \$3,000,000

Crosswind Runway Construction -- \$3,500,000

Facilities:

Visual Glide Slope Indicator Lighting Replacement -- \$2,500,000

Equipment:

Comments:

Lengthen and widen the existing runway, realign Taxiway A and install new lighting. Construct a crosswind runway.

TOKSOOK BAY (OOK)

Runway(s): 16/34 - 3218' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 5206

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 3,060

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 35,973

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

- Construct a new gravel crosswind runway
- Construct a new RSA
- Repair soft spot/rebuild taxiway
- Rehabilitate the runway and add needed surface course
- Build up the airport access road and resurface

Dimensional:

Facilities:

- Construct a 1-bay heated SREB with floor

Equipment:

- Dozer and grader, loader

Comments:

- Requires access road, utility relocation, NAVAID modification.
- Develop, evaluate and present alternative concepts to reconstruct or relocate the airport. Products of this study will include an airport master plan, an environmental assessment, an airport layout plan, design level surveying, controlled aerial photography and geotechnical soils analysis of the preferred airport alternative.

TULUKSAK (TLT)

Runway(s): 15/33 - 3300' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2641

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 49,920

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2012

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Scarify, reshape and recompact runway, taxiway and apron

Apply dust palliative

Dimensional:

Facilities:

Equipment:

Comments:

TUNTUTULIAK (A61)

Runway(s): 02/20 - 3025' x 90'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 3665

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 36,395

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2006

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Scarify, reshape, and recompact runway, taxiway, and apron surface (M&O SPM)

Dimensional:

Facilities:

Equipment:

Loader

Comments:

TUNUNAK (4KA)

Runway(s): 08/26 - 1778' x 30'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1791

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 56,973

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2012

Airfield Manager: L.J. DAVIS, 907-545-4617

NEEDS:

Surfaces:

Dimensional:

Extend runway

Expand apron

Facilities:

Build a new SREB (in design)

Equipment:

Grader, dozer, snow plow, loader wheel

Comments:

TWIN HILLS (A63)

Runway(s): 18/36 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 43

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 41,409

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1994

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Resurface and apply dust palliative to runway, taxiway, and apron

Dimensional:

Brush Cutting (M&O OR)

Facilities:

Construct a new additional heated 1-bay SREB with 20' wide door, a pole mounted rotating beacon, concrete floors with an oil-water separator system

Add two 3,000 gallon double wall fire rated fuel tanks; one with fuel dispenser

Equipment:

Grader & loader both with snow attachments

Comments:

Add distance between airport and waste facilities (per ALP)

Install MIRL, and PAPIs or REILs

Identify pad for and install AWOS

UGASHIK (9A8)

Runway(s): 06/24 - 3100' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 9

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 15,790

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 0

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Dimensional:

Remove ROFA obstructions

Facilities:

Equipment:

Grader

Comments:

Add distance between airport and waste facilities (per ALP)

Install MIRL, and PAPIs or REILs

Identify pad for and install AWOS

UMIAT (UMT)

Runway(s): 06/24 - 5583' x 100'

Surface: Gravel

Lighting: BCN

NAVAIDS: N/A

Classification: Local

Enplanements: 652

Borough: North Slope

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 39,041

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 2,089

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Umiat Airport Lease Lot Development -- \$2,500,000

SREB construction -- \$3,000,000

Airfield lighting installation -- \$100,000

PAPI, WX Reporting & WX Camera needed -- FAA

Equipment:

Snow Wing Grader -- \$350,000

Dozer Crawler 8-10T -- \$350,000

Comments:

Surveying airport lease lots, placing fill material, installing fencing and developing an updated land occupancy drawing.

UMNAK - Ft. Glenn

Runway(s): Inactive / Abandoned

Surface:

Lighting:

NAVAIDS:

Classification:

Enplanements:

Borough: Aleutians West

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 0

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ,

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

UMNAK - North Shore

Runway(s): Inactive / Abandoned

Surface:

Lighting:

NAVAIDS:

Classification:

Enplanements:

Borough: Aleutians West

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 0

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ,

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

UNALASKA / DUTCH HARBOR (DUT) - Tom Madsen Airport

Runway(s): 12/30 - 4100' x 100' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/VASI/REIL
NAVAIDS: NDB/DME

Classification: Regional	# Enplanements: 28556	Borough: Aleutians West
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 48,928
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$ 1,008,565
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2014

Airfield Manager: DALE RUCKMAN, 907-581-1786

NEEDS:

Surfaces:

Rehabilitate pavement (hangar/terminal apron, taxiway A); Pave road by Ramp A gate
Maintain pavement markings (M&O SPM); Vehicle gates with electronic swipe capability
Perimeter fencing and gate repairs/replacement; Repair Apron B; Maintain crack seal

Dimensional:

Erosion control along runway; Embankment being eroded center south side of the runway

Facilities:

Torpedo building demolition and cleanup (GF)
Convert WWII hangar into a chemical storage building (GF) (in design - project to bid for 2014)
Rehabilitate existing WWII hangar into deicing chem storage tank, mixing tank, a vehicle, and miscella

Equipment:

Deicer truck; ARFF bunker gear; ARFF SCBA compressor
Badging computer, software upgrade and printers

Comments:

Move residential trailers off airport property; Update the Master Plan
Construct a boat launch ramp; Environmental analysis
Replace 4,600' of 8' fence, 150' of 4' fence
Replace 3 drive through gates and 3 pedestrian gates
Construct additional lease lots
Airport Safety Improvements (in design)
Chemical and Equipment Storage Building (in design) - Est Apr '15

VALDEZ (VDZ) - Valdez Pioneer Field

Runway(s): 06/24 - 6500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/REIL/PAPI
NAVAIDS: LDA/DME/NDB

Classification: Regional	# Enplanements: 13318	Borough: Valdez-Cordova
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 95,230
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 972,891
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2007

Airfield Manager: STEVE SEARLES, 907-835-4695

NEEDS:

Surfaces:

Dimensional:

Facilities:

Valdez Airport Security Upgrades -- \$2,500,000

Equipment:

Snowplow 1 Way Ridg -- \$350,000

Snow Wing Truck -- \$350,000

ARFF Vehicle -- \$1,000,000

Broom Runway Push -- \$350,000

Truck Plow Airport 4x4 -- \$350,000

Airport Operations Vehicle -- \$80,000

Handicap Pass Loader -- \$350,000

Snow Blower 7,500 ton per hour

Comments:

Construct a deicing material storage building at the Valdez Airport.

WALES (IWK)

Runway(s): 18/36 - 3990' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 1259

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 550

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 96,942

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1991

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Wales Airport improvements -- \$5,500,000

Dimensional:

Facilities:

Wales SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface runway, apron and taxiway, and install new lighting.

WHALE PASS SPB (96Z)

Runway(s): NW/SE - 10000' x 1000' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Community	# Enplanements: 189	Borough: Prince of Wales
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 0
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 1,572
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

WHITE MOUNTAIN (WMO)

Runway(s): 15/33 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1270

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 53,483

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1991

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

White Mountain Airport Improvements -- \$3,500,000

Dimensional:

Facilities:

White Mountain SRE Upgrade -- \$150,000

Equipment:

Comments:

Resurface runway, apron and taxiway, apply a dust palliative and upgrade lighting system.

WHITTIER (IEM)

Runway(s): 04/22 - 1480' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 0

USPS Hub:

School Facility: Yes

Ops Cost/Yr: \$ 12,757

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: PAUL BERTHOLL, 907-783-2232

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Conduct airport master plan
continues

Shot Gun Cove Rd expansion

WILLOW (UO)

Runway(s): 13/31 - 4400' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Local

Enplanements: 5002

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$ 63,357

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$ 71,745

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1989

Airfield Manager: RAYMOND ADAMS, 907-495-6286

NEEDS:

Surfaces:

- Place E-1 on runway, taxiways, and service areas, and compact Runway and taxiway resurface
- Construct a new GA apron with 100 tie downs
- Construct vehicle parking for the apron; Construct new lighted segmented circle
- Apply dust palliative, Senior Center Access Road Relocation
- Vehicle gates with push button electric
- Perimeter fencing repairs/replacement; Dedicated helicopter operations area

Dimensional:

- Cut trees and remove hill by South Taxiway (M&O OR)

Facilities:

- Construct a new SREB

Equipment:

- 4 to 6 CY LOADER WHEEL; SNOW BLOWER

Comments:

- Removal of island in Willow Lake (GF)
- Install fencing for the perimeter of the upland airport
- Install barrier fencing behind the floatplane leaseholds
- Rehabilitation/extension of the existing access road
- Tree clearing
- Airport master plan

WISEMAN (WSM)

Runway(s): 02/20 - 2000' x 30'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$ 0

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$ 2,656

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Wiseman Airport Rehabilitation -- \$400,000

Dimensional:

Facilities:

Wiseman Airport Access Road Improvements -- \$200,000

Equipment:

Comments:

Runway surface repairs, brushing, and tree clearing.

WRANGELL (WRG)

Runway(s): 10/28 - 5999' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/HIRL/VASI/REIL
NAVAIDS: LDA/DME

Classification: Regional	# Enplanements: 11807	Borough: Wrangell
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$ 21,997
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 436,728
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2006

Airfield Manager: WILLIE BLOOM, 907-874-3107

NEEDS:

Surfaces:

FY'15 Apron/TWY Rehab -- \$3,000,000

Dimensional:

FY'17 Apron & Lease Lot Development -- \$3,500,000

Facilities:

Equipment:

FY'18 Self-Propelled Runway Broom -- \$550,000

Comments:

FY'17 WHA/WHMP Update \$140,000

YAKUTAT (YAK)

Runway(s): 11/29 - 7745' x 150'
02/20 - 6475' x 150' **Surface:** Asphalt **Lighting:** BCN/App_Lts/VASI/REIL/PAPI
NAVAIDS: ILS/DME/VOR

Classification: Regional	# Enplanements: 10135	Borough: Yakutat
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$ 159,260
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$ 648,237
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2004

Airfield Manager: ROBERT LEKANOF, 907-784-3293

NEEDS:

Surfaces:

FY'15 RWY 11/29 Rehab -- \$7,500,000

Dimensional:

Facilities:

FY'14 Aeronautical Survey -- \$250,000

FY'15 Perimeter Fence -- \$2,000,000

Wildlife Hazard Assessment -- \$140,000

Equipment:

Comments:

FY'14 WHA/WHMP Update -- \$140,000