

Alaska Airport Needs Directory

**Department Of Transportation
&
Public Facilities**

As of: February 28, 2019

Region: All



This report provides only a portion of the income and expense data related to rural airport operations for DOT&PF. It does not reflect funds received from FAA capital or maintenance grants, Air Carrier Compliance program, or M&O badge or ramp fees. It does not reflect expenses for FAA and State share for capital and maintenance project grants, managerial expenses by Commissioner, Deputy Commissioner, Statewide Aviation staff, or administrative costs incurred by Division of Administrative Services (Budget, Finance, IT, appeals functions), Statewide Aviation Leasing, ROW, Planning, Design and Engineering Services or Construction. It does not reflect expenses for the rural airport Facilities component building costs such as repairs, electricity and heating fuel, or other utilities for buildings. It does include Maintenance and Operations costs such as personnel, utilities and fuel for equipment, runway lights, and some buildings such as heated storage.

ADAK (ADK)

Runways: 05/23 - 7,790

Surface: ASPH-F

Lighting: HIGH

Classification: Local Non-NPIAS

CY16 Enplanements: 2,151

Borough: Aleutians West Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$7,507.06

USPS Hub: No

School Facility: K-12

FY18 Ops Cost: \$61,849.48

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/12/2016

Airfield Manager: INNOCENT DUSHKIN, 907-592-8026

Hours of Operation:

ALL/ALL/0800-1600

Last Major Improvement: Unobligated- state funded project closing crosswind in 2014

NEEDS:

Construct Passenger Shelter

Taxiway A

Construct Tie-Downs

Test Adak Need for Training

Construct Toilet Facilities

Traffic control gates

Extend RSA on runway

Upgrade Vehicle Gates with Electronic Swipe Capability

Fence Repairs

Improve Drainage

Installation of FAA Weather Cameras

Loader

Major Pavement Rehabilitation on Main Runway Needed

New radios (9) for SRE equipment

Pavement Repairs

Plow with Attachments

Purchase Badging Computer, Software Upgrade and Printer

Removal of Old Lighting on Closed Surfaces

Repair Mower

Repair RW 36 Water Pump

Replace ARFF Bunker Gear

Skid Steer with Attachments

SRE Building Upgrades & Repairs

SREB Repairs

Sweeper

AKHIOK (AKK)

Runways: 04/22 - 3,120

Surface: GRAVEL-G

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 460

Borough: Kodiak Island Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility:

FY18 Ops Cost: \$22,602.18

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/10/2016

Airfield Manager: BRUCE MCNEIL, 907-487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0002-002-1994

NEEDS:

Acquire 21 acres of property to control expanded airspace

REIL, and navigation lighting aids

Brush Cutting

Relocate AWSS

Construct 180' Runway Extension

Relocate part of access road

Construct and relocate new apron to provide offsets for non-precision approaches

Relocate taxiway and apron

Construct New Segmented Circle and Wind Cone

Remove OFA/OFZ penetrations

Construct Passenger Shelter

Replace Cones

Construct supplemental wind cone

Replace existing apron

Construct taxiway B

Replace Segmented Circle

Construct Toilet Facilities

Replace/Relocate new 2-bay SREB

Demolish existing SREB

Runway, taxiway, and apron pavement rehabilitation

Grade Runway 4/22

SREB Cleanup

Grade safety Areas

Improve runway to accommodate additional use

Install MIRL Runway Lighting

Install Perimeter Fence

Install taxiway edge lighting

Install VGSI (PAPI)

Loader

Lower access road profile to mitigate airspace obstructions

Obliterate part of access road

Rehabilitate/resurface access road

AKIACHAK (Z13)

Runways: 01/19 - 3,300

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: K-12

FY18 Ops Cost: \$30,525.92

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/26/2017

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0461-002-2010

NEEDS:

Airport Master Plan

Apply dust palliative

Construct crosswind runway

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Dust Control

Extend 3,300' runway to 6,000'

Install AWOS (Various)

Install Papi and Reil

Install VGS! (PAPI)

Install Weather Cameras

Stockpile for Repairing Gravel Runway

AKIAK (AKI)

Runways: 03/21 - 3,200

Surface: GRVL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 3,570

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: K-12

FY18 Ops Cost: \$28,665.14

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/20/2014

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0004-002-2003

NEEDS:

Building organization and cleaning

Construct new SREB

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust Control

Grader

Install ASOS or AWOS

Install VGSI (PAPI)

Loader

MIRL Inoperable

Obstruction Removal

provide a portable emergency eye wash station

Replace all cones and unlit markers

replace fuel tank signage and install security lighting

Runway, taxiway, and apron pavement rehabilitation

Test Akiak Need for Training

Tree obstruction removal

Update ALP

Vandalism Issues

AKUTAN (7AK)

Runways: 09/27 - 4,500

Surface: ASPH

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 1,644

Borough: Aleutians East Borough

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: K-12

FY18 Ops Cost: \$836,325.10

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/24/2015

Airfield Manager: DALE RUCKMAN, (907) 581-1786

Hours of Operation:

ALL/ALL/0700-1900

Last Major Improvement: Construct New Airport Phase 7
3-02-0005-007-2015

NEEDS:

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install PAPI or VASI

Install VGSI (PAPI)

ALAKANUK (AUK)

Runways: 16/34 - 4,000

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 5,136

Borough: Kusilvak Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$135,884.77

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JOHN WILSON, (907) 625-1025

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport Phase 4
3-02-0440-004-2011

NEEDS:

Airport Signage

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install ASOS or AWOS

Install VGSI (PAPI)

Loader

Loader

ALEKNAGIK /NEW (5A8)

Runways: 15/33 - 2,030

Surface: GRAVEL-G

Lighting:

Classification: Community Off-Road

No Enplanements: 0

Borough: Dillingham Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: K-8

FY18 Ops Cost: \$8,022.26

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/16/2015

Airfield Manager: NORMAN HEYANO, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: No capital-Rehab RW 15/33 (2010)

NEEDS:

Aleknagik Airport Improvements

Brush Cutting

Construct a new float plane dock

Construct New SREB

Construct Passenger Shelter

Construct Runway Safety Areas

Construct Tie-Downs

Construct Toilet Facilities

Correct Non-Standard Conditions

Extend current runway to 3,000'

Grader

Improve NSTD Markings on Runway 15/33

Improve Windsock Visibility

Install ASOS or AWOS

Install MIRL Runway Lighting

Install VGSI (PAPI)

Remove Trees

Replace Primary Wind Cone and Segmented Circle

Resurface Runway

Wind cone for seaplane base

ALLAKAKET (6A8)

Runways: 05/23 - 4,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$4,415.31

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$89,997.33

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/24/2014

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Expand Apron 3-02-0009-006-2009

NEEDS:

Apply Dust Palliative

Replace Fuel Storage Tank and Enhance Security Measures

Cleanup and Organization of Equipment, Parts, and Supplies

SRE Building Replacement

Compactor

SRE Repairs

Construct Passenger Shelter

SREB upgrade or replace

Construct Tie-Downs

WX Reporting Needed

Construct Toilet Facilities

Construct Ultimate Apron

Dozer

Erosion Repair on Ramp/Taxiway Throat

FAA Survey Clear Obstructions & Mark Property Boundary

Fuel Farm Upgrades

Grader

Install AWOS

Install external speaker on equipment

Install Lighted Supplemental Wind Cone

Install Protective Bollards (SREB)

Install RW 5/23 PAPI and REIL

Install VGS1 (PAPI)

Realign Primary Wind Cone

Relocate Segmented Circle

Repair Threshold Markers

AMBLER (AFM)

Runways: 01/19 - 4,000
10/28 - 2,410

Surface: GRVL-DIRT-F
GRVL-DIRT-F

Lighting: MED
MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$1,711.94

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$154,255.31

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/07/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: RW 9/27 & 18/36 Rehabilitation
3-02-0354-006-2016

NEEDS:

Ambler Access Road Improvements

Ambler Airport Improvements

Ambler Airport Improvements Stage 2

Ambler Airport Improvements Stage 3

Ambler SRE Building Replacement

Construct 996' Runway Extension

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Grader

ANGOON (AGN)

Runways: NW/SE - 10,000

Surface: WATER

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 2,466

Borough: Hoonah-Angoon Census Area

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$625.00

USPS Hub: Yes

School Facility: K-12

FY18 Ops Cost: \$2,932.80

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: SCOTT GRAY, (907) 465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: Acquire Land for Dev, Access Road
3-02-0018-001-1987

NEEDS:

Construct Land Airport

ANIAC (ANI)

Runways: 05W/23W - 3,000
11/29 - 6,001

Surface: WATER
ASP-H

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 14,675

Borough: Bethel Census Area

Air Carrier Hub: Yes

Medical Facility: Yes

FY18 Revenue: \$60,964.74

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$466,410.29

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/13/2017

Airfield Manager: RICHARD CILETTI, 907-675-4345

Hours of Operation:

ALL/MON-SAT/0800-1600

Last Major Improvement: Construct RW 10/28 & Rehab Apron
3-02-0019-011-2018

NEEDS:

Abandoned Drums	Improve/Extend RSA Runway 10/28
Airport ramp repairs	Install Fencing
Broom Runway Towed	Install navaids (PAPIs, REILs, localizer)
Building Timers	Install Perimeter Fence
Conduct erosion and drainage study	Light Obstructions
Construct Crosswind runway	Loader
Construct floatplane ramp	Move runway
Construct full parallel taxiway	New sand storage building
Construct Full Parallel Taxiway	Pavement Markings
Construct helipad	Placards- Crowley Fuels
Construct partial parallel taxiway	Provide erosion protection
Correct pavement markings on runway, taxiways, & apron	Ramp light rehab
Crack Seal	Reconfigure and expand apron and develop new lease lots
Crack sealing on runway, taxiways, & apron	Rehab/Overlay and Strengthen Pavement RW 10/28
Culvert replacement	Rehabilitate apron and taxiway pavement (391,241 sq. ft.)
directional plow	Relocate approach lighting system
Extend fencing and repair gates	Relocate service road
External Directional speakers for equipment	Remove dike by clinic and realign road
Fix leaking SREB roof	Remove Junk and Hazardous Materials
Fuel Tank Bollards	Remove obstacles and penetrations
Grader	Remove obstructions to Part 77 surfaces, ROFA and RSAs

ANIAK (ANI)

Remove power poles and install underground power lines

Remove trooper housing and FAA buildings

Replace sign panels

Replace wind cone lights with LED

Safety Equipment and Fencing

Security Enhancements

Segmented Circle rehab

Snow Blower

Snow Blower

Snow Plow

SREB needs door rehab to weatherize

Stand by generator

ANVIK (ANV)

Runways: 17/35 - 4,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 1,360

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,922.63

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$87,339.38

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: ERIK WEINGARTH, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Extend & Rehab RW 17/35, Improve Access Road, Expand Apron, Construct RSA
3-02-0021-004-2004

NEEDS:

Aeronautical Survey

Apply Dust Palliative

clean culverts

Clear Vegetation Around Windcone

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install Edge Light Can Markers

Install Runway PAPI and REIL, and Aeronautical Survey

Install ULSD Tank

Loader

Renovate SRE Building

Replace SRE Building

Re-Surface Runway, Apron, and Taxiway, Improve Drainage and Install New Lighting

Tree Removal

U-Blade Loader

ATKA (AKA)

Runways: 16/34 - 4,500

Surface: ASPH-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Aleutians West Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: K-12

FY18 Ops Cost: \$44,885.44

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/20/2016

Airfield Manager: DALE RUCKMAN, 907-581-1786

Hours of Operation:
UNATNDD

Last Major Improvement: Extend & Rehab RW 15/33, Construct Apron & SREB 3-02-0394-005-2008

NEEDS:

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install REILs

Install VGSI (PAPI)

Installation of FAA Weather Cameras

Lengthen RW to 5,000'

Maintain crack seal

Maintain pavement markings (M&O SPM)

Repair and Add Pavement Markings on Airport

Sand seal taxiway and apron

Seal coat airport pavement

SREB Maintenance and Timer Installation

Visual Aid Repair

ATMAUTLUAK (4A2)

Runways: 15/33 - 3,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$16,439.82

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/08/2016

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Extend & Rehab RW 15/33, Construct SREB
3-02-0379-002-2002

NEEDS:

Airport Lighting Repair

Apply dust palliative

Construct a 1-bay Heated SREB with Floor

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Grader with Attachments

Install AWOS System

Install Weather Cameras

Minor Gravel Resurfacing

BARANOF WARM SPRINGS FLOAT AND SEAPLANE FLOAT (BNF)

Runways: E/W - 10,000

Surface: WATER-E

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: City and Borough of Sitka

Air Carrier Hub: No

Medical Facility: No

No Revenue: \$0.00

USPS Hub: No

School Facility: None

No Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: HARBORMASTER, (907) 747-3439

Hours of Operation:
UNATNDD

Last Major Improvement:

NEEDS:

Airport Ownership Change

BASIN CREEK (Z47)

Runways: 16/34 - 2,000

Surface: GRVL-DIRT-G

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$17,592.52

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/12/2017

Airfield Manager: RON ENGSTROM, 907-443-2586

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Rehab Windsock

Straighten Cones on Runway

Wildlife Mitigation

BEAVER (WBQ)

Runways: 05/23 - 3,934

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 989

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$1,650.75

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$90,357.27

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Install RW Lighting
3-02-0028-001-1988

NEEDS:

Apply Dust Palliative

Brush Cutter - Fecon Skidsteer

Brush cutting

Construct 66' Runway Extension

Construct Passenger Shelter

Construct SREB

Construct Tie-Downs

Construct Toilet Facilities

Establish contingency shelter (connex shack)

Extend runway and RSA

Grader

Grading and drainage improvements

Hazmat removal

Install VGSi (PAPI)

Lighted Supplemental Wind Cone

Loader

New fuel storage tank (3000+ gal), construct fence to secure and add lighting

Obtain wind data (crosswind runway needed?)

Pull Behind Compactor

Rehabilitate segmented circle

Replace beacon access ladder and secure

Replace cones/markers and replace nonfrangible bases on threshold panels

Replace Windsock Pole and Lighting

Resurface runway, apron and taxiway and create berm to block the two roads that cross the runway

Snow Blower

Survey, Clear Obstructions, and Mark Property Boundary

Update ALP

WX Reporting Needed

BETHEL (BET)

Runways: 01L/19R - 6,400
01R/19L - 4,000
12/30 - 1,858

Surface: ASPH-F
ASPH-G
ASPH-GRVL-G

Lighting: HIGH
HIGH
MED

Classification: Regional

CY16 Enplanements: 156,228

Borough: Bethel Census Area

Air Carrier Hub: Yes

Medical Facility: Yes

FY18 Revenue: \$383,393.45

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$1,534,704.43

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: LJ DAVIS, 907-543-2495

Hours of Operation:

OCT-APR/MON-FRI/0500-2200

OCT-APR/SAT-SUN/0800-2200

MAY-SEP/MON-FRI/0630-2200

MAY-SEP/SAT-SUN/0800-2200

Last Major Improvement: Access Control Project
3-02-0029-024-2017

NEEDS:

Acquire & construct alternate access to Kasayuli Subdivision

Construct a new 10,000' runway to accommodate 747 type aircraft

Acquire 54 acres

acquire 722 acres

Construct ARFF building

Acquire Land

Construct cargo apron and widen access road

Acquire land for w/in 2,000' of VORTAC and elsewhere for land use compatibility

Construct GA Apron and Support Area with Taxiway

Additional Landside Security Lighting

Construct new air cargo apron

Airport Gate Card Reader Installation

Construct new gravel runway (02S/20S)

Airport Gate Replacement

Construct Service Roads

Apron/Taxiway Preventative Maintenance 1,794,600 sq. ft.

Construct Tie-Downs

ARFF SCBA compressor

Construct Wind Cone on East End of Runway

ARFF Truck

Crack Seal

ARFF Truck

Crack Seal

ARFF Vehicle

Deicer Truck

Badging computer, software upgrade and printers

Design and implement the appropriate stabilization solutions

BLADE BELLY

Develop new lease lots

BROOM RUNWAY TOWED

Dozer

Build 4000' Crosswind RW with Lighting and NAVAIDs and RSA

Dozer

Commercial apron rehab

Dump Truck

Conduct a geotechnical analysis

Erosion Control and Stability Control

Construct 4,600' x 140' RSA

Expand and Strengthen N Air Taxi Apron pavement for heavier aircraft (Dash 8)

Expand N Air Taxi Apron to the south (to Lot 1B)

BETHEL (BET)

Extend crosswind runway	pavement and 833,760 sq. ft. apron/taxiway pavement
Extend RSA runway 12	Reconfigure vehicle parking and access road for main terminal and N Air Taxi aprons
Extend Taxiway M to Runway 1L/19R	Rehabilitate apron and taxiway pavement (1,263,260 sq. ft.)
Fencing	Rehabilitate RW 1L19R
Friction Measuring Trailer	Relocate security fencing on southern end of RPZ for runway 02
Grader	Remove Part 77 obstructions
Grader	Replace ARFF bunker gear
Grader	Reshape and compact RSA beyond each threshold for 1000'
HANDICAP PASS LOADER	Road Repair
Install MIRL east of the primary runway 18/36	Runway Preventative Maintenance
Install PAPIs and REILs Runway 12/30	Runway stabilization project
Install Perimeter Fence	Safety Area Grading
Install/replace security fencing around expanded northwest apron	Sander
Loader	Shoulders Rwy 1L/19R
Loader	Sinking Areas 1R/19L
Loader	Snow Blower
Loader	Snow Blower
Loader	Snow Blower
Loader with Attachments	Snow Plow
Master plan update	South GA Apron Reconstruction
Mitigate wildlife problem in pond just south of Runway 1R threshold with suspended cable grid	Stabilize safety areas
New Pull Behind Broom	TRLR TILT
Oshkosh Carrier with Broom	Truck Mounted Deicing System and Storage Tank
Parallel runway and other improvements stg. 6 ROW	Truck Plow Airport
Parallel runway lighting and ROW	Twy C and Tower Road Pavement Repairs
Pavement Markings	Utility Wagon
Pavement Markings	Vegetation Control
Perimeter fencing repairs/replacement	West Heavy Apron Expansion
Preventative maintenance on 300,000 sq. ft. runway	

BETTLES (BTT)

Runways: 02/20 - 5,190

Surface: GRVL-G

Lighting: MED

Classification: Local NPIAS Lower

CY16 Enplanements: 3,620

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$45,709.51

USPS Hub: Yes

School Facility: None

FY18 Ops Cost: \$327,654.71

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/24/2014

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SPB 3-02-0030-004-2001

NEEDS:

Airport Paving

Apply Dust Palliative

Bettles Airport Lighting

Bettles Lighting & Surface Repair

Brush Cutter

Clear Vegetation Around Airport

Loader Mounted Snow Blower

Miscellaneous Building Repairs

Purchase and install exterior speakers on equipment

Re-Compact Runway

Re-Grade Apron

Regrade, shape, and compact runway

Remove and replace threshold signs

Repair airfield lighting

Repair/replace and realign marker cones

Replace Overhead Doors (SREB)

Replace Windsock Pole and Lighting

Resurface Runway, Apron, and Taxiway, Upgrade Lighting System, Remove Obstructions, and Complete Grading and Drainage Improvements

Update ALP

BIG LAKE (BGQ)

Runways: 07/25 - 2,450

Surface: GRAVEL-G

Lighting: MED

Classification: Local NPIAS High

No Enplanements: 0

Borough: Matanuska-Susitna Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$54,362.46

USPS Hub: No

School Facility: K-12

FY18 Ops Cost: \$46,090.38

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 08/02/2016

Airfield Manager: STEVE BANSE, 907-745-2159

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Approach Clearing

Conduct Master Plan

Construct a GA apron with gravel surface adjacent to airport

Construct Gate/Barricade at Hughes Homestead Road

Construct Perimeter Fence

Construct SREB

Construct taxiways between apron and runway

Extend lease lot access road

Extend taxiway to the east

Grading Project

Increase number of lease lots

Loader

New Design Survey datums

Obstruction Removal

Regrade Perimeter Access Road

Remove Parking Signs along Runway

Replace Lighting System

Replace Missing Threshold Marker

Shift R/W to east and south

BIRCH CREEK (Z91)

Runways: 16/34 - 4,000

Surface: GRAVEL-G

Lighting: MED

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$500.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$106,256.63

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate TW & RW 16/34
3-02-0033-003-2003

NEEDS:

Brush cutter

Resurface runway, taxiway, apron

Compactor

Survey, Clear Obstructions, and Mark Property Boundary

Construct SREB

Update ALP

Contingency Shelter

Weather reporting system

Dozer

Dust Pallative

expand apron

Fence and secure fuel tank

Grader

Install New Lighting

Installation of FAA Weather Cameras

Lighted Supplemental Wind Cone

Loader

PAPI

Purchase compactor attachment

Rehabilitate current SREB

Remove hazmat and trash

Remove old threshold panels and approach indicators

Replace cones and damaged lights

Replace Fuel Storage Tank and Enhance Security Measures

Replace Windsock Pole and Lighting

BIRCHWOOD (BCV)

Runways: 02L/20R - 1,800
02R/20L - 1,800

Surface: GRVL-F
GRVL-F

Lighting: MED

Classification: Local NPIAS High

No Enplanements: 0

Borough: Municipality of Anchorage

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$243,716.10

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$99,907.24

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 06/15/2015

Airfield Manager: TOM GRMAN, 907-338-1432

Hours of Operation:
UNATNDD

Last Major Improvement: Reconstruct TW B, C, D, E, G, & Apron, Rehab
RW 02R/20L 3-02-0034-007-2018

NEEDS:

Acquire property for RPZs and land use compatibility

Add electric power to transient areas

Add paved intersection taxiway on South side of airport.

Additional East Side Lease Lot Development

Additional GA local and transient aircraft parking on ramp

Airport Pavement and Lighting Repairs

Airport Perimeter Road Improvements

Apply Dust Palliative

Brush Cutting

Change Main Runway Design Markings

Change TWY A

Construct New Connecting Taxiways (Taxiways F and I)

Construct new gravel runway 02S/20S and new ultralight runway

Crack Seal

Develop additional southeast Apron lease lots

Expand East Apron

Expand NE and SW Aprons

Expand northwest apron, rehabilitate apron and taxiway

Fix hump/bump/ruts in Tundra Tire/Ski strip

Grade and Relevel CAP Leasing Area

Master Plan Update

Minor Gravel Resurfacing

Northeast Apron Pavement Rehabilitation

Obstruction removal

Pavement Markings

Purchase Property for Compatible Land Use

Relocate security fencing on southern end of RPZ for runway 02

Relocate segmented circle and windsock to center of field

Remove and replace secondary wind cone

RPZ Fencing

Runway/Taxiway Pavement Rehab and RSA

Security Fence

Snow Removal Equipment Building

Widen taxiways at runway intersections

BOB BAKER MEMORIAL (IAN)

Runways: 06/24 - 3,400

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 5,700

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,818.43

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$86,790.35

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/06/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Reconstruct & Extend RW 6/24, Reconstruct Lighting, Rehab Apron
3-02-0146-004-2018

NEEDS:

Acquire land

Apply Dust Palliative

Brush Cutting

Construct 600' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Drainage project to prevent uphill water from saturating the runway embankment

Expand apron

Fuel Tank Upgrade

Improve aircraft parking setback

Install RCO

Lease lots

Rehabilitate surfaces

remove trees

Replace segmented circle and wind cone tower

Replace the lighting system

Runway extended 600'

SREB repairs

BOUNDARY (BYA)

Runways: 05/23 - 2,325

Surface: GRVL-DIRT-G

Lighting:

Classification: Local NPIAS Lower

CY15 Enplanements: 2

Borough: Southeast Fairbanks Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$311.17

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 10/05/2016

Airfield Manager: DENNIS BISHOP, 907-883-5128

Hours of Operation:
UNATNDD

Last Major Improvement: Acquire Land for Dev, Construct TW & Extend RW
5/23
3-02-0036-001-1989

NEEDS:

Apply Dust Palliative

Boundary Airport Improvements

Replace airport signage

Resurface runway, apron, and taxiway

BREVIG MISSION (KTS)

Runways: 05/23 - 2,110
12/30 - 2,990

Surface: GRVL-G
GRVL-G

Lighting: MED
MED

Classification: Community Off-Road

CY16 Enplanements: 3,522

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$80,344.30

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/08/2015

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: Rehab RW 4/22, Construct TW, Install Lighting
3-02-0294-002-1997

NEEDS:

Acquire Land	replace missing carsoniote style light markers and or install new reflective bands.
Apply Dust Palliative	Replace wind cone tower, lighting and segmented circle
Brevig Mission Airport Improvements	Resurface runway, apron, and taxiway
Brevig Mission Lighting & Resurfacing	Update ALP
Brevig Mission SRE Building Replacement	Upgrade airport lighting
Building Improvements	
Construct 1,890' Runway Extension	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Extend Apron	
Extend Runway 11/29	
Extend Runway 4/22	
Fuel tank repairs	
Grader and Loader	
Improve existing access road	
Improve GPS Approach	
Install aircraft tie-downs	
Obliterate existing landfill	
Obliterate road	
Repair Shoulders, Light Cans, and Lighting System	

BUCKLAND (BVK)

Runways: 11/29 - 3,200

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$120,169.95

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/06/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0399-003-2017

NEEDS:

Apply Dust Palliative

Unlighted Wind Cone

Buckland Airport Improvements

Update ALP

Buckland Airport Improvements

Upgrade airport lighting

Buckland SRE Building Replacement

Construct 800' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Expand the apron

Extend Runway 11/29 to 3,400'

Fuel tank safety and signage

Grader

install additional fuel tank bollards

PAPI

Purchase New Fire Extinguishers and Portable Emergency
Eye Wash Station

Reestablish Runway Crown and Compact Surface

Repaint SREB exterior

Replace Primary Wind Cone

Resurface existing runway and taxiway

Ultimate RPZ

CENTRAL (CEM)

Runways: 08/26 - 2,782

Surface: GRVL-DIRT-P

Lighting: MED

Classification: Community On-Road

CY16 Enplanements: 150

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility:

FY18 Ops Cost: \$29,313.26

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, 907-451-5276

Hours of Operation:
UNATNDD

Last Major Improvement: Improve Access Road, Construct RW 7/25, Install Lighting, Acquire Land
3-02-0045-001-1989

NEEDS:

Apply Dust Palliative

Central Airport Improvements

Central SRE Building Replacement

Construct 618' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install VGSI (PAPI)

Resurface runway, apron, and taxiway

Update ALP

Upgrade airport lighting

CHALKYITSIK (CIK)

Runways: 03/21 - 4,000

Surface: GRVL-DIRT-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 791

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$90,316.20

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/26/2017

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 3/21, Install Lighting
3-02-0046-003-1993

NEEDS:

Apply Dust Palliative

Update ALP

Brush & Tree Clearing

Upgrade / Improve SRE building

Brush Cutter

Visual Aid Replacement

Chalkyitsik Airport Improvements

WX Reporting Needed

Chalkyitsik SRE Building Replacement

Compactor

Connex Storage Unit - Fire extinguisher

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Correct drainage problems at the end of the runway

Grader

Install VGS1 (PAPI)

Loader

Rehabilitate Airport Lighting System

Relocate the apron and access road

Remove or Improve the fuel tanks on the apron

Replace EEB

Replace Windsock Pole and Lighting

Resurface Runway, Apron, & Taxiway

Survey, Clear Obstructions, and Mark Property Boundary

CHANDALAR LAKE (WCR)

Runways: 03/21 - 3,000

Surface: GRVL-DIRT-G

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 14

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,244.73

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: JEFF RUSSELL, 907-452-2207

Hours of Operation:
UNATNDD

Last Major Improvement: Improve Access Road, Extend RW 3/21,
Construct TW & Apron, Acquire Land for
Approaches
3-02-0047-001-1994

NEEDS:

Update ALP

CHANDALAR SHELF (5CD)

Runways: 01/19 - 2,529

Surface: GRAVEL-G

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$732.93

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$3,797.29

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: JEFF RUSSELL, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0431-001-2004

NEEDS:

ALP Update

Chandalar Camp Runway Rehabilitation

Develop lease lots

Resurface all operational surfaces

Update ALP

Upgrade signage/markings

CHEFORNAK (CFK)

Runways: 16/34 - 3,230

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$31,447.04

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/08/2016

Airfield Manager: LJ DAVIS, 907-543-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0442-002-2010

NEEDS:

Construct 1,500' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust Palliative & RSA Grading

Grader

Install VGS1 (PAPI)

Loader

SREB Safety Updates

Wildlife Hazards

CHENEGA BAY (C05)

Runways: 16/34 - 3,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: K-12

FY18 Ops Cost: \$98,757.35

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/28/2016

Airfield Manager: SEAN MONTGOMERY/CARL HIGH, (907) 262-2199

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, Rehab RW 15/33, Apron, and
Access Road
3-02-0419-004-2004

NEEDS:

Brush Cutting

Building cleanup and fire extinguishers

Cone and marker repair / replacement

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Expand RSA to 150' x 3,900'

Extend runway to 3,300'

Improve GPS Approach

Install ASOS or AWOS

Install lighted wind cone at rwy 16 end

Install REILS

Install VGS (PAPI)

Level out the Runway

Obstruction Removal

Pave Runway

Repair Airport Signs and Replace Secondary Windsock Pole

CHEVAK (VAK)

Runways: 02/20 - 3,220

Surface: GRVL-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 8,772

Borough: Kusilvak Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$45,446.64

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/08/2016

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0468-002-2007

NEEDS:

Apply dust palliative

Update ALP

Beacon

Conduct Master Plan

Construct 780' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust Control

Erosion study

Improve airport access

Install Perimeter Fence

Install Signage

Lease-lot development

Lighting Repairs

Loader

Minor Gravel Resurfacing

Obstacles/penetrations mitigated

Resurface runway, taxiways and apron

ROW Acquisition

Snow Blower

SREB Safety Repairs

CHICKEN (CKX)

Runways: 13/31 - 2,500

Surface: GRVL-DIRT-G

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 20

Borough: Southeast Fairbanks Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$250.00

USPS Hub: Yes

School Facility: None

FY18 Ops Cost: \$22,372.65

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 10/05/2016

Airfield Manager: DENNIS BISHOP, 907-883-5128

Hours of Operation:
UNATNDD

Last Major Improvement: Improve ARFF, Construct RW 13/31 & Apron,
Acquire Land
3-02-0053-001-1987

NEEDS:

Apply Dust Palliative

Brush Cutting

Chicken Airport Improvements

Fuel Tank Upgrade

Resurface Runway, Apron, and Taxiway

Update ALP

CHIGNIK (AJC)

Runways: 02/20 - 2,600

Surface: GRAVEL-G

Lighting:

Classification: Community Off-Road

No Enplanements: 0

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$3,981.64

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$25,759.40

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Rehab TW, Extend RW 2/20
3-02-0330-001-1992

NEEDS:

Construct 700' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Culvert replacement

Expand SREB to include an additional bay, heat, and
insulation

Grader and Loader

Install Concrete Pad at SREB entrance

Install Runway MIRL Lighting

Install VGSI (PAPI)

Resurface runway, taxiway, and apron with 9" of new gravel

CHIGNIK LAGOON (KCL)

Runways: 04/22 - 2,200

Surface: GRVL-DIRT-F

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 553

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$24,250.70

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Add surface course aggregate to the runway. Currently at 3"

Apply Dust Palliative

Construct 1,490' Runway Extension

Construct 10' of gravel access road

Construct Passenger Shelter

Construct SREB

Construct Tie-Downs

Construct Toilet Facilities

Determine potential runway realignments

Install MIRL Runway Lighting

Install VGSI (PAPI)

Repair and replace windsock poles and markers

Replace windsock, poles and markers

Resurface existing gravel runway

Snow removal equipment

CHIGNIK LAKE (A79)

Runways: 08/26 - 2,800

Surface: GRAVEL-P

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 5

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$743.56

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$15,880.20

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Rehab & Extend RW 8/26, Rehab TW & Apron
3-02-0331-001-1985

NEEDS:

Construct 500' Runway Extension

Construct a replacement SREB

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Expand RSAs and expand apron

Grader and SRE

Identify future pad for weather reporting system

Install MIRL Runway Lighting

Install REILs

Install VGSI (PAPI)

Lengthen/widen runway to community class standards

Remove OFA penetrations, brush clearing

Resurface runway

RPZ land acquisition

Update ALP

CHISANA (CZN)

Runways: 12/30 - 3,000

Surface: TURF-GRVL-P

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 97

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Brushing, tree clearing and stockpiling surfacing material for future maintenance.

Chisana Airport Improvements

Improve airport for all-season operations, including runway surface repairs

Tie-down replacement

Update ALP

CHISTOCHINA (CZO)

Runways: 02/20 - 2,060

Surface: TURF-GRVL-F

Lighting:

Classification: Community On-Road

No Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Apply Dust Palliative

Chistochina Airport Relocation

Construct a new runway, apron, taxiway, aviation support area

Construct new airport access road

Construct Passenger Shelter

Construct Passenger Shelter

Construct SREB

Construct Tie-Downs

Construct Toilet Facilities

Construct Toilet Facilities

Develop ALP

Develop ALP

Extend Runway 1,340'

Install MIRLs

Install PAPI or VASI

MIRL Runway Lighting

PAPI or VASI

Runway Extension

Tie-down replacement

CHITINA (CXC)

Runways: 13/31 - 2,850

Surface: GRVL-DIRT-G

Lighting:

Classification: Local NPIAS Lower

CY14 Enplanements: 11

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,921.05

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$33,308.82

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0059-002-1999

NEEDS:

Apply Dust Palliative

Chitina Airport Paving

Dust Palliative

Fuel Tank Upgrades

Loader

Parking lot expansion and Apron expansion

Part 77 tree removal and brush cutting

Place frangible mounted aircraft movement sign near
beginning of Twy

Place obstruction light on Maintenance shop buildings

Raise 2 panels in segmented circle

Replace faded cones and damaged threshold cone

Replace wind sock

Resurface runway, taxiway, and apron

SRE Building Upgrades

Update ALP

CHUATHBALUK (9A3)

Runways: 09/27 - 3,401

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$48,145.29

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/14/2017

Airfield Manager: RICHARD CILETTI, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB & New Airport
3-02-0460-001-2002

NEEDS:

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Grader

Grader

Gravel Resurfacing

Gravel Resurfacing

Gravel resurfacing

Install ASOS or AWOS

Rehabilitate access road

Replace Airport Lighting

Shoulder erosion

Taxiway Repair

CIRCLE CITY (CRC)

Runways: 15/33 - 2,979

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community On-Road

No Enplanements: 0

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK-12

FY18 Ops Cost: \$56,275.71

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Construct RW 14/32 & Apron, Install RW Lighting,
Improve Access Road
3-02-0407-002-1986

NEEDS:

Circle Airport Taxiway and Apron Rehabilitation

Construct 421' Runway Extension

Construct Circle SRE Building

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Grader

Install ASOS or AWOS

Install VGSI (PAPI)

Lighted Supplemental Wind Cone

Loader

SREB Building

Survey, Clear Obstructions, and Mark Property Boundary

Update ALP

CIRCLE HOT SPRINGS (CHP)

Runways: 09/27 - 3,669

Surface: GRAVEL-G

Lighting:

Classification: Local NPIAS Lower

CY14 Enplanements: 15

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$1,160.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$2,096.86

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, 907-451-5276

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

SRE Building Replacement

Taxiway and Apron Rehabilitation

CLARK BAY (HYL)

Runways: E/W - 10,000

Surface: WATER

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 1,867

Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$199.18

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 11/14/2016

Airfield Manager: TIM LACOUR, 907-755-2229

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SPB 3-02-0470-001-2006

NEEDS:

CLARKS POINT (CLP)

Runways: 18/36 - 3,200

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 862

Borough: Dillingham Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: K-12

FY18 Ops Cost: \$28,338.26

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/15/2015

Airfield Manager: NORMAN HEYANO, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0062-003-2004

NEEDS:

Acquire Land

Brush Cutting

Clark's Point Runway Extension

Construct access road

Construct apron and Lease lots

Construct Passenger Shelter

Construct SREB

Construct Tie-Downs

Construct Toilet Facilities

Construt Maintenance Road Access to Segmented Circle

Fueling System upgrades

Install MIRL Runway Lighting

Install VGS1 (PAPI)

Minor Gravel Resurfacing

Remove part 77 obstructions

Repair/replace runway lights.

Replace cones and markers

Reshaping embankment

Resurfacing gravel runway

Update ALP

Widen runway by 10'

CLEAR (Z84)

Runways: 01/19 - 3,997

Surface: ASPH-G

Lighting: MED

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Denali Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,140.40

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$16,019.06

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 1/19, Construct Apron, Improve
Access Road, Install RW Lighting, Acquire Land
3-02-0420-001-1993

NEEDS:

Lighted Supplemental Wind Cone

PAPI and WX Reporting Needed

SREB building

Survey, Clear Obstructions, and Mark Property Boundary

Update ALP

COLD BAY (CDB)

Runways: 08/26 - 4,900
15/33 - 10,179

Surface: ASPH-G
ASPH-G

Lighting: HIGH
HIGH

Classification: Regional

CY16 Enplanements: 10,941

Borough: Aleutians East Borough

Air Carrier Hub: Yes

Medical Facility: No

FY18 Revenue: \$108,627.49

USPS Hub: Yes

School Facility: K-12

FY18 Ops Cost: \$956,317.16

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 08/11/2014

Airfield Manager: HAROLD KREMER, 907-532-5000

Hours of Operation:

MAY-SEP/ALL/0700-1800

OCT-APR/ALL/0530-1800

Last Major Improvement: Expand ARFF Building
3-02-0065-012-2016

NEEDS:

Add 40' of crosswind runway pavement, 300' of crosswind RSA

Loader

Airport Fence and Gate Repairs

Maintain Pavement Markings

ARFF Building Expansion

Minivan

ARFF Building Renovations

Minor Runway Pavement Repair

ARFF bunker gear

New AEB Apron and Taxiway

ARFF Vehicle

Old ARFF Building Removal

Badging computer, software upgrade and printer

Overlay South Apron and Resurface ARFF Apron

Brush Cutting

Paint and Exterior Repairs on ARFF Building

Construct Full Parallel Taxiway

Paint and exterior repairs on sand storage building

Construct Stand-by Generator Building

Pavement repairs

Construct Tie-Downs

Pavement Repairs (Runway, Taxiway, and Ramp)

Construct Toilet Facilities

Provide additional SRE storage as needed

Crosswind Runway Reconfiguration

Realign and Pave St. Louis Road

Culvert replacements (roadways)

Re-Grade and Compact Safety Areas

Dump Truck

Relocate Segmented Circle

Expand Terminal Apron

Repair Safety Area Ditches

Extend runway 8/26 and reconfigure CW runway

Replace lighting on runway 15/33 and taxiway C

Fence Repairs

Replace World War II era culverts at Trout Creek

Install necessary storm drainage, signage

Runway 15/33 Culvert Replacement

Install Perimeter Fence

Runway 15/33 Safety Area Expansion / MALSR Relocation

Install REIL & PAPI on Runway 8/26

Runway lighting electrical repairs

COLD BAY (CDB)

Sand seal north and south apron areas to include Runway 15
elephant ear turn around and the Runway 8/26 turn around

Sand Storage Building Repairs

COLDFOOT (CXF)

Runways: 02/20 - 4,021

Surface: GRAVEL-G

Lighting: MED

Classification: Local NPIAS Lower

CY16 Enplanements: 8,242

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$21,202.21

USPS Hub: No

School Facility:

FY18 Ops Cost: \$230,234.33

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: JEFF RUSSELL, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron, RW 1/19, TW, & RW Lighting
3-02-0425-002-2015

NEEDS:

Coldfoot Airport Improvements

Coldfoot SRE Building Replacement

Install AWOS (Various)

Install new lighting and erosion protection.

Install permanent erosion control

Remove obstructions

Resurface all airport operational surfaces

Update ALP

COPPER CENTER 2 (Z93)

Runways: 13/31 - 2,200

Surface: GRVL-F

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$1,312.91

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

CORDOVA MUNI (CKU)

Runways: 06/24 - 1,800
09W/27W - 8,000

Surface: GRAVEL-G
WATER

Lighting:

Classification: Local NPIAS High

CY13 Enplanements: 4

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$14,905.21

USPS Hub: No

School Facility: K-12

FY18 Ops Cost: \$2,626.96

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/23/2016

Airfield Manager: ROBERT MATTSON, 907-424-3202

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Blade Belly

Cordova Eyak Lake SRE Building

Develop ALP

Drainage Project

Handicap Pass Loader

Remove Unapproved Parking

Snow Plow

Truck Plow Airport

Utility Wagon

COUNCIL (K29)

Runways: 10/28 - 3,000

Surface: TURF-F

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$2,695.24

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/17/2015

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0413-002-1998

NEEDS:

Apron Expansion

Brush Cutting

Dust Pallative

Grading and grass clearing on runway

Install aircraft tie-downs

Lease Lots

Replace Cones

Replace Panels

Replace Segmented Circle

Shoulder Stabilization

Update ALP

Wind Sock replacement

CRAIG (CGA)

Runways: N/S - 10,000

Surface: WATER

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 2,638

Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility: Yes

No Revenue: \$0.00

USPS Hub: Yes

School Facility: K-12

No Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JON BOLLING, 907-826-3275

Hours of Operation:

ALL/ALL/DALGT

Last Major Improvement:

NEEDS:

Acquire additional property at Seaplane Base

Add four pull-out ramps to SP float for transient aircraft

Expand the terminal building

Improve street access and provide additional parking for SPB

Install additional bull rail on the center section of float for tying up skiffs

Install pipe bollards and guardrails to protect NE and SE corners of building and eaves around sewer pump station electrical panel, fire hydrant, and ends of the bull rail at the top of the ramp approach

New roof, gutters, downspouts and soffit screens on the building

Repair erosion damage to the bank and install new armor rock on the N side of the ramp

Repair non-skid surfaces on the float and haul out ramps

Repair or replace worn planking

Repair subgrade and repave parking lot

Replace corroded transition plates between floats

Replace Craig SPB Facilities (building, floats and access)

Replace damaged sidewalks on NW and SW corners of terminal building

Replace parking lot, ramp and float lighting with LEDs

Replace signage

Upgrade/Repair Access Ramp and Abutment

CROOKED CREEK (CJX)

Runways: 13/31 - 2,029

Surface: GRVL-DIRT-P

Lighting:

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$18,140.77

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/14/2017

Airfield Manager: RICHARD CILETTI, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Construct RW 13/31 & Apron
3-02-0073-001-1991

NEEDS:

Acquire Land

Add >3000 CY of surface course to runway

Construct 1,271' Runway Extension

Construct a new heated 2-bay SREB

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust Control

Grader

Install MIRL Runway Lighting

Install REIL and AWOS

Install VGS! (PAPI)

Master plan update

Obstruction Removal

Rehabilitate Runway

Reshape runway crown, shoulders, and RSA, and compact

Segmented Circle Panels

SREB

Terrain penetrations removal

DAHL CREEK (DCK)

Runways: 08/26 - 4,780

Surface: GRAVEL-G

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 233

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$14,317.62

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$116.08

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/07/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 8/26, Construct TW & Apron, Remove Obstructions
3-02-0075-002-1986

NEEDS:

Brush Cutting

Dahl Creek Airport improvements

Dahl Creek Airport Lease Lot Development

Install fencing

Relevel or replace wind cone tower and sock

Replace cones and markers

Replace segmented circle

Survey and develop lease lots

Survey and expand apron

Update ALP

DEADHORSE (SCC)

Runways: 06/24 - 6,500

Surface: ASPH-G

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 78,629

Borough: North Slope Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,250,924.06

USPS Hub: No

School Facility:

FY18 Ops Cost: \$2,647,363.89

Part 139 Cert: Yes

On/Off Road: On

Last CIMP Inspection Date: 09/02/2016

Airfield Manager: TIM PARAULT, 907-659-2553

Hours of Operation:

ALL/ALL/0600-1730

Last Major Improvement: Security Improvements/ARFF Bay Addition
3-02-0339-017-2016/3-02-0339-016-2015

NEEDS:

Access Road between Block 500 and new aprons to Dalton Hwy	Fence and Gate Security Improvements
Access Roads for Lots in Blocks 70 and 80	Friction Measure Trailer
Airport Master Plan Update	Grader
Airport Operations Vehicle	Grader
Airport Operations Vehicle	Handicap Pass Loader
Approach Lights	Handicap Pass Loader
Apron Expansion	Lease Lots East of Dalton Hwy.
Blower (7,500 ton per hour)	Lease Lots South Along Dalton Highway
Cat II Approach	New Heavy Apron
Deadhorse Airport Apron Expansion	New Itinerant Apron
Deadhorse Airport Security Upgrades	New Localizer
Deadhorse Apron Expansion	New Taxiways
Deadhorse Drive Extension	PAPI
Deadhorse Fence Installation	Renovate " Kiewitt" Building
Deadhorse SREB/ARFF Building Replacement	Replace "Butler" Building
Drainage Improvements	Replace "old blue shop"
Drainage Improvements - Phase II	Replace airport signage
Electrical repairs and safety checks	Resurface Apron and Taxiways
Expand existing apron to accommodate larger aircraft	Road between Blocks 200 and 700
Expand Heavy Apron	Road between Blocks 50 and 301
Expand Heavy Apron	Road North of Block 200

DEADHORSE (SCC)

Runway 23 ILS

Runway 23 Localizer

Runway Light Cleaning Plow

Secure Gravel Source

Security Upgrades

SREB / ARFF Building Addition to add two double equipment bays and a sand storage bay

SREB/ARFF Building Replacement

Towed Broom Runway Plow

Towed Broom Runway Plow (22' + width)

Weather Reporting Equipment Upgrade

West Lake Colleen Road Lease Lots

Wildlife Control - Phase I

Wildlife Control - Phase II

DEERING (DEE)

Runways: 03/21 - 3,320
12/30 - 2,660

Surface: GRVL-DIRT-G
GRVL-DIRT-G

Lighting: MED
MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$132,307.70

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/05/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate & Extend RW
3-02-0400-004-2001

NEEDS:

Building repairs	Snow Fence

Construct 680' Runway Extension	

Construct Passenger Shelter	

Construct Tie-Downs	

Construct Toilet Facilities	

Dozer	

Dust Palliative	

Expand RSA	

Extend apron	

Extend ROFA	

Extend ROFZ	

Extend runway 680'	

Grader	

Install Culvert	

Relocate Electrical Equipment Enclosure	

Relocate Lighted Wind Cone and Segmented Circle	

Relocate rotating beacon	

Relocate Terminal Bldg	

Repaint building exterior	

Replace overhead door	

Replace Segmented Circle	

DILLINGHAM (DLG)

Runways: 01/19 - 6,400

Surface: ASPH-G

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 32,568

Borough: Dillingham Census Area

Air Carrier Hub: Yes

Medical Facility: Yes

FY18 Revenue: \$184,326.74

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$1,148,787.52

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 10/28/2015

Airfield Manager: NORMAN HEYANO, 907-842-5511

Hours of Operation:

ALL/ALL/0800-1830

Last Major Improvement: Rehabilitate RW 1/19
3-02-0078-016-2017
Access Control Project
3-02-0078-018-2018

NEEDS:

Acquire Land	Expand main terminal apron, vehicle parking area, and RSA
Additional tie-downs	Expand Water/Sewer to all Airport Properties
Airport fence and gate repairs	Extend ROFA
Apron and Taxiway Pavement Rehabilitation	Improve W. Airport Road
ARFF bunker gear	install emergency eye wash station
ARFF SCBA compressor	Install MALSR
Badging computer, software upgrade and printers	Main Apron Redesign for Better Drainage
Build Heliport	Maintain Pavement Markings
Construct 2000' Crosswind Runway and RSA	Master Plan Update
Construct an FAA-compliant RSA	Minor Pavement Repairs
Construct FSS	Pave vehicle parking area
Construct Full Parallel Taxiway	Pave/rehabilitate GA apron and taxiway
Construct RSA embankment	Pavement Markings
Construct Toilet Facilities	Perimeter fencing repairs/replacement
Crack Seal	Realign Wood River Road
Deicer Truck	Reconstruct and Pave Public Parking Area
Dillingham Airport Equipment	Relocate VASI or install PAPI
Dillingham Airport Improvements Stage 2 - FAA Navigation Equipment	Relocate wind cone
Dillingham Airport Improvements Stage 3	Remove buildings
Dillingham SPB Master Plan	Remove Kananak and W. Airport Roads
Door jamb/roof repairs	Remove trees

DILLINGHAM (DLG)

Remove Trees in Approach Surfaces

Repair/repaint exterior panels

Repair/repaint exterior panels

Shift runway away from cemetery

Snow Blower

South Apron Expansion

SUV

Update DLG Surveys and Light Obstructions

Vehicle gates with electronic swipe capability

Water Tanker and Deicing Truck

DIOMEDE (DM2)

Runways: H1 - 64

Surface: CONC-G

Lighting:

Classification: Community Off-Road

No Enplanements: 0

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK-12

FY18 Ops Cost: \$3,121.11

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron, Acquire Land for Development
3-02-0381-001-1993

NEEDS:

Diomedes Temporary SRE Building

Diomedes Weather Reporting

Dozer

Dozer

Little Diomedes Helipad Improvements

Little Diomedes SRE Building Construction

Repair ice scour damage to helipad embankment and replace
riprap

Replace Diomedes lighting and wind cone.

EAGLE (EAA)

Runways: 07/25 - 3,600

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 583

Borough: Southeast Fairbanks Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$8,831.72

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$37,340.91

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/31/2017

Airfield Manager: DENNIS BISHOP, 907-883-5128

Hours of Operation:
UNATNDD

Last Major Improvement: Construct TW & Apron, Install RW Lighting,
Improve Access Road, Extend RW 6/24
3-02-0083-001-1984

NEEDS:

Brush Cutting

Construct Passenger Shelter

Construct Tie-Downs

Eagle Airport Improvements

Improve sub-grade and drainage

Install New Lighting

Relocate apron and access road to meet standards

Resurface runway and taxiway

Update ALP

EDWARD G PITKA SR (GAL)

Runways: 06/24 - 2,794
08/26 - 6,000

Surface: GRAVEL-G
ASPH-CONC-F

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 12,564

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$56,714.13

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$749,866.52

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/23/2014

Airfield Manager: MARVIN THURMOND, 907-656-1236

Hours of Operation:

OCT-APR/MON-FRI/0600-1700

Last Major Improvement: Rehab Apron, Install NAVAID & Segmented Circle,
Remove Obst.
3-02-0102-007-2017

NEEDS:

Airfield lighting and signage repairs

Brush Cutter

Compactor

Construct 7,249' Full Parallel Taxiway

Construct Passenger Shelter

Construct Tie-Downs

Deicer Truck

Fueling equipment repairs

Loader

Paint Truck

Painting

PAPI Needed

Repaving

Replace Segmented Circle and Primary Wind Cone

Runway Undulation Repairs

Sand Storage

security/wildlife fencing

Towed Broom 22' or wider

Undulation Repair

EEK (EEK)

Runways: 17/35 - 3,242

Surface: GRVL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 6,483

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$39,308.13

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/11/2016

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB & New Airport
3-02-0085-003-2002

NEEDS:

Apply Dust Palliative

Beacon

Brush Cutting Around Segmented Circle

Construct 100,000 sq ft Apron and Aviation Support Area

Construct a 2,150' x 12' airport access road

Construct a 2,400' x 60' gravel crosswind runway w/ RSA

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Grader

Grader and loader

Install MIRL and airport lighting

Loader

Primary Windsock & Rotating Beacon Repair

Purchase 225 acres of land

Repair dips on southern end of runway

SREB Repairs

Wildlife Mitigation

ELFIN COVE (ELV)

Runways: NW/SE - 10,000

Surface: WATER-E

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 780

Borough: Hoonah-Angoon Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: None

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/01/2016

Airfield Manager: SCOTT GRAY, (907) 465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Install Electric Power to Dock

Remove Cleats

Weather Reporting Improvements

ELIM (ELI)

Runways: 01/19 - 3,401

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 4,698

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$137,211.22

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: JOHN WILSON, (907) 625-1025

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 1/19
3-02-0090-005-2008

NEEDS:

20:1 Clearance

Upgrade Existing SREB

Apply Dust Palliative

Construct 599' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Embankment stabilization

Erosion repairs

Fuel Tank repairs

Install Runway PAPIs and REILs, and Aeronautical Survey

Install VGS (PAPI)

Loader

Purchase a Portable Emergency Eye Wash Station

Realign Access Road

Relocate beacon off of building

Repair/Renovate SRE Building

Replace Segmented Circle

Replace SRE Building

Resurface Runway, Apron, and Taxiway, Improve Drainage
and Install New Lighting

Upgrade Existing SREB

EMMONAK (ENM)

Runways: 16/34 - 4,601

Surface: GRAVEL-G

Lighting: MED

Classification: Regional

No Enplanements: 0

Borough: Kusilvak Census Area

Air Carrier Hub: Yes

Medical Facility: No

FY18 Revenue: \$10,183.80

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$208,714.46

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: JOHN WILSON, (907) 625-1025

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0397-005-2016

NEEDS:

Acquire Land	Update ALP

Aeronautical Survey and Install ILS	

Apply Dust Palliative	

Brush Cutting	

Construct 399' Runway Extension	

Construct Full Parallel Taxiway	

Construct Passenger Shelter	

Construct SREB	

Construct Tie-Downs	

Construct Toilet Facilities	

Culvert Replacement	

Dozer	

Extend Runway and Improve RSA	

Install new lighting	

Loader	

Relocate Beacon	

Repair Segmented Circle	

Replace Culvert	

Replace Secondary Wind Cone	

Runway Rehabilitation, Ultimate	

U-Blade Loader	

EXCURSION INLET (EXI)

Runways: NW/SE - 1,000

Surface: WATER

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 151

Borough: Haines Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/06/2017

Airfield Manager: SCOTT GRAY, (907) 465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Float Maintenance

Replace seaplane float

FALSE PASS (KFP)

Runways: 14/32 - 2,150

Surface: GRVL-DIRT-G

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 371

Borough: Aleutians East Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$900.00

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$17,908.67

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/16/2016

Airfield Manager: JEFF DOERNING, 907-532-5000

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron, Acquire Land, Improve SREB & Access Road, Rehabilitate RW 13/31
3-02-0097-001-1988

NEEDS:

Acquire Right-Of-Way for Runway Extension

Roundtop Creek Bank; Raise Runway Profile

Apply Dust Palliative

Relocate REILs

Clear Vegetation Around Airport

Repair Current SRE Building

Construct 1,150' Runway Extension

Repair Windsock

Construct New SRE Building

Resurface RSA and grade to drain

Construct Passenger Shelter

Rotating beacon

Construct Tie-Downs

Segmented circle

Construct Toilet Facilities

Taxiway lighting

Electrical enclosure building

Existing SREB Lighting Update

Extend edge lighting

Fuel tanks

Grader

Grader

Install lighted windsock

Install MIRL Runway Lighting

Install MIRLs

Install VGS1 (PAPI)

Loader

Paint New Threshold Markers

Relocate Apron; Construct Lease Lots on Apron; Resurface Runway and Reconstruct Taxiway; Place Riprap Along the

FLAT (FLT)

Runways: 08/26 - 4,045

Surface: TURF-GRVL-P

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 5

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/20/2017

Airfield Manager: STEFFEN STRICK, 907-524-3241

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Brush Cutting

grading

Repair Windsock

wind sock /cones and markers

FORT YUKON (FYU)

Runways: 04/22 - 5,000

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Regional

CY16 Enplanements: 11,605

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$23,814.17

USPS Hub: Yes

School Facility: PK-12

FY18 Ops Cost: \$77,569.75

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB & Rehab Apron
3-02-0100-004--2009

NEEDS:

- Airport Operations Vehicle
-
- Blower (7,500 ton per hour)
-
- Brush cutting
-
- Construct 5,000' Full Parallel Taxiway
-
- Construct Tie-Downs
-
- Construct Toilet Facilities
-
- Create material stockpile
-
- Dust Pallative
-
- Erosion Control
-
- Grader
-
- Lighted Supplemental Wind Cone
-
- Loader
-
- Place signage and/or post/rocks on road that crosses runway
-
- Re-plumb fuel tanks
-
- Resurface runway, taxiway and apron
-
- Runway Light Cleaner
-
- Survey, Clear Obstructions, and Mark Property Boundary
-
- Towed Broom (22'+ width)

FUNTER BAY (FNR)

Runways: NE/SW - 10,500

Surface: WATER-E

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 20

Borough: Hoonah-Angoon Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$3,200.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/01/2016

Airfield Manager: SCOTT GRAY, (907) 465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Elevate Cleats on the Dock

Install Wind Cone

Maintain Dock

Mark Seaplane Threshold and Runway Edges

Replace seaplane float

Replace Slip Proof Grates

GALBRAITH LAKE (GBH)

Runways: 13/31 - 5,182

Surface: GRAVEL-G

Lighting: MED

Classification: Local NPIAS Lower

CY16 Enplanements: 786

Borough: North Slope Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$5,000.29

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: RENIER SWART, (907) 787-8959

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

GAMBELL (GAM)

Runways: 16/34 - 4,499

Surface: ASPH-CONC-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 5,679

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$182,603.31

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: Reconstruct RW 16/34 Lighting, Rehab RW 16/34,
TW & Apron
3-02-0103-004-2017

NEEDS:

Building Improvements

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Fix runway cracks

Gambell Airport Pavement Rehab and Lighting

Grader and Loader

Improve GPS Approach

Improve Runway Safety Areas

Pavement Markings

Repave and Expand Apron

Resurface runway and taxiway

Update ALP

GIRDWOOD (AQY)

Runways: 02/20 - 2,095

Surface: GRAVEL-G

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Municipality of Anchorage

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$28,109.43

USPS Hub: No

School Facility: KG - 8

FY18 Ops Cost: \$10,860.83

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: PAUL BERTHOLL, 907-783-2232

Hours of Operation:
907-783-2232

Last Major Improvement: Rehabilitate RW 1/19 & Install Perimeter Fencing
3-02-0104-002-2002

NEEDS:

Construct apron for transient parking

Construct erosion protection

Construct new airport access road

Construct New Lease Lots and M&O Reserve

Dust Control

Expand Apron

Expand runway

Extend parallel taxiway to north

Extend perimeter fencing

Extend RSA, ROFA, and OFZ

Improve drainage

Install runway edge markers

Lower power/telephone lines

Maintenance building reserve north of the existing lease lot

Obstruction Removal

Pave access road

Relocate both thresholds

Remove Part 77 obstructions (trees)

Replace signage, with a frangible base

Update ALP

GOLD KING CREEK (AK7)

Runways: 09/27 - 2,558

Surface: GRVL-DIRT-F

Lighting:

Classification: Local Non-NPIAS

CY16 Enplanements: 11

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$101.17

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

GOLOVIN (GLV)

Runways: 03/21 - 4,000

Surface: GRAVEL-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 4,247

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$67,697.24

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 16/34 & Lighting, Construct TW & Apron
3-02-0106-004-2016

NEEDS:

Building Improvements

Construct Cross wind runway

Construct Passenger Shelter

Construct taxiway, apron and access road

Construct Tie-Downs

Construct Toilet Facilities

Expand RPZ

Golovin Airport Runway and Apron Improvements

Grader

Install aircraft tie-downs

Install VGSI (PAPI)

Replace the existing airport lighting

Resurface and rehabilitate the runway

Ultimate Approach to Runway 20

Update ALP

GOODNEWS (GNU)

Runways: 06/24 - 3,300

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 1,491

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$28,283.41

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/25/2017

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW
5/23 3-02-0107-002-2009

NEEDS:

Apply Dust Palliative

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Determine Need for Wildlife Hazard Program

Install VGSi (PAPI)

Misc.

Miscellaneous Cleanup

Runway Lighting Change

GOOSE BAY (Z40)

Runways: 08/26 - 3,000

Surface: GRVL-G

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Matanuska-Susitna Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$10,849.21

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 08/04/2016

Airfield Manager: KYLER HYLTON, (907) 246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Install RW Lighting, Improve SREB & Access
Road 3-02-0409-002-1987

NEEDS:

Brush Cutting

Construct Perimeter Fence

Equipment

Minor Gravel Resurfacing

Rehab Threshold Markings

SREB Renovation

GRAYLING (KGX)

Runways: 17/35 - 4,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 1,243

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$82,379.59

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: ERIC WEINGARTH, (907) 438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Construct RW and Apron
3-02-0109-005-2008

NEEDS:

Apply Dust Palliative

Clear Vegetation Around Airport

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Erosion repairs

Erosion stabilization

Grader and Dozer

Install Runway PAPI, REIL, Aeronautical Survey

Install VGS1 (PAPI)

Repair Airfield Lighting and Markers

Repair Runway Threshold Markers

Repair SRE Building

Replace fuel tank

Replace SRE Building

Update ALP

GULKANA (GKN)

Runways: 15/33 - 5,001

Surface: ASPH-G

Lighting: MED

Classification: Community On-Road

CY16 Enplanements: 355

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$24,506.73

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$95,255.00

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

Hours of Operation:

JUN-SEP/MON-FRI/0900-1700

Last Major Improvement: Rehabilitate Apron, TW &RW Remarking
3-02-0110-005-2015

OCT-MAY/MON-FRI/1000-1500

NEEDS:

Apply Dust Palliative

Complete Aeronautical Survey/Remove Part 77 obstructions

Construct Passenger Shelter

Construct Runway 33L/15R

Construct Security Fence for Fuel Tanks

Construct Tie-Downs

Construct Toilet Facilities

Decrease Vertical Runway Grade

Grader

Grader

Grader

Gulkana Airport Apron and Taxiway Repaving

Increase RSA Runway 33R/15L

Install Airport Markings/Signage

Install floodlighting in ramp area

Loader

Place cones on Twy C

Place gate across road

Preventative Maintenance on 504,500 sq. ft. runway pavement
and 168,160 sq. ft. apron/taxiway pavement

Ramp sign removal

Reconstruct apron and taxiway pavement

Reconstruct Runway, Apron & Taxiway Pavement 229,280
sq.ft.

Rehab Runway, Apron and Txy

Rehabilitate SREB building

Relocate FAA facility currently inside OFA

Relocate secondary windsock and/or add an additional

Remove obstacles

Repair and rehab apron

Replace sign panels

Replace Twy A cones with blue banded cones

Resurface airport access road and parking area resurfacing

Resurface medevac apron and taxiway

Segmented Circle Rehab

Snow Blower

GUSTAVUS (GST)

Runways: 02/20 - 3,010
11/29 - 6,720

Surface: ASPH-G
ASPH-G

Lighting: MED

Classification: Regional

CY16 Enplanements: 8,607

Borough: Hoonah-Angoon Census Area

Air Carrier Hub: Yes

Medical Facility: No

FY18 Revenue: \$80,728.06

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$136,686.89

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 11/12/2015

Airfield Manager: JEFF JARVIS, 907-697-2251

Hours of Operation:

1 SEP-1 JUN/ALL/0600-1400

1 JUN-1 SEP/FRI-MON/1030-1830

1 JUN-1 SEP/TUE-THU/0600-1830

Last Major Improvement: Improve RSA 11/29
3-02-0111-005-2011

NEEDS:

Construct 6,721' Full Parallel Taxiway

Construct Future Apron

Construct New SRE/ARFF Building

Construct Sand and Chemical Building

Construct Tie-Downs

Construct Ultimate 50' wide Taxiway

FY'15 Aeronautical survey in conjunction with pavement project design

Mow Grass on Airport

Obstruction Survey

Rehab Runway 11/29, Apron and Taxiways

Remove and Repaint Both Runways

Replace or service fire extinguishers and eye wash stations

Replace overhead doors

Resurface asphalt aprons

WHA/WHMP Update

HAINES (HNS)

Runways: 08/26 - 4,000

Surface: ASPH-G

Lighting: MED

Classification: Community On-Road

CY16 Enplanements: 7,436

Borough: Haines Borough

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$18,694.52

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$17,296.24

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 04/07/2015

Airfield Manager: MATT BORON, 907-766-2340

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron, TW & Install Perimeter
Fencing
3-02-0112-006-2017

NEEDS:

Brush Cutting in Runway 8/26 Safety Area

Construct Hard Stands

Construct Sand and Chemical Building

Crack Sealing / Banding

Repaint Markings

Runway Rehabilitation

Update ALP

WHA/WHMP Update

HEALY RIVER (HRR)

Runways: 15/33 - 2,910

Surface: ASPH-G

Lighting: MED

Classification: Community On-Road

No Enplanements: 0

Borough: Denali Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$27,027.35

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$2,759.37

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 09/15/2016

Airfield Manager: TOM WILLIAMS, 907-451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 15/33 & TW, Expand Apron
3-02-0414-002-1995

NEEDS:

Airport Lighting replacement

Construct 488' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Healy River Airport Land Lease Extension

Healy River Airport Lighting Replacement

Healy River Airport Resurfacing

Healy River Tree Removal

Install Perimeter Fence

Install VGSI (PAPI)

Replace Wind Cones

Resurface all operational surfaces

Update ALP

HOLY CROSS (HCA)

Runways: 01/19 - 4,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$83,658.55

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/02/2014

Airfield Manager: ERIK WEINGARTH, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0120-003-2001

NEEDS:

2 Loaders

Aeronautical Survey

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust Palliative

Install VGS1 (PAPI)

Raise Runway Grade, Clear Obstructions, Resurface All
Operational Surfaces and Install New Airport Lighting

Relocated and Replace Segmented Circle and Wind Cone

Repair Runway Visual Aids

Replace SRE Building

Resurface Runway

Update ALP

HOMER (HOM)

Runways: 04/22 - 6,701
06W/24W - 2,501

Surface: ASPH-F
WATER

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 44,246

Borough: Kenai Peninsula Borough

Air Carrier Hub: Yes

Medical Facility: Yes

FY18 Revenue: \$217,354.81

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$782,241.61

Part 139 Cert: Yes

On/Off Road: On

Last CIMP Inspection Date: 06/25/2015

Airfield Manager: KEVIN JONES, 907-235-8872

Hours of Operation:

NOV-MAR/ALL/0400-2030

APR-OCT/ALL/0600-2030

Last Major Improvement: Improve RSA 4/22, Rehab TW-C
3-02-0122-016-2018

NEEDS:

2 Snow Plows - 1 with attachments	Construct multiple connective taxiways, heliport, and access ramp
Acquire lease lots, SREB lot	Construct new access road to the GA apron
Acquire Lot 2, Block 400 lease lot	Construct New Regulator Building
Address Part 139 issues on runway 04/22 by filling, regrading, and leveling the RSA	Construct Tie-Downs
Address Part 139 RSA issues along runway 04/22	Crack Seal
Apply dust palliative on GA and Beacon areas	Deicer Truck
ARFF bunker gear	Demo existing SREB and construct new 5-bay facility w/ FSS
brush Cutting	Develop Heliport off Taxiway E and access road
Brush Cutting	Drainage Maintenance & Repair
Brush Cutting Equipment	Expand east terminal apron and access road
Build a new multi-bay ARFF building	Expand RPZ
Chemical and deicing material storage facility	Expand west terminal apron
Cold Storage Building repairs	Extend taxiways, south apron, and GA apron toward Lampert Lake
Construct 30-space vehicle parking lot	External Speakers for all equipment
Construct 5-Bay SREB	Gravel Surface Repairs/Grading
Construct 6,701' Full Parallel Taxiway	Homer RSA Regrading
Construct a full-length parallel taxiway on north side of runway 04/22	Install PAPI lighting system
Construct access road to the dock	Install pavement markings
Construct Boat House Building	Install Rotating Beacon/Floating Transient Floatplane Dock at Beluga Lake
Construct Chemical and Deicing Material Storage Building	

HOMER (HOM)

- Maintain pavement markings (M&O SPM)
- Master Plan Update
- New ARFF Vehicle
- New taxiway and access road to GA lease lots
- Obstruction Removal
- Parallel Taxiways and South Apron Extension
- Pavement Markings
- Perimeter fencing repairs/replacement
- Rebuild GA Tiedowns
- Rehab Approach Lighting and Taxiway Edge Lighting
- Rehabilitate Pavement on GA Apron & TW A & B
- Rehabilitate runway, taxiway, and apron
- Remove berm from Elephant Ear to RWY 22 approach.
- Remove Elephant Ear apron (M&O SPM)
- Remove trees between elephant ear and Lampert Lake (M&O OR)
- Replace snow removal equipment
- Replace snow removal equipment
- Replace snow removal equipment
- Replace surface course
- Replace taxiway signs
- Replace/relocate rotating beacon
- Runway, NAVAIDS, Lights, and Fencing relocation to east
- Safety Areas and Drainage improvements
- Sand Storage Building Lighting timer
- Secure and Monitor Vehicle Parking
- Surface course replacement
- SUV, grader
- Tree removals east of runway
- Vehicle gates with electronic swipe capability
- Visual Aids

HOMER-BELUGA LAKE (5BL)

Runways: NE/SW - 3,000

Surface: WATER

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough: Kenai Peninsula Borough

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$686.91

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: KEVIN JONES, 907-235-8872

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Construct a rescue boat house and lake side floats

Construct access road

Construct Access Road and Ramp

Construct floating dock

Construct floatplane slips

Construct ramp access and turnaround

Control Waterfowl on Lake

Float Plane Base Improvements

Fueling Facility

Homer Beluga Lake Float Plane Base Planning Study

New rotating beacon

Rescue Boat

Water lane acquisition

HOONAH (HNH)

Runways: 06/24 - 3,367

Surface: ASPH-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 6,958

Borough: Hoonah-Angoon Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$8,805.30

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$79,505.52

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: KEN MESERVE, 907-945-3426

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 6/24 & Expand Apron
3-02-0125-005-2012

NEEDS:

Apron Improvements and Lease Lot Access

Construct Tie-Downs

Construct Toilet Facilities

Crack Seal Runway 6/24

FY'18 Apron/TWY Rehab

FY'19 Obstruction Removal

Improve Airport Utilities

Install Perimeter Fence

Obstruction Survey

Pavement Markings RW 6/24

Property Acquisition

Replace Beacon tower with a tip down style for safer access
for maintenance.

Sand and Chemical Storage Shed

Sweeper

Update ALP

HOONAH (OOH)

Runways: E/W - 9,000

Surface: WATER

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Hoonah-Angoon Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$308.50

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/01/2016

Airfield Manager: KEN MESERVE, 907-945-3423

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Chart and Light Zip Line Obstruction

Haul Out Ramp

Maintain Dock

OOH Hydraulic Engineering

Seaplane Base Improvements

Threshold and RW Edge Marking

Tiedown Cleats

HOOPER BAY (HPB)

Runways: 13/31 - 3,300

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 8,354

Borough: Kusilvak Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$1,136.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$44,432.86

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/04/2017

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, Rehab Access Road
3-02-0126-008-2016

NEEDS:

Construct 1,200' Runway Expansion

Construct 3-Bay SREB

Construct access road

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Demolish Old SREB

Dozer

Land acquisition

Loader

Loader and Dozer

New lighting

Relocate apron

HOPE (5HO)

Runways: 17/35 - 2,040

Surface: GRAVEL-F

Lighting:

Classification: Community On-Road

No Enplanements: 0

Borough: Kenai Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$6,520.84

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$4,236.81

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 07/20/2015

Airfield Manager: DREW MOTSINGER, 907-269-5672

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Clear trees

Construct a GA apron and taxiway

Construct access road

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install ASOS or AWOS

Install MIRL Runway Lighting

Install new wind cone A

Install VGS1 (PAPI)

New Tie-downs

Reconstruct the runway to A2 standards

Regrade safety areas

Repair/Replace Cones and markers

resurface runway

HUGHES (HUS)

Runways: 17/35 - 3,381

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 2,157

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$250.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$106,330.03

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/23/2014

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Expand Apron, Install RW Lighting & Rehab,
Acquire Land for Development
3-02-0127-001-1990

NEEDS:

Apply Dust Palliative

Brush Cutter

Brush Cutter

Clear Vegetation in Runway Safety Areas

Compactor

Compactor

Construct 620' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Construct Ultimate Apron

Install ASOS or AWOS

Install New Wind Cone

Install VGSI (PAPI)

Install Weather Reporting Station and GPS Approach

Loader

Loader

Purchase compactor attachment

Raise Airport Grade, Relocate Apron, and Apply Dust Palliative
on Operational Surfaces

Re-Grade and Level Runway

Replace Runway Lighting System

Replace SRE Building

Resurface Runway

Supplemental Wind Cone

Survey, Clear Obstructions, and Mark Property Boundary

Update ALP

HUSLIA (HLA)

Runways: 03/21 - 4,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$3,054.98

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$88,933.07

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/23/2014

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron 3-02-0128-006-2010

NEEDS:

-
- | | |
|---|------------|
| Apply Dust Palliative | Update ALP |
| ----- | |
| Brush Cutter | |
| ----- | |
| Clear Obstructions | |
| ----- | |
| Clear Vegetation in Runway Safety Areas | |
| ----- | |
| Compactor | |
| ----- | |
| Construct Passenger Shelter | |
| ----- | |
| Construct Run-Up Pad on Apron | |
| ----- | |
| Construct Tie-Downs | |
| ----- | |
| Construct Toilet Facilities | |
| ----- | |
| Construct Ultimate Apron | |
| ----- | |
| Fuel Tank Upgrade | |
| ----- | |
| Install Wind Cone | |
| ----- | |
| Repair airfield lighting | |
| ----- | |
| Repair Erosion on Shoulders | |
| ----- | |
| Repair SRE building | |
| ----- | |
| Repair/Replace Runway Threshold Lights | |
| ----- | |
| Replace Beacon Light (White Side) | |
| ----- | |
| Replace Runway Edge Cones | |
| ----- | |
| Replace SRE Building | |
| ----- | |
| Runway Grading and Crown Restoration | |
| ----- | |
| SREB Cleanup | |
| ----- | |

HYDABURG (HYG)

Runways: E/W - 5,000

Surface: WATER

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 23

Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$130.17

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 11/14/2016

Airfield Manager: TIM LACOUR, 907-755-2229

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron & Acquire Land
3-02-0129-001-1994

NEEDS:

HYD Rehab

replace wind sock

IGIUGIG (IGG)

Runways: 05/23 - 3,000

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 315

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$4,433.68

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$42,272.04

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 11/13/2017

Airfield Manager: CLINT ANELON, 907-571-1261

Hours of Operation:
UNATNDD

Last Major Improvement: Acquire Land, Improve SREB & Access Road,
Install RW Lighting, Construct Apron & TW,
Improve RSA
3-02-0131-001-1993

NEEDS:

Acquire additional ROW

Apply Dust Palliative

Brush Cutting

Conduct ALP Update

Construct a Heated 1-Bay SREB

Construct Passenger Shelter

Evaluate and Expand the Property Boundary at the terminal
for land interest

Expand apron

Extend runway 05/23 to 3,300'

Grader, loader, snow removal equipment

Install apron concrete parking pads (2) and additional tie
downs

Install VGS1 (PAPI)

Miscellaneous SREB Cleanup

Reinstall tie downs on apron

Replace and extend existing MIRL

Resolve Airport Land Use Compliance Issues

Resurface Runway and Taxiway

ILIAMNA (ILI)

Runways: 08/26 - 5,086
18/36 - 4,800
E/W - 2,998

Surface: ASPH-G
ASPH-G
WATER-E

Lighting: MED
MED

Classification: Regional

CY16 Enplanements: 4,835

Borough: Lake and Peninsula Borough

Air Carrier Hub: Yes

Medical Facility: No

FY18 Revenue: \$66,978.56

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$535,024.80

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 11/14/2017

Airfield Manager: CLINT ANELON, 907-571-1261

Hours of Operation:

OCT-MAY/M-F/0800-1630

JUN-SEP/M-W/0600-1630

JUNE-SEP/TH/0600-1400

Last Major Improvement: Construct TW C, Strengthen RW 7/25 & 17/35,
Improve Access Road, Acquire Security
Equipment, Install Generator, Construct Service
Road

NEEDS: 3-02-0132-006-2002

Acquire Land

Acquire Snow Removal Equipment

Acquire Snow Removal Equipment

Airfield Lighting and Signage

Construct 4,400' x 200' north/south waterway

Construct 5,086' Full Parallel Taxiway

Culvert replacement

Seal coat airport pavement

KAKE (AFE)

Runways: 11/29 - 4,000

Surface: ASPH-P

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$622.74

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$169,439.05

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: SCOTT GRAY, (907) 465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: Reconstruct RW 11/29 & TW Lighting, Rehab RW
11/29 & Improve RSA 3-02-0398-007-2018

NEEDS:

Acquire Land

Construct access road

Construct apron and leasing area

Construct Hard Stands

Construct Tie-Downs

Construct Toilet Facilities

Extend OFZ & OFA 1000'

Extend RSA 1000'

Extend runway 1000'

Fix Part 77 obstructions

FY'16 Runway Rehab

FY'18 SRE Building and Parking Lot

FY'22 Obstruction Removal and Runway Extension

FY'23 Apron Expansion

PAPI

Remove electric power vault

Remove passenger shelter

Replace Kake Runway Lighting

Replace Kake Taxiway Lighting

Runway Rehab

Test Taxilane Rehab

KALSKAG (KLG)

Runways: 06/24 - 3,198

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 5,248

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$533.19

USPS Hub: Yes

School Facility: 4 - 12

FY18 Ops Cost: \$37,938.18

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/18/2017

Airfield Manager: RICHARD CILETTI, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: Install Perimeter Fence
3-02-0136-002-2003

NEEDS:

Brush Cutting

Construct 10' of gravel access road

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Demolish or Sell Old SREB

Dust Control

Fencing

Grader

Gravel Resurfacing

Improve runway safety area grade and slopes

Relocate Access Road

River Erosion a Concern

Security lighting

Threshold Markers

Timers for lighting

KALTAG (KAL)

Runways: 03/21 - 3,986

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 2,388

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$1,924.61

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$113,672.99

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/23/2014

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron, Improve RSA, SREB, & Access Road, Install RW Lighting
3-02-0137-002-1991

NEEDS:

Apply Dust Palliative

Remove/Relocate Landfill

Brush Cutter

Remove/Relocate Wildlife Ponds

Brush Cutter

Repair airfield lighting

Clear Vegetation in Runway Safety Areas

Repair Airport Fuel Tank

Compactor

Replace Fuel Storage Tank and Enhance Security Measures

Compactor

Replace Segmented Circle

Construct 14' Runway Extension

Replace SRE Building

Construct Passenger Shelter

SRE Building Repairs

Construct Tie-Downs

Survey, Clear Obstructions, and Mark Property Boundary

Construct Toilet Facilities

Test Need for Training

Construct Ultimate Access Road

Update ALP

Construct Ultimate Apron

Install Both PAPIs on Runway 3/21 (replace VASI)

Install New Light Can

Install New Wind Cone

Install New Wind Cone

Install VGSi (PAPI)

Lighted Supplemental Wind Cone

Regrade Ramp

Regrade Runway and Safety Areas

Rehabilitate All Operational Surfaces, Replace Airport Lighting System, and Apply Dust Palliative

KANTISHNA (5Z5)

Runways: 10/28 - 1,887

Surface: GRVL-DIRT-G

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Denali Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, 907-451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Update ALP

KARLUK (KYK)

Runways: 10/28 - 2,000

Surface: GRVL-G

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 446

Borough: Kodiak Island Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$87.70

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$23,823.71

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/13/2016

Airfield Manager: BRUCE MCNEIL, 907-487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Airport surface rehabilitation

Wind cone replacement (M&O DM)

Apron extension by 200'

Brush cutting (M&O OR)

Clear brush around segmented circle (M&O OR) Replace circle

Construct 1,300' Runway Extension

Construct new maintenance building

Construct Passenger Shelter

Construct Toilet Facilities

Grader

Improve Access Road

Install MIRL Runway Lighting

Install Perimeter Fence

Install VGS (PAPI)

Leasehold interest extended in 2012

Rehabilitate runway, taxiway and apron; aggregate needed

Rehabilitate West end of Runway

replace cones and or bands and re align cones

SREB and yard cleanup

Stabilize RSA embankment

verify landfill proximity to airport

Village has Native Sovereignty Issues

KASAAN (KXA)

Runways: N/S - 2,000

Surface: WATER

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 251

Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 11/15/2016

Airfield Manager: TIM LACOUR, 907-755-2229

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron
3-02-0139-001-1989

NEEDS:

KASIGLUK (Z09)

Runways: 17/35 - 3,000

Surface: GRVL-DIRT-F

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$34,913.97

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 03/01/2018

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Install RW & Apron Lighting, Construct TW, Acquire Land, Expand Apron, Improve SREB, Install RW VGS, Extend RW 17/35, & Improve Access Road 3-02-0341-001-1997

NEEDS:

Apply Runway Dust Palliative	Reconstruct runway 17/35 to address settlement and line of sight issues
Brush cutting	Rehab runway 17/35
Construct 1-bay heated SREB	Re-level segmented circle
Construct 2-bay heated SREB	Relevel Windsock Tower
Construct Crosswind Runway	Repair safety area undulations and soft areas
Construct Passenger Shelter	Replace cones and reflective bands
Construct Security Fence for Fuel Tanks	Replace Faded Runway Edge Lighting Globes
Construct Terminal Building	replace threshold panels with current standard markers
Construct Tie-Downs	Safety Area
Construct Toilet Facilities	Stockpile gravel for surface repairs
Dust Control	Visual Aids
Grader	
Grader with Attachments	
Improve SREB	
Install VGS! (PAPI)	
Loader	
Loader	
Loader	
Minor Gravel Resurfacing	
Minor Gravel Resurfacing and Dust Control	
Placards, fire extinguishers and signage for fuel tanks	

KASILOF (5KS)

Runways: 01/19 - 2,400

Surface: GRAVEL-G

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough: Kenai Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 6

FY18 Ops Cost: \$385.19

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 09/13/2016

Airfield Manager: SEAN MONTGOMERY/CARL HIGH, 907-262-2199

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Acquire Ownership of RPZ Area

Additional tie-downs

Brush cutting and tree removal

Brush cutting/Tree removal

Brush Cutting/Tree removal

Clear brush and terrain

Clear surface penetrations

Cone and Marker Repair / Replacement

Install aircraft tie-downs

RSA & RPZ

Wildlife Mitigation

KETCHIKAN INTL (KTN)

Runways: 11/29 - 7,500
WNW/ESE - 9,500

Surface: ASPH-G
WATER

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 131,144

Borough: Ketchikan Gateway Borough

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$537,954.92

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: MIKE CARNEY, 907-225-6800

Hours of Operation:

ALL/ALL/0600-2130

Last Major Improvement: Improve ARFF Building
3-02-0144-023-2016

NEEDS:

Airport parking and circulation improvements

GA and air cargo expansion

ARFF Vehicle

Grader

BROOM RUNWAY SP

HANDICAP PASS LOADER

BROOM RUNWAY TOWED

Improve Terminal Building

Brushing, safety areas and fence line

Install a second boarding ramp in terminal

Construct additional vehicle parking at the ferry dock and terminal

Ketchikan Seaplane Ramp and Floats

Construct executive hangars

KIA fuel storage

Construct floatplane terminal

KTN Paving by SREB & ARFF Buildings

Construct parking structure

Loader

Construct Tie-Downs

Master Plan Update

Crack Seal Runway 11/29

Obstruction Survey for runway 11/29

Deicer Truck

PAPI bases need fill around them to eliminate hump

Dump Truck

Pavement overlay of GA apron

Exit taxiway

Pavement overlay of lower apron access TXY.

Expand Access Road

Preventative Maintenance for 1,125,000 sq. ft. runway and 587,100 sq. ft. apron/taxiway

Expand GA and Air Cargo Aprons

Ramp Repair

Expand M&O/SREB and ARFF

Reconstruct 127,000 sq. ft. runway/taxiway pavement

Fencing repairs (Lower apron fence non standard)

Relevel surface drains and hard stands on ramp

Fencing repairs to eliminate wildlife hazards

Remove part 77 obstructions

FY'14 30' Trap Plow

Repaint Runway Markings

FY'14 Multi-purpose carrier

KETCHIKAN INTL (KTN)

Replace hardstands

Runway pavement seams bleed water in winter

Sander

Search and Rescue Boat

Snow Blower

Snow Plow

Utility Wagon

KING COVE (KVC)

Runways: 07/25 - 3,500

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 1,700

Borough: Aleutians East Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,084.68

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$49,187.36

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/15/2016

Airfield Manager: HAROLD

Hours of Operation:
UNATNDD

Last Major Improvement: Acquire Safety/Security Equipment & Install
Perimeter Fencing 3-02-0147-004-2010

NEEDS:

Brush cutting

Construct Heated Passenger Waiting Terminal

Construct New 3-Bay SRE Building

Construct Tie-Downs

Construct Toilet Facilities

Expand Runway and Runway Safety Area and Widen Taxiway

Grader and Loader

Grading and digouts for shoulders, RSA and apron areas

Renovate Existing SREB

Repair/Maintain Drainage Systems Along Runway

Resurface Runway, Apron, and Taxiway

Update ALP

Vehicle gates with push button electric

Wildlife and Minor Work

KING SALMON (AKN)

Runways: 12/30 - 8,901
18/36 - 4,017
NW/SE - 4,000

Surface: ASPH-P
ASPH-G
WATER

Lighting: HIGH
MED

Classification: Regional

CY16 Enplanements: 47,195

Borough: Bristol Bay Borough

Air Carrier Hub: Yes

Medical Facility: No

FY18 Revenue: \$173,682.30

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$1,007,296.60

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 07/14/2014

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:

ALL/ALL/0800-1800

Last Major Improvement: Rehabilitate RW 12/30 & TW A, B & E
3-02-0148-017-2018

NEEDS:

ARFF bunker gear

Grader

ARFF SCBA compressor

Install 5 Auto-Gate Proxy Readers

ARFF Vehicle

Install REIL and PAPI for Runway 18/36

Badging computer, software upgrade and printers

Install Transit Shelter on Apron

Brush cutting (M&O OR)

Loader

Chart and remove obstructions

Master Plan Update

Chart and remove obstructions

Minivan

Compactor

Overhead Crane

Complete RSA

Purchase RPZ

Construct 4-Bay SRE Building

Purchase Signs

Construct Full Parallel Taxiway

Re-grade and Compact Runway Safety Area

Construct GA Sanitation Facility

Rehabilitate GA Apron and Taxiway G

Construct Parallel Taxiway; Realign and Pave Main Street and
Jensen Road; Expand Long Term Vehicle Parking Area;
Expand Terminal Apron

Rehabilitate Runway 18/36 and Runway 18 Overrun

Rehabilitate Taxiways

Construct Sand Storage Facility

Remove and Repaint Markings

Construct Tie-Downs

Remove leadin Twy

Construct Toilet Facilities

Remove Taxiway P

Crack Seal Pavement

Repair/Replace Segmented Circle Panels

Dozer

Replace edge lighting for both runways

Fence and Gate Repair

Replace wind cones

GA Parking Solution

KIPNUK (IIK)

Runways: 17/35 - 3,200

Surface: GRAVEL-F

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$752.81

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$37,919.87

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/08/2016

Airfield Manager: LJ DAVIS, 907-543-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct RW 3-02-0150-004-2010

NEEDS:

Airfield Vandalism

Apply Dust Palliative

Construct 100' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Construct two SREBs

Environmental

Install VGSI (PAPI)

Replace edge lighting

SREB Safety Repairs

KITOI BAY (KKB)

Runways: E/W - 4,000

Surface: WATER

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 105

Borough: Kodiak Island Borough

Air Carrier Hub: No

Medical Facility: No

No Revenue: \$0.00

USPS Hub: No

School Facility: None

No Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: KODIAK REGIONAL AQUACULTURE ASSOC.,

Hours of Operation:
UNATNDD

Last Major Improvement:

NEEDS:

KIVALINA (KVL)

Runways: 12/30 - 3,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 5,910

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,287.79

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$92,023.12

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/05/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Acquire Easement for Approaches & Improve
Airport Erosion Control, Construct Erosion
Protection
3-02-0152-005-2018

NEEDS:

Apply Dust Palliative

Clear Transitional Surface by Remove Brush

Construct 1,000' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Expand Apron

Expand RSA and ROFA

Grader and Loader

Install VGSI (PAPI)

Kivalina Airport Erosion Control

Kivalina SRE Building Replacement

Loader

loader mounted snow blower

Paint Building Exterior

Reestablish Runway Crown and Compact Surface

Rehabilitate Runway Surface

Relocate Landfill

repair or replace furnaces

Replace wind cone, runway cones and or color bands.

Widen Runway by 15'

KLAWOCK (AKW)

Runways: 02/20 - 5,000

Surface: ASPH-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$35,040.42

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$151,088.93

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: TIM LACOUR, 907-755-2229

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB
3-02-0154-0082001

NEEDS:

add 7 smaller aircraft tie downs

add NPI markings

Apron/Taxiway Preventative Maintenance

BROOM RUNWAY TOWED

Brush cut RSA RWY 2/20

Brush Cutting in Runway Safety 2/20 Area

construct access road and aircraft pullout ramp to provide SP access to airport apron

construct access taxiway to GA aviation lease lots

Construct air cargo apron improvements and a cargo terminal

Construct Apron

Construct ARFF building and purchase ARFF vehicle

construct connector road between apron and access road

Construct float plane haul out and access road

Construct helipad

construct lease lots

Construct Parallel Taxiway

Construct ramp parking hard stands

Construct runway extension

Construct SREB

Construct Terminal Building

Construct Tie-Downs

Construct Toilet Facilities

Crack Seal Runway 2/20

Dump Truck

Electrical conduit exposed

Evaluate /Repair Runway Undulations

Expand apron and lease lots

expand terminal aircraft parking apron

extend W&S Utilities

FY'20 Obstruction Removal

Hazmat Barrels Located on Airport

Improve Access Road

improve airfield pavement

install approach lighting

Paint 6 biz jet parking spaces

parking lot 100 sq. ft.? raise approx. 1000 lf. of Access road to apron grade

Pavement Preservation

Reconfigure apron lease lot arrangement

Reduce runway grade, extend runway 1000'

Rehabilitate Runway 02/20

Relocate ASOS Wind Sensor

KLAWOCK (AKW)

relocate wind sensor

Remove Part 77 obstructions

Remove ROFA and airspace obstructions

Repair erosion damage and install permanent beach erosion control

Replace Segmented Circle and Wind Cone

Runway markings (NPU) poor

Runway signs

Safety Area Drainage

Sander

Transfer PAPI ownership to FAA, restore Runway 20 PAPI's

Wildlife control

KOBUK (OBU)

Runways: 09/27 - 4,020

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 3,165

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$100,890.05

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/07/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron & RW 9/27 & Extend RW
9/27 3-02-0427-003-2003

NEEDS:

ASOS needs to be connected to emergency generator

AWOS

Brush Cutting

Building upgrades

Construct new Taxiway

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Floodlights

Fuel Tank Upgrade

grade and compact safety areas

Install ASOS or AWOS

Install VGS (PAPI)

Rehabilitate Runway Surface

KODIAK (ADQ)

Runways: 01/19 - 5,009
08/26 - 7,533
11/29 - 5,400

Surface: ASPH-G
ASPH-G
ASPH-G

Lighting: HIGH
HIGH
HIGH

Classification: Regional

CY16 Enplanements: 80,372

Borough: Kodiak Island Borough

Air Carrier Hub: Yes

Medical Facility: Yes

FY18 Revenue: \$233,629.41

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$1,282,245.11

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 10/10/2016

Airfield Manager: PHILLIP SMITH, 907-487-4952

Hours of Operation:

SAME AS ARPT MAINT HRS

Last Major Improvement: Improve Airport Drainage
3-02-0158-019-2015

NEEDS:

Apron A, B, C Rehab pavement

Vehicle gates with electronic swipe capability

ARFF bunker gear

ARFF Vehicle 3000 gal.

Badging computer, software upgrade and printers

Construct new 3-bay ARFF building

Construct Tie-Downs

Grader

Maintain pavement markings and crack seal (M&O SPM)

Minivan

New Equipment

Perimeter fencing repairs/replacement

Rehabilitate Runway 11/29 Pavement

Remove Part 77 tree obstructions (M&O OR)

Replace electric gate A

Replace fence/gates around perimeter of ramp

Replace fencing around Commercial Apron perimeter

Sand seal aprons A & C (M&O SPM)

Surface Area and Reconfigure Drainage between RW 7 and 11

Taxiway F Rehab Pavement

Tree/Brush Cutting around Airport

Upgrade the ARFF vehicle from 1,500 to 3,000 gallons

KOKHANOK (9K2)

Runways: 07/25 - 3,300

Surface: GRVL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$736.37

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$45,153.90

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 11/14/2017

Airfield Manager: CLINT ANELON, 907-571-1261

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 6/24, Expand Apron, Construct SREB
3-02-0406-002-2005

NEEDS:

Airport Drainage

Apply Dust Palliative

Brush Cutting

Construct Passenger Shelter

Construct SREB

Construct Tie-Downs

Construct Toilet Facilities

Expand RSAs

Expand runway to 4,200' x 75'

Grader & loader with attachments

Install one or two apron concrete parking pads

Install PAPs and REILs

Miscellaneous SREB Cleanup and Cone Replacement

Replace Devils Creek culvert

Resurface gravel runway, taxiway, and apron

Wildlife Hazard on Airport

KOLIGANEK (JZZ)

Runways: 09/27 - 3,300

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Dillingham Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$3,176.67

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$26,736.10

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: NORMAN HEYANO, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Reconstructed and Extended RW to 3,300' in 2015

NEEDS:

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Grader & Loader with Attachments

Install AWOS

Install REILs

Loader

KONGIGANAK (DUY)

Runways: 01/19 - 2,400

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$29,488.54

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/08/2016

Airfield Manager: LAWERENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 18/36, Widen RSA
3-02-0380-003-2010

NEEDS:

- Add surface course to runway surface

- Construct 900' Runway Extension

- Construct a new apron and segmented circle

- Construct new SREB

- Construct Passenger Shelter

- Construct SREB

- Construct Tie-Downs

- Construct Toilet Facilities

- Environmental

- Grader and Loader

- Install ASOS or AWOS

- Install VGS! (PAPI)

- Loader

- Minor Gravel Resurfacing

- Replace Wind Cone

- Resurface south half of existing runway

- Runway Resurfacing

- Scarify, reshape and recompact surfacing material runway
(M&O SPM)

- Upgrade Windssock with Lighting

KOTLIK (2A9)

Runways: 02/20 - 4,400

Surface: GRAVEL-F

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Kusilvak Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$123,140.47

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: JOHN WILSON, (907) 625-1025

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Taxiway, RW 2/20 & Apron & Improve
Access Road & SREB 3-02-0159-002-1995

NEEDS:

20:1 Clearance

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install AWOS (Various)

Install VGSI (PAPI)

Repair Ramp

Replace runway markers and cones

Replace segmented circle and light tower

Resurface airport and electrical system replacement

KOYUK ALFRED ADAMS (KKA)

Runways: 01/19 - 3,002

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 3,952

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$112,822.06

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: JOHN WILSON, (907) 625-1025

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron, Acquire Land for Development,
Improve SREB
3-02-0161-002-1991

NEEDS:

Building upgrades

Construct 998' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

New ULSD tank

Repair airfield lighting

resurface runway

Update ALP

KOYUKUK (KYU)

Runways: 06/24 - 4,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 1,991

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 10

FY18 Ops Cost: \$88,510.91

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 03/23/2014

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RSA, Rehab & Extend RW 6/24, Expand Apron, Construct SREB 3-02-0162-002-2003

NEEDS:

Building Maintenance

Compactor

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Grader

Install ASOS or AWOS

Koyukuk SRE Building Replacement

Lighted Supplemental Wind Cone

Loader

PAPI Needed (Runway 24)

Survey, Clear Obstructions, and Mark Property Boundary

Upgrade lighting

KWETHLUK (KWT)

Runways: 18/36 - 3,199

Surface: GRVL-DIRT-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 5,716

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$23,866.09

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/08/2017

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Construct New Airport
3-02-0435-001-2001

NEEDS:

Acquire Land	Replace cones and reflective bands
-----	-----
Apply Dust Palliative on Runway	Replace Faded Runway Edge Lighting Globes
-----	-----
Beacon	Safety Area
-----	-----
Brush Cutter	SREB maintenance
-----	-----
Brush cutting	Stockpile gravel for surface repairs
-----	-----
Brush Cutting	

Construct 1-bay SREB with Floor	

Construct 1-bay SREB with floor	

Construct Passenger Shelter	

Construct Tie-Downs	

Construct Toilet Facilities	

Dozer	

Dust Control	

Grader	

Grader	

Loader	

Minor Gravel Resurfacing & Dust Control	

Rehab RW 18/36 gravel surface, safety areas, txys and ramp	

Relevel and Repair Windsock Tower	

Remove RW 36 approach (hill)	

Repair safety area undulations and soft areas	

KWIGILLINGOK (GGV)

Runways: 15/33 - 1,835

Surface: GRVL-DIRT-F

Lighting:

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$38,199.43

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/18/2017

Airfield Manager: LAWERENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron, RW 15/33 & TW
3-02-0165-004-2018

NEEDS:

Acquire Native Allotments and Tribal Property

Apply Dust Palliative

Construct 1,465' Runway Extension

Construct 2, 1-bay SREBs

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Grader

Grader, snow plow and wing attachments, loader

Gravel Surface Repair

Install erosion projection for rwy embankment along tidal
slough

Install MIRL Runway Lighting

Install VGS (PAPI)

Loader

Rehabilitate runway, taxiway, and apron surfaces

Replace Wind Cone

Replace Wind Cone Tower

Reshape, recrown and compact runway surface

Resolve Trespass Property Issues

Runway reduced to 1840 x 30 on 6-27-11 in message to FAA
from the previous 2,472'.

LAKE LOUISE (Z55)

Runways: 13/31 - 2,900

Surface: GRAVEL-E

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Matanuska-Susitna Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$250.00

USPS Hub: No

School Facility: K - 12

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 10/24/2015

Airfield Manager: JOHN HOFFMAN, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 12/30, Access Road, & Apron
3-02-0430-002-20-2010

NEEDS:

Remove obstructions on dock at Seaplane Base

Remove/replace Wind Cone

Safety area/ ramp grading

Secure runway

LARSEN BAY (2A3)

Runways: 04/22 - 2,690

Surface: GRVL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Kodiak Island Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$24,665.50

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/13/2015

Airfield Manager: BRUCE MCNEIL, 907-487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB & Access Road, Install RW Lighting, Construct Apron, Acquire Land 3-02-0166-001-1993

NEEDS:

Add a GPS Approach

Airport Lighting Repair

Apply Dust Palliative

Brush Cutting

Construct 1-bay SREB

Construct 600' Runway Extension

Construct Passenger Shelter

Construct Toilet Facilities

Grader

Install VGSI (PAPI)

Level out Runway 4/22

Purchase a Portable Emergency Eye Wash Station

Regrade RSA

Rehabilitate Runway Surface and Edges

Remove old chevron panel signs

Remove Trees on West end of Runway

Repair/replace runway lights.

SREB cleanup

Stream realignment

Wind Sock replacement

LEVELOCK (9Z8)

Runways: 01/19 - 3,284

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$34,172.37

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB
3-02-0167-002-2003

NEEDS:

Apply Dust Palliative

Brush cutting

Construct Crosswind 07/25 Runway

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Extend RSA to 120' x 3761'

Install ASOS or AWOS

Install VGSI (PAPI)

Place E-1 on apron, shoulders, and RSA and compact (M&O
SPM)

Rehabilitate airfield with new aggregate on runway, taxiway,
apron, shoulders, and RSA

Replace threshold markers

LIME VILLAGE (2AK)

Runways: 10/28 - 1,500

Surface: GRVL-DIRT-F

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$774.68

USPS Hub: No

School Facility:

FY18 Ops Cost: \$28,717.74

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/20/2017

Airfield Manager: STEFFEN STRICK, 907-524-3241

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Airport is subject to river erosion and ice jam flooding.

building

Bypass trail at the airport for access around the airport

Construct a second SREB

Construct new community class airport

Construct RSA (4800' x 75')

Construct runway (4000' x 75'), taxiway, apron (60,000 sqft)

Construct SREB with rotating beacon

Embankment repair and obstruction removal

Embankment/Erosion

equipment fuel tank

Extend electric power lines to airport and acquire 50 acres of land

Grader

grader

Grader and loader

Grader, snow plow, loader wheel

Reestablish airport Right of Way

Remove brush and trees from approaches

Remove trees from primary surface

Remove Windsock from on Top of SREB

Resurface eroded material on west end of runway

runway

Runway cannot be lengthened without expensive relocation

SREB

windsock

LIVENGOOD CAMP (4AK)

Runways: 15/33 - 3,000

Surface: GRVL-G

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$991.49

USPS Hub: No

School Facility:

FY18 Ops Cost: \$4,300.83

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/30/2016

Airfield Manager: JEFF RUSSELL, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Minor Drainage Work

Remove Possible Obstructions

LLOYD R ROUNDTREE SEAPLANE FACILITY (63A)

Runways: NE/SW - 9,000

Surface: WATER-E

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Petersburg Borough

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$2,667.99

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/10/2016

Airfield Manager: BARRY YOUNGBERG, (907) 772-4624

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron & Acquire Land
3-02-0340-001-1994

NEEDS:

Replace Wind Sock

Veg clearing /wildlife management /mat replacement

MANLEY HOT SPRINGS (MLY)

Runways: 18/36 - 3,400

Surface: GRAVEL-G

Lighting: MED

Classification: Community On-Road

CY16 Enplanements: 240

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$-100.00

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$125,041.77

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 11/30/2017

Airfield Manager: JEFF RUSSELL, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0170-003-2015

NEEDS:

Construct Passenger Shelter

Extend and widen runway to 3,400' x 75'

Increase clear area to treeline runway end 18

Install VGSI (PAPI)

Manley Airport Improvements and Apron Construction

Wheel Loader

MANOKOTAK (MBA)

Runways: 03/21 - 3,300

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Dillingham Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$3,796.27

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$42,432.81

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/15/2015

Airfield Manager: NORMAN HAYANO, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0473-002-2007

NEEDS:

Apply Dust Palliative

Construct additional lease lots

Construct Additional Taxiway

Construct Tie-Downs

Construct Toilet Facilities

Construction SRE/highway M&O building

Expand RPZ

Extend Access Road by Apron

Extend Apron Additional 400' x 300'

Extend ROFA 700'

Extend ROFZ 700'

Extend RSA to 4,600'

Extend Runway to 4,000'

Fuel tank upgrades

Install REILs

Install VGSI (PAPI)

Relocate Wind Cone and Segmented Circle

Snow Blower

Visual Aid repairs/replacement

MARSHALL DON HUNTER SR (MDM)

Runways: 07/25 - 3,200

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Kusilvak Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$750.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$82,887.01

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: ERIK WEINGARTH, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport & Improve SREB
3-02-0363-003-1999

NEEDS:

Construct 800' Runway Extension

Construct Crosswind Runway

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Fuel Tank Upgrade

Install VGS1 (PAPI)

Marshall Airport Improvements

purchase a portable emergency eye wash station

Severe Cracking & Lighting Shifting

Shoulder and slope repair

Threshold Lighting Repair

Update ALP

MAY CREEK (MYK)

Runways: 13/31 - 2,700

Surface: TURF-GRVL-G

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 22

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Develop ALP

Tie-down replacement

MC GRATH (MCG)

Runways: 05/23 - 2,000
16/34 - 5,936

Surface: GRAVEL-G
ASPH-G

Lighting: MED
MED

Classification: Regional

CY16 Enplanements: 4,007

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: Yes

Medical Facility: No

FY18 Revenue: \$72,359.46

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$246,167.38

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/24/2016

Airfield Manager: STEFFEN STRICK, 907-524-3241

Hours of Operation:

MAY-SEPT/MON-WED/0700-1730

OCT-APR/MON-FRI/0800 - 1630

MAY-SEPT/THURS/0700-1500

Last Major Improvement: Construct RW & Apron
3-02-0176-005-2006

NEEDS:

Construct Tie-Downs

Construct Toilet Facilities

Crack Seal

Erosion Control

Expand SREB

Install Perimeter Fence

Install wind cone and segmented circle

Obstruction removal

Pavement Markings

Pavement Rehabilitation

Perimeter fencing repairs/replacement

Rehabilitate Runway 16/34 Lighting

Rehabilitate Runway, Taxiway, and Apron Pavement

Snow Blower

Snow plow, snow blower, dump truck, snow attachments

Vehicle gates with push button electric

MCCARTHY (15Z)

Runways: 01/19 - 3,501

Surface: GRVL-DIRT-F

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$10,324.95

USPS Hub: No

School Facility:

FY18 Ops Cost: \$13,301.76

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: Construct RW 1/19
3-02-0334-003-1999

NEEDS:

Update ALP

MEKORYUK (MYU)

Runways: 05/23 - 3,001

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 2,225

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$60,963.16

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/26/2016

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate TW, Apron, & RW 5/23, Install RW Lighting 3-02-0178-001-1984

NEEDS:

Abandon east GA apron and the GA "elephant ear" apron

ASOS and RCO improvements

Build Crosswind Runway

Building cleaning and safety checks

Construct 930' Runway Extension

Construct a new segment circle

Construct new three bay SREB

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Grader

Gravel Resurfacing

Install lighting

Install New Windsock

Loader wheel, grader, bulldozer, snow attachments, snow blower

Minor Gravel Resurfacing

Reconstruct runway with grade raise

Rehab Runway & Access Road

Rehabilitate Runway/Access Road

Replace Electrical Lighting Vault and Transformer

Resurface Access Road

Resurface runway and build crosswind runway

Runway Extension

Segmented Circle

SREB

Update ALP

Upgrade or construct heated SREB

Upgrade Runway Lighting

Visual Aids

MERLE K (MUDHOLE) SMITH (CDV)

Runways: 09/27 - 7,500
16/34 - 1,899

Surface: ASPH-G
GRVL-DIRT-F

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 34,290

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$60,188.99

USPS Hub: No

School Facility: K-12

FY18 Ops Cost: \$740,568.77

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 08/24/2016

Airfield Manager: ROB MATTSON, 907-424-3202

Hours of Operation:

ALL/MON-FRI/0700-1730

Last Major Improvement: Apron, TW, & GA Improvements
3-02-0067-014-2016

ALL/SAT-SUN/0700-1730

NEEDS:

AARF/Maintenance Shop Replacement

Replace Damaged Culverts

Airport crack sealing

Resolve drainage problems

Airport Operations Vehicle

Runway 9/27 Tree Removal

Blower (7,500 ton per hour)

Runway Light Plow Cleaner

Chemical Storage Building Replacement

Runway Resurfacing

Complete obstruction removal

Sand Storage Repairs

Construct Access Road

SREB Replacement

Construct Full Parallel Taxiway

Towed Broom 22' or wider

Construct partial parallel and connecting taxiways

Transient and GA aircraft parking

Construct Tie-Downs

Tree removal

Cordova Airport Apron, Taxiway and GA Improvements Stage 2

Wildlife Control Measures

Cordova Airport RSA Improvements (Drainage)

Cordova Airport Security Upgrades

Cordova SREB/ARFF Building Replacement

Deicer Truck

Expand existing apron area

Heliport pad, aviation support areas

Install Perimeter Fence

Maintenance Equipment

Rehabilitate the runway safety areas, including grading and drainage improvements, clearing and grubbing.

METLAKATLA (MTM)

Runways: E/W - 5,000
N/S - 5,000

Surface: WATER
WATER

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 2,513

Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$2,087.06

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: SCOTT GRAY, (907) 465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate SPB
3-02-0369-003-2004

NEEDS:

Master Plan Update

Metlakatla Seaplane Base Rehab and Reconfigure

MEYERS CHUCK (84K)

Runways: NW/SE - 7,000

Surface: WATER

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: City and Borough of Wrangell

Air Carrier Hub: No

Medical Facility: No

No Revenue: \$0.00

USPS Hub: No

School Facility:

No Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: GREG MEISSNER, HARBOR MASTER, (907) 874-3736

Hours of Operation:
UNATNDD

Last Major Improvement:

NEEDS:

MINCHUMINA (MHM)

Runways: 03/21 - 4,184

Surface: GRAVEL-G

Lighting: MED

Classification: Local NPIAS Lower

CY16 Enplanements: 3

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,042.20

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$102,398.66

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/26/2014

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0180-002-1991

NEEDS:

Clean up Shop Area

Clean, organize and inventory materials

Compactor

FY'18 Seaplane Float Rehab/Reconfiguration

Grader

Leasehold cleanup

Lighted Supplemental Wind Cone

Lighting Repairs

PAPI Needed (Runway 21)

Repair Wiring and Conduit

Replace eye wash stations

Replace Windsock Pole and Lighting

Runway resurfacing

Survey, Clear Obstructions & Mark Property Boundary

taxiway culvert replacement

Update ALP

Wildlife control

Wind Cone Replacement

MINTO AL WRIGHT (51Z)

Runways: 02/20 - 3,400

Surface: GRAVEL-G

Lighting: MED

Classification: Community On-Road

No Enplanements: 0

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$36,765.17

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: JEFF RUSSELL, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, RW, & Apron
3-02-0336-002-2007

NEEDS:

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Update ALP

MOUNTAIN VILLAGE (MOU)

Runways: 02/20 - 3,501

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 6,656

Borough: Kusilvak Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$1,654.40

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$95,397.60

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: ERIK WEINGARTH, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 2/20 & Construct RSA
3-02-0184-002-2004

NEEDS:

Apply Dust Palliative

Construct 499' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Fuel Tank Upgrade

Install PAPI

Repair PAPI

Repair REIL Lighting

Repair Shoulder/RSA cracking

Repair/Renovate SRE Building

Replace Segmented Circle

Replace supplemental edge markers

Replace Wind Cone

Resurface Runway

Safety Area Repairs

Update ALP

NAKNEK (5NK)

Runways: 08/26 - 1,950
08W/26W - 2,000
14/32 - 1,836

Surface: GRAVEL-P
WATER
GRAVEL-P

Lighting:

Classification: Local NPIAS High

No Enplanements: 0

Borough: Bristol Bay Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$18,064.14

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 07/15/2014

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Airport is not federally obligated

Brush Cutter

Clear Vegetation in Runway Safety Areas

Compactor and Grader

Full Survey of Airport Property Boundary

Improve Drainage

Loader and Blower

New ALP for Seaplane Base Study

Re-Grade and Compact North/South Runway

Repair Windssock

Snow removal attachments

Update ALP

NANWALEK (KEB)

Runways: 01/19 - 1,850

Surface: GRAVEL-P

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 2,869

Borough: Kenai Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$20,032.61

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/27/2016

Airfield Manager: KEVIN JONES, 907-235-5217

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Acquire acreage for new airport

Construct 1,450' Runway Extension

Construct 2-mile access road connecting Port Graham & Nanwalek

Construct airport parking apron

Construct new SREB

Construct Storage Shed

Construct Toilet Facilities

Develop ALP

Install AWOS or ASOS

Install MIRL Runway Lighting

Install Secondary Wind Cone

Install VGS1 (PAPI)

Landfill relocation

Mark Runway Edges

Minor Gravel Resurfacing

Minor Gravel Resurfacing

Provide shore protection

Replace all cones and markers

Shape and Compact Runway and Taxiway

Study alternative locations for constructing a new airport

Transformer replacement

NAPAKIAK (WNA)

Runways: 16/34 - 3,248

Surface: GRAVEL-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 2,221

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$25,636.94

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/18/2014

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB
3-02-0188-002-2003

NEEDS:

20:1 Clearance

Address Boundary Crossing Issues

Apply Dust Palliative

Brush Cutting (M&O OR)

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust Control

fencing

Grader

Grader, loader, snow plow attachments

lighting repairs

Loader

Minor Gravel Resurfacing

Place E-1 on runway crown and compact

Repair Cones

Replace Electrical Lighting Vault and Transformer

SREB Repair

Update ALP

Update Master Plan

wildlife control

NAPASKIAK (PKA)

Runways: 02/20 - 3,000
09W/27W - 15,000

Surface: GRVL-G
WATER

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 2,497

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$42,992.30

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/18/2014

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron, TW, Rehabilitate RW 1/19,
Improve SREB & Access Road, Install RW
Lighting
3-02-0189-002-1991

NEEDS:

Airport relocation study needed

Replace fuel tanks

Apply dust palliative

Replace Primary Wind Cone Tip Down Mechanism

Beacon

Replace Segmented Circle and Wind Cone Tower

Brush Cutting

Rwy 20 approach clearance

Construct a 1-bay Heated SREB with Floor

Construct a 1-bay heated SREB with floor

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust Control

Electrical vault replacement

Grader

Grader, loader, snow plow attachments

Install ASOS or AWOS

Install VGSI (PAPI)

Loader

Minor Gravel Resurfacing

New Lighted Cones

Place E-1 on runway crown and compact

Repair Rotating Beacon

Replace Electrical Lighting Vault and Transformer

NELSON LAGOON (OUL)

Runways: 08/26 - 4,003

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Aleutians East Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility:

FY18 Ops Cost: \$19,445.82

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/15/2016

Airfield Manager: HAROLD

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB & Access Road, Expand Apron,
Rehabilitate RW 8/26 & RW Lighting, Acquire Land
3-02-0190-001-1996

NEEDS:

Airport surface repairs

Construct a New 1-bay SREB

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Electrical vault replacement

Grade Taxiway, TSA, and Apron (M&O SPM)

Grader, loader, snow plow, motor grader

Grass Cutting

Install VGS1 (PAPI)

Place E-1 on runway crown, shoulders, and RSA, and compact

Replace Airport Lighting

Replace threshold markers

Replacement runway lighting

Transformer replacement

Update ALP

NEW STUYAHOK (KNW)

Runways: 14/32 - 3,281

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 1,210

Borough: Dillingham Census Area

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$1,875.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$63,632.13

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: NORMAN HEYANO, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB & New Airport
3-02-0436-003-2006

NEEDS:

Construct crosswind 04/22 runway (3,300' x 60')

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Construct ultimate taxiway

Drainage Maintenance & Repair

Dust Control

Expand the RSAs

Expand the runway to 5,000' x 100'

Grader

Grader

Minor Gravel Resurfacing

Transformer replacement

NEWTOK (EWU)

Runways: 15/33 - 2,202

Surface: GRVL-P

Lighting:

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$31,793.22

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/11/2016

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate TW, RW 15/33, & Apron
3-02-0194-005-2017

NEEDS:

Acquire Parcels B & C

Construct 1,098' Runway Extension

Construct 1-bay 1 heated SREB

Construct a new airport at Mertarvik (currently village is impacted by river erosion)

Construct lighting, 1.5-mile access road

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Develop airport site alternatives upon relocation of community

Dust Control

EIS concurrent with new airport at Mertarvik

Grader

Install MIRL Runway Lighting

Install VGSI (PAPI)

Minor Gravel Resurfacing

Replace 2 Wind Cones

Segmented Circle

NIGHTMUTE (IGT)

Runways: 03/21 - 3,200

Surface: GRVL-DIRT-F

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$38,740.05

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/22/2017

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 2/20, Expand Apron, Construct SREB
3-02-0195-001-2007

NEEDS:

Acquire Additional Equipment

Airport master plan

Apply Dust Palliative

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install ASOS or AWOS

Install VGS (PAPI)

Miscellaneous SREB Cleanup

Repair Sinking/Settling Runway End

Surface Rehabilitation

NIKOLAI (FSP)

Runways: 05/23 - 4,021

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$60,371.30

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/27/2017

Airfield Manager: STEFFEN STRICK, 907-524-3241

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW, Improve SREB, Rehabilitate RW
3-02-0357-001-2001

NEEDS:

build maint

building maint

cones secodary wind sock

cones/end markers/windsock

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

external speaker

Grader

Loader

Loader

NINILCHIK (NIN)

Runways: 10/28 - 2,400

Surface: GRAVEL-G

Lighting:

Classification: Local Non-NPIAS

CY15 Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$1,309.43

USPS Hub: No

School Facility:

FY18 Ops Cost: \$389.20

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 09/13/2016

Airfield Manager: SEAN MONTGOMERY/CARL HIGH, 907-262-2199

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Cone and Marker Repair / Replacement

Minor Gravel Resurfacing

RSA

Segmented Circle

NOATAK (WTK)

Runways: 01/19 - 3,992

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 6,556

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$10,424.92

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$115,627.78

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/05/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 18/36, Expand Apron, Install RW Lighting, Improve SREB
3-02-0198-002-1992

NEEDS:

-
- Brush Cutting Widen runway by 15'
 -
 - Construct Passenger Shelter
 -
 - Construct SREB
 -
 - Construct Tie-Downs
 -
 - Construct Toilet Facilities
 -
 - Expand RPZ
 -
 - Expand RSA
 -
 - Fuel Tank Upgrades
 -
 - Grader
 -
 - Install GPS Approach
 -
 - Loader
 -
 - New school facility
 -
 - Noatak Airport Relocation
 -
 - Noatak Airport Relocation
 -
 - Relocate Equipment building
 -
 - Remove existing road
 -
 - Remove existing storage building
 -
 - Repair SREB
 -
 - Replace Segmented Circle and Wind Cone Tower
 -
 - Snow Blower
 -
 - Update ALP
 -

NOME (OME)

Runways: 03/21 - 6,176
10/28 - 6,009

Surface: ASPH-G
ASPH-G

Lighting: MED
HIGH

Classification: Regional

CY16 Enplanements: 75,739

Borough: Nome Census Area

Air Carrier Hub: Yes

Medical Facility: Yes

FY18 Revenue: \$167,490.65

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$1,852,261.45

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 07/11/2017

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
ALL/ALL/0700-2100

Last Major Improvement: Rehabilitate RW 10/28 & North Apron, Rehab RW
3/21
3-02-0199-026-2018

NEEDS:

Acquire Land	Construct vehicle access road and parking area
Acquire Land	Crack sealing and ponding repairs
Add Obstruction Light to Ravn Hangar	Deicer Truck
Airport Operations Vehicle	De-icing Fluids Storage/Treatment study/design
Apply Dust Palliative	Dozer
Apron reconstruction stage I	Expand GA Runway stage II
Apron resurfacing phase II	Extend Runway 10/28
Apron resurfacing phase III	Fence perimeter of airfield and Perimeter Roads
ARFF Vehicle	Friction Measuring Trailer
Broom Runway Push	GRAVEL SCREEN PLANT
Construct drainage improvements and a new GA facility	Identify additional lease lots
Construct Fencing	Improved Replacement Schedule and Funding For Maintenance Equipment.
Construct Full Parallel Taxiway	Increase pavement strength to accommodate larger aircraft
Construct gravel Runway 03L /21 R	Increase RSA, ROFA, and ROFZ, runway 10/28
Construct new airport access road	Install 12' Fencing around ARFF Building
Construct New EEB	Install aircraft tie-downs
Construct new GA runway	Install Electronic Access Controls for airfield
Construct parallel taxiway	Install More Fencing
Construct RSA 03/21	Loader
Construct RSA 10/28	Loader
Construct Tie-Downs	Master Plan Update

NOME (OME)

Miscellaneous Building Repair

Need Long-Range Plan for Compatible Uses for Security and Operational Issues

Nome Airport Paving

Pave remaining gravel aprons and TXY's in NE hangar area.

Pavement Markings

Prepare Land Use Plan and Property Acquisition

Preventative Maintenance for 1,711,650 sq. ft. of runway and 489,709 sq. ft. of apron and taxiway pavement

Provide Additional Tie-Downs

Purchase EMAS Broom

Reconstruct Runway 10/28 Subgrade Stage I

Reconstruct Runway 10/28 Subgrade Stage II

Reconstruct Runway 10/28 Subgrade Stage III

Rehabilitate 650,535 sq. ft. apron, taxiway and runway pavement including Runway 10/28

Relocate Snake River

Remove obstructions to Part 77 surfaces and RVZ

Repave Runway 3/21

Replace Existing Loader

Replace Runway 10-28 Lighting

Replace tow behind broom

Restripe 10/28 Runway

Restripe RW 3/21 Markings

Runway 10/28 increase pavement strength

Runway Light Cleaning Plow

Sander

Shorten RW, RSA, ROFA, and ROFZ, lengthen RSA beyond RW ends and RPZ (21L) and RW 03/21L

Snow Blower

Snow Blower

Snow Blower

Storm water management plan

Taxiway D & F Grading

Taxiway G Crack Seal

Terrain Removal / line of sight improvements

Travel Trailer

Utility Wagon

NOME CITY FIELD (94Z)

Runways: 03/21 - 1,950

Surface: GRVL-G

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$12,480.64

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$80,041.87

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Brush Cutting

Dahl Creek Airport improvements

Dahl Creek Airport Lease Lot Development

Install aircraft tie-downs

Install Fencing

Relevel or replace wind cone tower and sock

Replace Cones

Replace Segmented Circle

Survey and Develop more lease lots

Survey and Expand Apron

Update ALP

NONDALTON (5NN)

Runways: 02/20 - 2,800

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$51,161.56

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 11/13/2017

Airfield Manager: CLINT ANELON, 907-571-1261

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0432-002-2003

NEEDS:

Apply Dust Palliative

Construct 500' Runway Extension

Construct Passenger Shelter

Construct Toilet Facilities

Excavate Area North of RW 2/20 and 9/27 Intersection to meet
Line of Sight Standards

Remove Brush

Replace a 1-Bay SREB

Update ALP

NORTHWAY (ORT)

Runways: 05/23 - 5,100

Surface: ASPH-G

Lighting: MED

Classification: Community On-Road

CY16 Enplanements: 3

Borough: Southeast Fairbanks Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$6,955.20

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$70,846.85

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 10/06/2016

Airfield Manager: DENNIS BISHOP, 907-883-5128

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0203-003-1993

NEEDS:

Apply dust palliative

Construct Passenger Shelter

Crack Sealing

Lighting Repairs

RSA Grading on Southside of Runway

SREB Repairs

NULATO (NUL)

Runways: 03/21 - 4,011

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 4,050

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$97,412.43

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 03/26/2014

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, Rehabilitate Apron, Access Road
& RW 2/20
3-02-0204-004-2010

NEEDS:

Apply Dust Palliative

Compactor

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Grader

Install AWOS (Various)

Install VGS (PAPI)

Lighted Supplemental Wind Cone

Survey, Clear Obstructions & Mark Property Boundary

Wx Reporting Needed

NUNAM IQUA (SXP)

Runways: 01/19 - 3,015
09W/27W - 15,000
18W/36W - 15,000

Surface: GRAVEL-F
WATER
WATER

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 2,651

Borough: Kusilvak Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: K-12

FY18 Ops Cost: \$97,599.09

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: JOHN WILSON, (907) 625-1025

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 2/20, Construct TW & Apron
3-02-0262-003-1999

NEEDS:

- Access Road and Causeway Construction
-
- Apply Dust Palliative
-
- Brush Cutter
-
- Brush Cutting
-
- Construct 985' Runway Extension
-
- Construct Passenger Shelter
-
- Construct Tie-Downs
-
- Construct Toilet Facilities
-
- Install ASOS or AWOS
-
- Install VGSI (PAPI)
-
- new ULSD tank
-
- Nunam Iqua Airport Improvements
-
- Regrade, recover D-1 and re-establish crown on runway
-
- Repair/ Replace secondary wind come tower
-
- Repair/Replace Light Can Bases as Needed
-
- Update ALP
-
- Widen and Extend Runway

NUNAPITCHUK (16A)

Runways: 18/36 - 2,420
NE/SW - 3,000

Surface: GRVL-DIRT-G
WATER

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$40,606.71

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/08/2016

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 18/36, Construct SREB
3-02-0446-001-2007

NEEDS:

Airport Access Road Improvements

Apply Dust Palliative

Construct 2 each 24' x 48' SREB (1 heated/1 unheated)

Construct 880' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Installed 2 fuel storage tanks on the aviation support area

New lighting

Reconstruct SREB & Mitigate Tank Spill

Rehabilitate Surfaces

OLD HARBOR (6R7)

Runways: 03/21 - 2,750

Surface: GRAVEL-P

Lighting:

Classification: Community Off-Road

No Enplanements: 0

Borough: Kodiak Island Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$1,379.73

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$14,175.31

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/11/2016

Airfield Manager: BRUCE MCNEIL, 907-487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: Construct RW 2/20, Improve SREB & Access Road, Construct TW & Apron 3-02-0421-001-1992

NEEDS:

-
- Add a GPS Approach Widen the runway to 75'
 -
 - Apply Dust Palliative
 -
 - Brush cutting (M&O OR)
 -
 - clean/organize SREB
 -
 - Construct 550' Runway Extension
 -
 - Construct a New 1-Bay SREB
 -
 - Construct Passenger Shelter
 -
 - Construct Toilet Facilities
 -
 - Extend Power and Light Runway
 -
 - Grader and Loader
 -
 - Install ASOS or AWOS
 -
 - Install MIRL Runway Lighting
 -
 - Install Perimeter Fence
 -
 - Install VGS (PAPI)
 -
 - Reestablish Runway Crown and Compact Surface
 -
 - Remove ROFA Obstructions
 -
 - Replace and Realign Runway Cones
 -
 - Replace Surface Course
 -
 - Replace Windsock
 -
 - Resurface Runway
 -
 - SREB Repairs
 -

OPHIR (Z17)

Runways: 11/29 - 1,940

Surface: GRVL-DIRT-P

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/23/2016

Airfield Manager: STEFFEN STRICK, 907-524-3241

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Gravel surfacing

OUZINKIE (4K5)

Runways: 08/26 - 3,300

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Kodiak Island Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$36,077.45

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/10/2016

Airfield Manager: BRUCE MCNEIL, 907-487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0480-002-2011

NEEDS:

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust control (M&O SPM)

Emergency eye wash station

Grader, loader, snow removal attachments

Install Perimeter Fence

Install VGS (PAPI)

Relocate wind cone

Replace cone bands

supplemental Wind Cone evaluation

Tree Removal

PEDRO BAY (4K0)

Runways: 09/27 - 3,002

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility:

FY18 Ops Cost: \$48,177.31

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 11/13/2017

Airfield Manager: CLINTON ANELON, 907-571-1261

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate & Extend RW 9/27, Install RW Lighting, Acquire Land 3-02-0215-003-1986

NEEDS:

Aeronautical Survey and Remove Part 77 Penetrations

Replace/Repair 1-bay SREB

Apply Dust Palliative

Clean/organize SREB

Clear Vegetation in Runway Safety Areas, and Segmented Circle

Conduct Master Plan

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install Concrete Parking Pads on Apron

Install External Speakers on Equipment

Install VASI and PAPI

Install VGS (PAPI)

Loader and Blower

Purchase fire extinguishers/emergency eye wash station

Regrade Safety Areas

Removal of Debris at Runway End

Remove Old Threshold Panels

Repair Shoulder Erosion on Taxiways and Ramp

Repair SRE Building

Repair/replace light lenses

Replace Runway Edge Cones

PERRYVILLE (PEV)

Runways: 02/20 - 3,300

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$19,767.74

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, RW, & Apron, Modify Access Road
3-02-0218-001-2005

NEEDS:

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Grader

Install AWOS (Various)

PETERSBURG JAMES A JOHNSON (PSG)

Runways: 05/23 - 6,400

Surface: ASPH-G

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 47,618

Borough: Petersburg Borough

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$75,186.59

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$453,132.37

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 08/04/2014

Airfield Manager: BARRY YOUNGBERG, 907-772-4624

Hours of Operation:

APR-SEP/MON-FRI/0600-1630

APR-SEP/SAT-SUN/0830-1630

OCT-MAR/ALL/0500-1600

Last Major Improvement: Rehabilitate & Rehab TW & Apron
3-02-0219-014-2014

NEEDS:

Apron and Taxiway Rehab

Construct Full Parallel Taxiway

Construct Tie-Downs

Construct Toilet Facilities

fuel tank signage/security upgrades

Grader

Mill and pave old portion of Apron

wildlife attractant reduction

PILOT POINT (PNP)

Runways: 07/25 - 3,280

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$250.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$31,211.15

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB
3-02-0222-002-2003

NEEDS:

Apply Dust Palliative

Construct 49' taxiway

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Expand apron

Expand the RSAs

Expand the runway to 5,050' x 100'

Extend existing access road

RSA edges repair

PILOT STATION (OAK)

Runways: 04/22 - 4,000

Surface: GRVL-DIRT-P

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Kusilvak Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$149,618.25

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$102,887.68

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: ERIK WEINGARTH, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0477-002-2017

NEEDS:

Apply Dust Palliative

Construct 1,459' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Expand Ramp

Grader, loader wheel, snow plow, snow removal attachments

Install ASOS or AWOS

Install ULSD Tank

Install VGSI (PAPI)

Loader

Reclaim and Resurface Runway and Safety Area

Relocate Airport

Remove/Replace Threshold Panels

Replace Segmented Circle

Replace SRE Building

Replace Threshold Markers

Resurface Runway

Update ALP

PLATINUM (PTU)

Runways: 14/32 - 5,000

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 997

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$570.59

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$42,948.70

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/18/2017

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, RW, TW, & Apron
3-02-0224-002-2-2009

NEEDS:

Apply Dust Palliative

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Determine if Wildlife Hazard Program is Needed

Develop lease lots

Loader

Miscellaneous SREB Cleanup

POINT BAKER (KPB)

Runways: N/S - 4,000

Surface: WATER

Lighting:

Classification: Local NPIAS Lower

CY16 Enplanements: 78

Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,688.41

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: SCOTT GRAY, (907) 465-4512

Hours of Operation:
DALGT

Last Major Improvement: Acquire Land, Construct Apron
3-02-0423-001-1994

NEEDS:

POINT HOPE (PHO)

Runways: 01/19 - 3,992

Surface: ASPH-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 5,832

Borough: North Slope Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$1,184.93

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$143,493.47

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/05/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0226-003-2000

NEEDS:

- Construct access road
-
- Construct Passenger Shelter
-
- Construct Tie-Downs
-
- Construct Toilet Facilities
-
- crack sealing
-
- Expand TSA
-
- Float Rehabilitation
-
- Fuel Tank Upgrade
-
- Increase the RSA to meet the current design standards.
-
- Pavement maintenance and marking repairs
-
- Pavement Markings
-
- Point Hope Airport Runway Realignment
-
- Realign the runway and increase the length by 8 feet to 4,000 feet.
-
- Rehabilitate Runway Pavement
-
- Replace Segmented Circle
-
- Replace Threshold Markers
-
- SREB Maintenance
-
- Update ALP
-
- Widen taxiway

PORT ALEXANDER (AHP)

Runways: N/S - 3,000

Surface: WATER

Lighting:

Classification: Community Off-Road

No Enplanements: 0

Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility: No

FY17 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY17 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: SCOTT GRAY, (907) 465-4512

Hours of Operation:
UNATNDD

Last Major Improvement:

NEEDS:

PORT GRAHAM (PGM)

Runways: 12/30 - 1,975

Surface: GRVL-DIRT-F

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 3,037

Borough: Kenai Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$20,604.69

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/27/2016

Airfield Manager: KEVIN JONES, 907-235-8872

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Airport brushing

Runway resurfacing

Airport relocation

Construct 1,325' Runway Extension

Construct airport parking apron

Construct new SREB

Construct Passenger Shelter

Construct Toilet Facilities

Drainage Maintenance & Repair

Drainage Maintenance & Repair

Grader

improve drainage around SREB /abandoned vehicle removal

Install ASOS or AWOS

Install AWOS or ASOS

Install MIRL Runway Lighting

Install VGS! (PAPI)

Obstruction Removal

Obstruction Removal

Regrade Runway and Safety Areas

Regrade Runway and Safety Areas

Replace and re-establish runway marking cones

Replace Wind Cone Tower

PORT HEIDEN (PTH)

Runways: 05/23 - 5,000
13/31 - 4,000

Surface: GRAVEL-G
GRAVEL-G

Lighting: MED
MED

Classification: Community Off-Road

CY16 Enplanements: 1,355

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$20,096.98

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$70,605.35

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 5/23 & 13/31, Construct RSAs
3-02-0234-004-2003

NEEDS:

Airport has known contamination issues from DOD activities from WWII.

Construct additional lease lots

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Grader

Loader Wheel and Aviation Radio

Update ALP

PORT LIONS (ORI)

Runways: 07/25 - 2,200

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 1,435

Borough: Kodiak Island Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$36,735.91

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/10/2016

Airfield Manager: BRUCE MCNEIL, (907) 487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW Lighting 7/25 Regulator Building
3-02-0235-004-2011

NEEDS:

Brush cutting (M&O OR)

Construct 1,100' Runway Extension

Construct a new, heated 2-bay SREB

Construct apron and taxiway

Construct Passenger Shelter

Construct Toilet Facilities

Dust control (M&O SPM)

Erosion control, improved drainage, brush cutting

Expand RPZ

Grader and Loader

Install new lighting system, rotating beacon, PAPIs, and REILs

Install Perimeter Fence

Install VGS1 (PAPI)

Install wind cones, modify utilities, and update lease lots

Land acquisition (5 parcels)

Obliterate old access road

Obstruction removal

Realign and extend Runway

Reconstruct or relocate airport

Reconstruct or relocate airport access road

Remove 20:1 ground penetrations and tree obstructions on

RWY 7 approach

Repair/replace runway lights.

replace segmented circle

Replace threshold cones with updated markers

Resurface Runway

Resurface/pave runway

Rotate the airport

Update ALP

PORT PROTECTION (19P)

Runways: NW/SE - 4,000

Surface: WATER

Lighting:

Classification: Community Off-Road

No Enplanements: 0

Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: SCOTT GRAY, (907) 465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Conduct Master Plan

PORTAGE CREEK (A14)

Runways: 01/19 - 1,470
10/28 - 1,920

Surface: GRVL-DIRT-G
GRVL-DIRT-F

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Dillingham Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$15,834.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: NORMAN HAYANO, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 1/19, TW & Apron, Construct RW
9/27, Improve SREB, Remove Obstructions
3-02-0348-001-1984

NEEDS:

Construct 2-bay heated SREB

Erosion Control and Stability Control

FY'19 Replace seaplane float

Grader

Grader & loader with attachments

Loader

Minor Gravel Resurfacing

Obstruction Removal

Purchase Aviation Radios

Reclaim existing 1-bay SREB

Remove RSA, OFZ, OFA, TSS Obstructions

Renew MLT Airport Lease

Repair Erosion on Both Runway Edges

Resurface and apply dust palliative to runway, taxiway, and
apron

PROSPECT CREEK (PPC)

Runways: 01/19 - 4,968

Surface: GRVL-G

Lighting: MED

Classification: Local NPIAS Lower

CY16 Enplanements: 724

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: None

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road:

Last CIMP Inspection Date:

Airfield Manager: RENIER SWART, (907) 787-8959

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Obstruction removal (O+M Operating)

QUARTZ CREEK (JLA)

Runways: 04/22 - 2,200

Surface: GRVL-DIRT-G

Lighting:

Classification: Local Non-NPIAS

CY15 Enplanements: 0

Borough: Kenai Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: KG-12

FY18 Ops Cost: \$288.83

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 11/01/2017

Airfield Manager: SEAN MONTGOMERY/CARL HIGH, 907-262-2199

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Additional tie-downs

Brush Cutting/Tree removal

QUARTZ CREEK /KOUGAROK/ (5QC)

Runways: 12/30 - 2,960

Surface: GRVL-DIRT-G

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$800.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/12/2017

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Apply Dust Palliative

Replace Faded Cones/Markers

Verify Sublease Situation

Wildlife Mitigation

RALPH M CALHOUN MEMORIAL (TAL)

Runways: 07/25 - 4,400

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 6,263

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,272.06

USPS Hub: No

School Facility: K - 12

FY18 Ops Cost: \$90,069.74

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/25/2014

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 7/25, Construct SREB, Extend
RSA, Expand Apron
3-02-0290-002-2004

NEEDS:

Compactor

Construct Passenger Shelter

Construct Tie-Downs

Dust Pallative

install a light on Beacon tower

Install external speaker on equipment

Loader

Purchas a portable eye wash station

Replace Fuel Storage Tank and Enhance Security Measures

Snow Blower, Grader and Loader Wheel

Supplemental Wind Cone

Survey, Clear obstructions and Mark Property Boundary

RAMPART (RMP)

Runways: 11/29 - 3,520

Surface: GRAVEL-G

Lighting: MED

Classification: Local NPIAS Lower

CY16 Enplanements: 603

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility:

FY18 Ops Cost: \$117,142.36

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Expand Apron, Rehabilitate RW
3-02-0244-003-2-2001

NEEDS:

Compactor

Grader

Lighted Supplemental Wind Cone

Loader

PAPI, WX Reporting & WX Cameras Needed

Rehabilitate airport for all-season operations, including runway
surface repairs and vegetation clearing.

SRE Building Replacement

Survey, Clear Obstructions and Mark Property Boundary

RED DEVIL (RDV)

Runways: 10/28 - 4,820

Surface: GRVL-F

Lighting:

Classification: Local NPIAS High

CY16 Enplanements: 152

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$618.63

USPS Hub: Yes

School Facility:

FY18 Ops Cost: \$58,224.85

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/19/2018

Airfield Manager: RICHARD CILETTI, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: Remove Obstructions, Construct SREB
3-02-0246-001-2005

NEEDS:

Construct a new taxiway and apron

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dozer

Dust Control

Grader

Install ASOS or AWOS

Install MIRL Runway Lighting

Install VGSI (PAPI)

Obstruction Removal

Update ALP

ROBERT/BOB/CURTIS MEMORIAL (D76)

Runways: 06/24 - 4,000

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$72,081.37

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/06/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0201-004-2001

NEEDS:

Construct access road

Construct Lease area

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Expand RSA, ROFA, & ROFZ

Extend Runway

Install one or two apron concrete parking pads

Install RCO

Lighted Supplemental Wind Cone and Segmented Circle

new lighted wind cone

Noorvik Airport Rehabilitation

Noorvik SRE Building Replacement

papi Repair

Repair/Replace Overhead Doors

Replace Fire Extinguisher

Shoulder/slope repairs

Update ALP

RUBY (RBY)

Runways: 03/21 - 4,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 3,435

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$114,204.70

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/25/2015

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 3/31, Expand Apron, Install RW Lighting, Rehabilitate TW 3-02-0248-001-1992

NEEDS:

Apply Dust Palliative

Brush Cutter

Clean up SREB interior and exterior

Clear Vegetation Around Airport

Compactor

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Fuel Tank Upgrade

Install PAPI and AWOS

Install Supplemental Wind Cone

Purchase compactor attachment

Regrade Runway and Safety Areas

Rehabilitate SRE Building

Relocate Road, Improve Approach, and Protect Safety Areas

Remove Unknown Barrels

Resurface Runway

Re-Surface Runway, Apron and Taxiway, Apply Dust Palliative, and Upgrade Airport Lighting System

Update ALP

RUSSIAN MISSION (RSH)

Runways: 17/35 - 3,620
18W/36W - 3,000

Surface: GRAVEL-G
WATER

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 3,845

Borough: Kusilvak Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$90,442.09

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: ERIK WEINGARTH, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Construct RW 17/35
3-02-0249-001-2000

NEEDS:

- 20:1 Clearance
-
- Aeronautical Survey
-
- Apply Dust Palliative
-
- Brush Cutting
-
- Construct Passenger Shelter
-
- Construct Tie-Downs
-
- Construct Toilet Facilities
-
- Dozer
-
- Fire extinguisher and emergency eyewash station replacement
-
- Grader
-
- Grader and Loader
-
- Obstruction Removal
-
- Repair/Renovate SRE Building & Replace Overhead Doors
-
- Repair/Replace PAPI
-
- Replace ULSD Tanks
-
- Replace Windsock Tower
-
- Survey for approach clearance
-
- Update ALP

SALMON LAKE (Z81)

Runways: 15/33 - 2,000

Surface: GRAVEL-G

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/12/2017

Airfield Manager: JOSEPH JOHNSON, 907-443-3431

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Dust Palliative

Install aircraft tie-downs

Install Segmented Circle

Install Updated Threshold Markers

Obtain wind data (crosswind runway needed?)

Relocate Threshold to 1860'

Remove Part 77 obstructions

Remove Road that Provides Direct Access

Replace Cones

Resurface runway, apron and taxiway

Revise ALP for Safety Areas and Ultimate Plan

Signage For "No Admittance"

Surface Safety Areas

Wildlife Hazards

SAND POINT (SDP)

Runways: 14/32 - 5,213

Surface: ASPH-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 6,298

Borough: Aleutians East Borough

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$18,868.51

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$239,881.24

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 02/03/2016

Airfield Manager: HAROLD KREMER, 907-532-5000

Hours of Operation:

JAN - DEC/SUN-SAT/0800-1600

Last Major Improvement: Extend RSA 13/31
3-02-0253-010-2005

NEEDS:

ARFF Vehicle	Perimeter fencing repairs/replacement
-----	-----
BROOM RUNWAY TOWED	Place a fabric type barrier on riprap on the bayside to prevent rock topping runway
-----	-----
Construct a New 2-Bay SRE/ARFF Building	Preventative maintenance on 542,900 sq. ft. apron/taxiway pavement
-----	-----
Construct New Heated Sand Storage Building	Preventative Maintenance on 788,850 sq. ft. runway pavement
-----	-----
Construct Tie-Downs	Re-Grade Runway Surface
-----	-----
Construct Toilet Facilities	Remove Part 77 obstructions from bluffs east of runway
-----	-----
Demo existing Sand Storage Building and construct new Sand Storage and SRE/ARFF buildings	Repaint all airport markings Layout and repair pavement markings on runway, taxiways and apron.
-----	-----
Demolish existing sand storage building and attach freight office build	Repair ponding areas in apron
-----	-----
Grader	RW Rehab and Extension; RSA Embankment and Shore Protection (Phase 1)
-----	-----
Grader	RW Rehab and Extension; Widen/Extend RSA, Pave Access Roads; Replace RW Lighting
-----	-----
Grader	Sander
-----	-----
Install water and sewer for SRE/ARFF building	Snow Blower
-----	-----
Installation of FAA weather cameras	Update ALP
-----	-----
Loader	Utility Wagon
-----	-----
Loader	Vehicle gates with push button electric
-----	-----
Loader wheel and Snow Blower	Widen and extend RSA
-----	-----
Maintain pavement markings and crack seal	

Minor Pavement Repairs	

Part 139 Certification	

SAVOONGA (SVA)

Runways: 05/23 - 4,400

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 6,016

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$189,720.85

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 5/23 & Lighting
3-02-0254-005-2009

NEEDS:

Construct Passenger Shelter

Construct taxiway

Construct Tie-Downs

Construct Toilet Facilities

Expand apron

Expand RPZ

Expand RSA

Improve GPS Approach

Install Lighted Windsock with Segmented Circle

Install PAPI

Savoonga runway repairs

Snow Blower Attachment

Upgrade Building Lighting and Siding

SCAMMON BAY (SCM)

Runways: 10/28 - 3,001

Surface: DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 7,483

Borough: Kusilvak Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$80,106.51

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/16/2017

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB
3-02-0255-002-2003

NEEDS:

Acquire Parcel 4 (East RW End)

Construct 299' Runway Extension

Construct a New 1-Bay SREB

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Elevate Runway

Lighting upgrades

Loader

Minor Gravel Resurfacing

Miscellaneous SREB Cleanup

Repair Erosion Issues (FEMA)

Update ALP

Upgrade Runway Lighting

Visual Aids

SELAWIK (WLK)

Runways: 04/22 - 3,002
09/27 - 2,659

Surface: GRAVEL-G
GRAVEL-G

Lighting: MED
MED

Classification: Community Off-Road

CY16 Enplanements: 5,899

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$86,563.11

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/06/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Improve RSA 3/21, Install RW VGS & Lighting,
Rehabilitated Apron 9/27
3-02-0256-003-19-1998

NEEDS:

Acquire Land RW 3/21 RPZ

Apply Dust Palliative

Brush Cutting

Construct 398' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Extend ROFA for both runways

Install PAPI on west 3/21 & 9-27

New BRL (ALP)

Repair existing 48" culvert

Repair/Replace Wind Cone Tower

Reshape and Re-establish Crown

Selawik SRE Building Upgrade

Update ALP

Widen RSA for both runways

Widen TSA and TOFA

SELDOVIA (SOV)

Runways: 16/34 - 1,845

Surface: GRAVEL-G

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 6,703

Borough: Kenai Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$11,179.56

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$72,720.53

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/26/2015

Airfield Manager: KEVIN JONES, 907-235-8872

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0258-004-2009

NEEDS:

Airport Improvements	Pave runway and apron
Airport surface and drainage repairs	Reconstruct or Relocate Airport
Community served by the AMHS and water taxis.	Rehabilitate access road
Construct 740' Runway Extension	Remove Brush in OFA
Construct Paved Access Road and Sidewalk	Remove Part 77 Encroachments
Construct SREB	Remove runway obstructions
Construct Taxiway	Replace threshold markers
Construct Tie-Downs	Resolve Airport Boundary
Develop Crosswind Runway	Runway cannot be significantly extended. More research to determine if gravel or pavement is safer for this airport.
Electrical and Grading Improvements	
Expand Alpha Apron	
Expand apron alpha	
Expand aviation support area lots	
Expand RSA on approach end of runway 16 to 300'	
Extend city water and sewer to the new SREB	
Improve drainage (M&O SPM)	
Install MIRL Runway Lighting	
Install VGS1 (PAPI)	
Lighting not recommended due to extreme terrain hazards	
Obstruction Removal	
Obstruction Removal	

SEWARD (SWD)

Runways: 13/31 - 4,533
16/34 - 2,289

Surface: ASPH-G
ASPH-G

Lighting: MED

Classification: Community On-Road

CY15 Enplanements: 6

Borough: Kenai Peninsula Borough

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$14,394.63

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$39,632.61

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 06/16/2014

Airfield Manager: KEVIN KNOTEK, (907) 288-2428

Hours of Operation:
UNATNDD

Last Major Improvement: Improve Airport Drainage
3-02-0259-003-1995

NEEDS:

Acquire RPZ and address compatible land use	-----	Master Plan Update
Airfield lighting repairs and security signage	-----	Master Plan Update
Clear Vegetation Around Airport	-----	Painting All Airport Markings
Construct 3-bay SREB	-----	Patching Taxiway A and Apron
Construct a Helipad	-----	Pave All Taxiways
Construct a Regulator Building	-----	Pave and Widen Taxiway A
Construct a SRE Building With Water and Sewer Services.	-----	Pavement Markings
Construct Area Lighting, Public Parking and a Security Fence	-----	Removal of Trees in the Approach Path
Construct New Regulator Building	-----	Remove Cones Around Lights
Construct Sand Storage Facility	-----	Remove Non-Frangible Sign
Construct Tie-Downs	-----	Repair Airport Lighting
Construct Toilet Facilities	-----	Repair or replace nav aids
Crack Seal	-----	Repair Runway Lighting
Drainage work	-----	Repave Apron
Dump Truck w/Sander	-----	Repave Apron
Extend Runway 12/30 and OFZ	-----	Replace threshold markers
Install Crosswind Runway Lights	-----	Replace Wind Sock
Install MIRLS	-----	Runway 12/30 Reconstruction
Install PAPI and REILs on Both Runways	-----	Sand Storage
Install Runway Direction Signs at Runway Ends	-----	Security signage
Land Acquisition	-----	Shift Runway

Widen Runway Safety Area

SHAGELUK (SHX)

Runways: 16/34 - 3,400
18W/36W - 5,000

Surface: GRVL-DIRT-G
WATER

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 1,123

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$50,956.16

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: ERIK WEINGARTH, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 16/34 & Improve SREB
3-02-0370-002-2000

NEEDS:

-
- | | |
|---------------------------------|------------|
| 20:1 Clearance on 16 Approach | Update ALP |
| ----- | |
| Access road erosion repair | |
| ----- | |
| Aeronautical Survey | |
| ----- | |
| Apply Dust Palliative | |
| ----- | |
| Clear Vegetation Around Airport | |
| ----- | |
| Construct Passenger Shelter | |
| ----- | |
| Construct Tie-Downs | |
| ----- | |
| Construct Toilet Facilities | |
| ----- | |
| Dozer | |
| ----- | |
| Grader | |
| ----- | |
| Install ULSD Tank | |
| ----- | |
| Loader | |
| ----- | |
| Raise Runway Embankment | |
| ----- | |
| Reclaim Airport Material | |
| ----- | |
| Relocate Beacon Off of Building | |
| ----- | |
| Repair/Renovate SRE Building | |
| ----- | |
| Repair/Replace Segmented Circle | |
| ----- | |
| Replace Cones | |
| ----- | |
| Replace SRE Building | |
| ----- | |
| Resurface Runway | |
| ----- | |
| Roadway Reconstruction | |
| ----- | |

SHAKTOOLIK (2C7)

Runways: 14/32 - 4,001

Surface: GRVL-DIRT-F

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$67,260.81

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: JOHN WILSON, (907) 625-1025

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0401-001-1998

NEEDS:

Apply Dust Palliative

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install Lighted Windsock

Install PAPIs

Install ULSD Tank

Reclaim and Resurface Runway

Relocate Beacon

Relocate Segmented Circle

Remove vegetation in and around lights.

Repair/Renovate SRE Building

Replace Runway Edge Cones

Replace Wind Cone Tower

Update ALP

SHEEP MOUNTAIN (SMU)

Runways: 05/23 - 2,270

Surface: GRVL-DIRT-P

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$440.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$8,641.98

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/30/2016

Airfield Manager: STEVE BANSE, 907-745-2159

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

CASC

Cone and Marker Repair / Replacement

Construct Parking Apron

Improve Drainage

Install Perimeter Fence

Level the Runway

SHISHMAREF (SHH)

Runways: 05/23 - 4,997

Surface: ASPH-P

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 3,849

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,948.84

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$238,472.66

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/08/2015

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 5/23, Apron, Lighting, & TW
3-02-0404-007-2015

NEEDS:

Airport Resurfacing

Building Improvements

Construct Tie-Downs

Construct Toilet Facilities

Fuel Tank Upgrade

Fuel Tank Upgrades

Improve GPS Approach

Install aircraft tie-downs

Leasing area

Pavement Markings

Rehabilitate Ramp surface

Repair RCO

Replace cones and markers

Replace Segmented Circle and Wind Cone Tower

Shishmaref Airport Erosion Control

Update ALP

SHUNGNAK (SHG)

Runways: 09/27 - 4,001

Surface: GRAVEL-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 4,251

Borough: Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$3,009.13

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$111,035.63

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/07/2015

Airfield Manager: ALVIN WERNEKE, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Install Lighting, Extend TW & RW 9/27, Improve SREB & Access Road
3-02-0265-001-1996

NEEDS:

Brush Cutting

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Regrade RW and Re-establish Crown

Repair/replace cones and or markers

Resurface runway, taxiway and apron

SREB Heavy Maintenance

Update ALP

SITKA ROCKY GUTIERREZ (SIT)

Runways: 11/29 - 7,200

Surface: ASPH-G

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 122,107

Borough: City and Borough of Sitka

Air Carrier Hub: Yes

Medical Facility: Yes

FY18 Revenue: \$57,729.45

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$780,410.76

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 06/29/2015

Airfield Manager: STEVE BELL, 907-966-2960

Hours of Operation:
ALL/ALL/

Last Major Improvement: Install Perimeter Fence
3-02-0268-031-2017

NEEDS:

Construct Full Parallel Taxiway

Crack Seal Apron and Taxiways

Crack seal runway 11/29

FY'16 GA Apron Development (Charcoal Island)

FY'16 Property Acquisition

FY'18 Construct Partial Parallel TWY

FY'18 Expand GA Apron and Lease Lots

Installation of FAA Weather Camera at Bioka Island

Old ARFF building repairs

Sitka Airport Access Road Relocation

Sitka Sand Storage/Dry Chemical Building

SRE Building Replacement

Terminal Modification

Vegetation Management

SKAGWAY (SGY)

Runways: 02/20 - 3,550

Surface: ASPH-G

Lighting: MED

Classification: Community On-Road

CY16 Enplanements: 6,623

Borough: Municipality of Skagway

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$20,390.98

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$31,360.12

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 04/06/2015

Airfield Manager: MISSY TYSON, 907-983-2323

Hours of Operation:
UNATNDD

Last Major Improvement: Construct TW 3-02-0270-006-2003

NEEDS:

Brush Cutting on RSA 2/20

Construct SRE Building

Construct Tie-Downs

Crack Seal Pavement

Exterior Paint

Install Segmented Circle

Install VGS1 (PAPI)

Land Acquisition

Repaint Markings

Repair Terminal Building

Repair/Replace HVAC

Repair/Replace Wind Cone

Replace Airport Lighting System

replace fencing

Replace REIL

Replace Terminal Flooring

SKWENTNA (SKW)

Runways: 10/28 - 3,400

Surface: GRAVEL-G

Lighting: MED

Classification: Local NPIAS Lower

CY16 Enplanements: 64

Borough: Matanuska-Susitna Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$2,783.95

USPS Hub: No

School Facility:

FY18 Ops Cost: \$81,726.78

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/07/2016

Airfield Manager: STEVE BANSE, (907) 745-3117

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 9/27, Install RW Lighting, Improve Access Road, Rehabilitate RW, Construct TW & Apron
3-02-0411-001-1987

NEEDS:

Cone and Marker Repair / Replacement

Construct 2-bay SREB

Construct a new two-bay SREB

Embankment protection needed

Erosion

FY'14 ARFF Truck

Move the existing maintenance shop and generator

Provide a 10k generator for lighting

Replace threshold markers

Segmented Circle

Snow Blower

Tree removal (M&O OR)

Upgrade airport lighting

SLEETMUTE (SLQ)

Runways: 14/32 - 3,100

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 418

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$38,478.41

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/19/2018

Airfield Manager: RICHARD CILETTI, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Brush Cutting

Construct 2-bay SREB

Construct new access road

Construct new apron and taxiway

Construct Passenger Shelter

Construct Toilet Facilities

Grader

Gravel Resurfacing

Install VGSI (PAPI)

Loader w/LDMT snow blower

Minor Gravel Resurfacing & Dust Control

Obstruction Removal

Sleetmute Test Airport Runway Resurfacing

Update ALP

SOUTH NAKNEK NR 2 (WSN)

Runways: 05/23 - 2,264
13/31 - 3,314

Surface: GRVL-DIRT-F
GRVL-DIRT-F

Lighting: HIGH
HIGH

Classification: Local NPIAS Lower

CY16 Enplanements: 433

Borough: Bristol Bay Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$28,291.24

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/15/2014

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Construct RW 12/30 & TW, Install
Lighting, Expand Apron, Rehabilitate RW 17/35
3-02-0186-001-1996

NEEDS:

Repair and extend lighting system

Repair RSAs

South Naknek Runway

STEBBINS (WBB)

Runways: 05/23 - 2,999

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 5,734

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$47,626.41

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: JOHN WILSON, (907) 625-1025

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Install RW Lighting, Extend RW
5/23, Construct Apron
3-02-0279-001-1995

NEEDS:

Apply Dust Palliative

Construct 1,001' Runway Extension

Construct SREB

Construct Tie-Downs

Construct Toilet Facilities

Expand/Widen Runway, Expand Apron and Taxiway, Reduce
Obstructions, and Apply Dust Palliative.

Grader

Install ASOS or AWOS

Install VGSI (PAPI)

Loader

New ULSD Tank

Repair Airport Lighting

Repair/Renovate SRE Building

Repair/Replace Wind Cone Photo Cell

Replace Runway Edge Cones

Replace Segmented Circle

Replace Wind Cone Tower

Update ALP

STEVENS VILLAGE (SVS)

Runways: 05/23 - 4,000

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 689

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility:

FY18 Ops Cost: \$102,732.41

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 06/26/2017

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport & SREB
3-02-0444-002-2005

NEEDS:

Brush Clearing

Compactor

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Drainage Improvements

Dust Palliative Application

Fuel Tank Upgrades

Grader

Install ASOS or AWOS

Lighted Supplemental Wind Cone

Replace Fuel Storage Tank and Enhance Security Measures

Replace MIRL

Stevens Village Airport Lighting & Resurfacing

Survey, Clear Obstructions, and Mark Property Boundary

WX Reporting Needed

STONY RIVER 2 (SRV)

Runways: 18/36 - 2,601

Surface: GRVL-DIRT-F

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 160

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$35,775.61

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/19/2018

Airfield Manager: RICHARD CILETTI, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Acquire Parcels 1-3 and 8-10.

Airport requires lease lot acquisition

Brush Cutter

Construct 2-bay SREB

Construct 699' Runway Extension

Construct a Separated Apron and Taxiway

Construct Passenger Shelter

Construct Temporary Equipment Building

Construct Toilet Facilities

Dozer

Erosion

Floatplane dock

Grader

Grader and Dozer

Improve drainage by runway

Install ASOS or AWOS

Install VGSI (PAPI)

Master Plan update

Obstruction Removal

Resurface Runway

SUMMIT (UMM)

Runways: 03/21 - 3,814

Surface: GRAVEL-G

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, 907-451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

TAKOTNA (TCT)

Runways: 04/22 - 3,300

Surface: GRAVEL-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 289

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$62,039.03

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/23/2016

Airfield Manager: STEFFEN STRICK, 907-524-3241

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0472-001-2009

NEEDS:

Building Repairs - Repair Leaking Roof Above Man Door

Construct 700' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Gravel Repairs

Install VGS1 (PAPI)

Repair Broken and Missing Lighting, Signs, & Cones

Runway Cracking Repair

TALKEETNA (TKA)

Runways: 01/19 - 3,500

Surface: ASPH-G

Lighting: MED

Classification: Community On-Road

CY13 Enplanements: 3

Borough: Matanuska-Susitna Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$84,931.40

USPS Hub: No

School Facility: PK - 6

FY18 Ops Cost: \$117,298.47

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 06/19/2014

Airfield Manager: STEPHEN HANSON, 907-733-2278

Hours of Operation:

APR-NOV/MON-THU/1500-0130

DEC-MAR/SUN-SAT/1500-0130

Last Major Improvement: Construct TW & Apron, Rehabilitate RW 18/36 & TW, Remove Obstructions, Acquire Land 3-02-0287-005-2016

NEEDS:

Aeronautical Survey

SRE Dump Truck

Airport Paving and Improvements

Vegetation Control

Apron Lease Lot Development and Flood Mitigation

Vehicle gates with push button electric

Beacon

Wind Cone Pole

Construct Toilet Facilities

Crack Seal

Crack Seal Pavement

Drainage Maintenance & Repair

Expand Maintenance Facility

Expand Maintenance Facility

Fencing

Install Pedestrian trail and signage

Mower

Pavement Markings

Plow Truck

Purchase Fire Extinguishers

Regrade Surfaces and Repair Airport Lights

Renovate Drains in M&O Shop

Re-Paint All Markings

Replace Airport Lighting

Replace Cones Around Lights

TATITLEK (7KA)

Runways: 13W/31W - 8,000
13/31 - 3,701

Surface: WATER
GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$78,107.29

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: STEVE SEARLES, 907-835-5658

Hours of Operation:
UNATNDD

Last Major Improvement: Improve Building & Access Road, Extend TW, RW
12/30, & Apron, Install RW Lighting
3-02-0342-002-1995

NEEDS:

Brush Cutter

Construct 299' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install ASOS or AWOS

Install VGS1 (PAPI)

Tatitlek SRE Building Replacement

Update ALP

TAZLINA (Z14)

Runways: 13/31 - 1,200

Surface: GRAVEL-G

Lighting:

Classification: Local Non-NPIAS

No Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

TED STEVENS ANCHORAGE INTL (ANC)

Runways: 07L/25R - 10,600
07R/25L - 12,400
15/33 - 10,960

Surface: ASPH-G
ASPH-CONC-E
ASPH-G

Lighting: HIGH
HIGH
HIGH

Classification: International

CY16 Enplanements: 2,521,076

Borough: Municipality of Anchorage

Air Carrier Hub: Yes

Medical Facility: Yes

No Revenue: \$0.00

USPS Hub: No

School Facility: PK-12

No Ops Cost: \$0.00

Part 139 Cert: Yes

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: JIM SZCZESNIAK, 907-266-2525

Hours of Operation:
ALL/ALL/ALL

Last Major Improvement:

NEEDS:

Additional runway widening and taxiway widening to meet
DGVI standards

Pavement maintenance including runway and taxiway rehab

Regular planned vehicle fleet replacement

TELLER (TER)

Runways: 07/25 - 2,983

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$95,025.11

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/08/2015

Airfield Manager: JOSEPH JOHNSON, 907-443-3431

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 7/25
3-02-0333-002-1999

NEEDS:

Construct 417' Runway Extension

Construct Access Road

Construct New Segmented Circle and Lighted Wind Cone

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust Pallative

Fuel Tank Upgrade

Grader

Improve GPS Approach

Install aircraft tie-downs

Install VGS1 (PAPI)

Lease Area and Lots

Refurbish Runway and lights

Repair Airfield Lighting

Replace cones

Teller Airport Runway Extension and Crosswind Runway
Construction

Teller SRE Building Replacement

Update ALP

Wildlife hazard mitigation

TENAKEE (TKE)

Runways: E/W - 10,000

Surface: WATER-F

Lighting:

Classification: Community Off-Road

CY16 Enplanements: 1,457

Borough: Hoonah-Angoon Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: K - 12

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: SCOTT GRAY, (907) 465-4512

Hours of Operation:

ALL/ALL/DALGT

Last Major Improvement: Rehabilitate SPB
3-02-0295-001-2005

NEEDS:

TETLIN (3T4)

Runways: 08/26 - 3,300

Surface: GRAVEL-G

Lighting: MED

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Southeast Fairbanks Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$27,819.45

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 10/06/2016

Airfield Manager: DENNIS BISHOP, 907-883-5128

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0467-002-2004

NEEDS:

Brush Cutting

Replace Primary Wind Cone Light

TOGIAK (TOG)

Runways: 03/21 - 4,400
10/28 - 982

Surface: GRVL-DIRT-G
GRVL-DIRT-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 1,438

Borough: Dillingham Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$6,312.49

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$36,177.77

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/15/2015

Airfield Manager: NORMAN HEYANO, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0402-001-2016

NEEDS:

3 CY LOADER WHEEL

Add two 3,000 gallon double wall fire rated fuel tanks; one with fuel dispenser

Clear and Repair Segmented Circle

Construct a new crosswind runway

Construct a separate electrical enclosure

Construct Tie-Downs

Construct Toilet Facilities

Dust Control

Extend OFA for RW 10-28

Extend RSA

Fix Part 77 obstructions

Install PAPI

Install Perimeter Fence

Loader

Minor Gravel Resurfacing

Obstruction Removal

Pave Runway 03/21

Pave taxiway and apron

Placards for fuel tank

Regrade Airport and Re-establish Crown

repair/replace wind cone tower

Replace Electrical Lighting Vault and Transformer

Replace Existing 2-Bay SREB with Heated 2-Bay SREB and Rotating Beacon

Replace faded light globes/ repair lighting

Replace the Airport Lighting

Replace/repair Threshold Markers

Resurface gravel runways, taxiways, and apron

Snow Blower

SREB repairs

Togiak Airport Improvements

Update ALP

Visual Aids

TOK JUNCTION (6K8)

Runways: 07/25 - 2,509

Surface: ASPH-G

Lighting: MED

Classification: Community On-Road

No Enplanements: 0

Borough: Southeast Fairbanks Census Area

Air Carrier Hub: Yes

Medical Facility: Yes

FY18 Revenue: \$16,241.63

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$16,559.43

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 07/31/2017

Airfield Manager: DENNIS BISHOP, 907-883-5128

Hours of Operation:

ALL/MON-FRI/0800-1800

Last Major Improvement: Construct Apron & TW
3-02-0412-002-1999

NEEDS:

Construct 1,491' Runway Extension

Construct Tie-Downs

Crosswind Runway Construction

Install AWOS (Various)

Install VGSI (PAPI)

SNOW BLOWER

Tok Runway Extension

Update ALP

TOKSOOK BAY (OOK)

Runways: 16/34 - 3,218

Surface: GRVL-F

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 7,875

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$3,415.48

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$32,269.11

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/08/2016

Airfield Manager: LAWRENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0441-001-2001

NEEDS:

Build up the airport access road and resurface, associated utility and NAVAID modification

Construct a 1-bay heated SREB with floor

Construct a 1-Bay SREB

Construct a new gravel crosswind runway

Construct a new RSA

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Grader

Gravel Resurfacing

Loader

Rehabilitate the Runway & Add Needed Surface Course

Repair soft spot/rebuild taxiway

Repair Windsock Tip Down Mechanism

Taxiway repair

Visual Glide Slope Indicator Lighting Replacement

TULUKSAK (TLT)

Runways: 15/33 - 3,300

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 3,514

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: K - 12

FY18 Ops Cost: \$41,487.58

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/20/2014

Airfield Manager: LAWERENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0484-002-2009

NEEDS:

Apply Dust Palliative

clean and organize building

Clean up abandoned materials

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust Control

install external speakers on equipment

Install VGSI (PAPI)

Master Plan Update

Repair / Replace Concrete Floors in SREB

Scarify, reshape and recompact runway, taxiway and apron

TUNTUTULIAK (A61)

Runways: 02/20 - 3,025

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$39,030.34

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/08/2016

Airfield Manager: LAWERENCE DAVIS, (907) 543-2498

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0303-002-2006

NEEDS:

Apply Dust Palliative

Beacon

Construct Tie-Downs

Construct Toilet Facilities

Install VGSI (PAPI)

Loader

Maintenance & Erosion

Repair Windssock

Scarify, reshape, and recompact runway, taxiway, and apron
surface (M&O SPM)

SREB Safety

Update ALP

TUNUNAK (4KA)

Runways: 16/34 - 3,300

Surface: GRAVEL-F

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Bethel Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$43,801.03

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 08/18/2017

Airfield Manager: LAWRENCE DAVIS, 907-543-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport
3-02-0486-002-2013

NEEDS:

Build a new SREB (in design)

Construct 1,522' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Expand apron

Install AWOS (Various)

Install VGS (PAPI)

Install Weather Cameras

Minor Gravel Resurfacing

Miscellaneous SREB Cleanup

TWIN HILLS (A63)

Runways: 18/36 - 3,000

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 40

Borough: Dillingham Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 8

FY18 Ops Cost: \$29,965.45

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/15/2015

Airfield Manager: NORMAN HEYANO, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Install RW Lighting, Improve Access Road, SREB,
& RSA 1/19, Construct TW & Apron, Acquire Land
3-02-0356-001-1994

NEEDS:

Add distance between airport and waste facilities

replace wind cones

Add two 3,000 gallon double wall fire rated fuel tanks; one with
fuel dispenser

SREB

beacon access

Brush Cutting (M&O OR)

Construct Additional Heated 1-Bay SREB and Rotating
Beacon

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Dust Control

Grader

Grader & Loader with Attachments

Install ASOS or AWOS

Install MIRL, and REILs

Install VGS! (PAPI)

Loader

Minor Gravel Resurfacing

Overhead door repairs

Relevel wind cone tower

Repair Airfield Lighting

replace fuel tank placards

UGASHIK (9A8)

Runways: 06/24 - 3,100

Surface: GRAVEL-G

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$8,967.75

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: PAUL HANSEN, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Add distance between airport and waste facilities

Construct Tie-Downs

Grader

Identify Pad and Install AWOS

Install MIRL, and PAPIs or REILs

Remove ROFA obstructions

UMIAT (UMT)

Runways: 06/24 - 5,583

Surface: GRVL-DIRT-P

Lighting:

Classification: Local Non-NPIAS

CY16 Enplanements: 81

Borough: North Slope Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$27,873.47

USPS Hub: No

School Facility:

FY18 Ops Cost: \$8,827.87

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: TOM WILLIAMS, (907) 451-5280

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Airfield lighting installation

Construct SREB

Construct Tie-Downs

Grader

Identify Pad and Install AWOS

Lighting Repairs

PAPI, WX Reporting & WX Cameras Needed

Umiat Airport Lease Lot Development

UNALAKLEET (UNK)

Runways: 15/33 - 5,900
09/27 - 1,900

Surface: ASPH-G
ASPH-G

Lighting: HIGH
MED

Classification: Regional

CY16 Enplanements: 18,199

Borough: Nome Census Area

Air Carrier Hub: Yes

Medical Facility: No

FY18 Revenue: \$26,021.97

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$636,018.24

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/26/2017

Airfield Manager: JOHN WILSON, (907) 625-1025

Hours of Operation:
ALL/MON-FRI/0800-1600

Last Major Improvement: Construct SREB
3-02-0309-005-2009

NEEDS:

Concrete repair or replacement

Construct Full Parallel Taxiway

Construct Tie-Downs

Dozer

Fencing

Fuel Tank Upgrades

Grader

Grooves

Install snow fence

Lease lot compliance

Pavement Markings

Power overhead doors

Rehabilitate Runway 8/26

Repaint Runway Markings

Resurface taxiway

Slip resistant coating on painted floor.

UNALASKA (DUT)

Runways: 13/31 - 4,500

Surface: ASPH-F

Lighting: MED

Classification: Regional

CY16 Enplanements: 31,700

Borough: Aleutians West Census Area

Air Carrier Hub: Yes

Medical Facility: Yes

FY17 Revenue: \$58,461.44

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$619,922.62

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 09/23/2015

Airfield Manager: DALE RUCKMAN, 907-581-1786

Hours of Operation:

ALL/ALL/0800-1630

Last Major Improvement: Construct SREB & Sand Storage
3-02-0082-015-2015

NEEDS:

Access Road Improvements

Correct power plant hill

Acquire Land

Deicer truck

Airfield Earthwork/Construction

Embankment Protection at Center Southside RW

Airfield/Roadway Improvements

Environmental analysis

Airport ramp B repairs

Extend OFZ

Apron A repairs

extend ROFA 284'

Apron Improvements

Extend ROFA 300'

ARFF bunker gear

Extend RSA 200'

ARFF SCBA compressor

Extend RSA 400'

ARFF water rescue access

Fence and Gate Repair

Badging computer, software upgrade and printers

Maintain crack seal

Building Demolition to Clear OFA

Maintain pavement markings (M&O SPM)

Cargo Building Improvements

Master Plan Update

Construct 900' Runway Extension

Misc Site Improvements

Construct additional lease lots

Move residential trailers off airport property

Construct Blast Pad

New Beacon Tower

Construct Boat Launch Ramp for Emergency Response

New tow broom

Construct Full Parallel Taxiway

Parking Improvements

Construct new buildings

Pave road by Ramp A gate

Construct Tie-Downs

Pave RSA

Correct Mt. Ballyhoo

Perimeter fencing and gate repairs/replacement

UNALASKA (DUT)

Reclaim Land

Reconstruction of Demolished Buildings

Rehabilitate pavement (hangar/terminal apron, txwy A)

Rehabilitate the SREB

Rehabilitate WWII Hangar

Relocate Service road

Relocated/Modify Facilities to Clear OFA

Remove Buildings

Remove existing guard rail

Remove part of east front road

Remove traffic control signals

Repair Apron B

Repair/replace rusted doors and siding.

Replace 3 drive through gates and 3 pedestrian gates

Replace 4,600' of 8' fence, 150' of 4' fence

Terminal Building Improvements

Toe of Fill

Unalaska Chemical Storage & SRE Building Rehab

Unalaska Mower Replacement

Unalaska Ramp A Repair

Unalaska Ramp B Repair

Unalaska Torpedo Bldg Demo & Clean Up

Vehicle gates with electronic swipe capability

VALDEZ PIONEER FIELD (VDZ)

Runways: 06/24 - 6,500

Surface: ASPH-G

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 12,664

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$122,739.10

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$969,945.58

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 09/06/2016

Airfield Manager: STEVE SEARLES, 907-835-5658

Hours of Operation:

MAY-SEPT/ALL/0700-1830

OCT-APR/ALL/0600-1830

Last Major Improvement: Extend RSA 6/24
3-02-0311-008-2007

NEEDS:

Add a GPS or RNAV Approach

Towed Runway Broom with Plow 22'+ width

Airport Operations Vehicle

Truck Plow Airport

ARFF building heavy maintenance

Valdez Airport Security Upgrades

ARFF Vehicle

Weather Reporting Equipment Upgrade

Broom Runway Push

Construct Tie-Downs

Handicap Pass Loader

Install thaw pipes

Repair roofing

Replace Existing SREB Annex

Replace fuel tanks

Replace SREB

Replace UREA building

Resurface Runway and new lights

Runway Light Cleaning Plow

Sand Shed Storage Addition - Urea

Sand Stacker

Snow Blower

Snow Plow

Snow Wing Truck

Terminal parking area paving

WALES (IWK)

Runways: 18/36 - 3,990

Surface: GRAVEL-G

Lighting: MED

Classification: Community Off-Road

No Enplanements: 0

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$656.44

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$126,788.73

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 10/08/2015

Airfield Manager: JOSEPH JOHNSON, 907-443-3431

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate SREB
3-02-0337-003-2002

NEEDS:

- Acquire land
-
- Building Improvements
-
- Construct Access Road
-
- Construct apron and leasing area
-
- Construct AWSS and Pad
-
- Construct New Segmented Circle and Wind Cone Tower
-
- Construct Passenger Shelter
-
- Construct taxiway
-
- Construct Tie-Downs
-
- Construct Toilet Facilities
-
- Demolish access road
-
- Dust Palliative
-
- Expand RPZ
-
- Fuel Tank Upgrade
-
- Improve GPS Approach
-
- Install aircraft tie-downs
-
- PAPI
-
- Regrade Safety Area patches to remove oversize rock
-
- Rehabilitate Runway Surface
-
- Remove existing taxiway and apron
-
- Replace or remove supplemental cones
-

- Snow Fence Repairs
-
- Wales Airport improvements
-
- Weather Reporting Improvements

WHITE MOUNTAIN (WMO)

Runways: 15/33 - 3,000

Surface: GRVL-DIRT-G

Lighting: MED

Classification: Community Off-Road

CY16 Enplanements: 3,873

Borough: Nome Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$97,212.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 07/25/2017

Airfield Manager: JOSEPH JOHNSON, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: Reconstruct RW 15/33 Lighting, Rehabilitate Apron, TW, Lighting & RW 15/33, Install NAVAIDs & Segmented Circle
3-02-0319-002-2018

NEEDS:

All visual aids

Rotating beacon

Apply Dust Palliative

Update ALP

Construct 1,000' Runway Extension

Wales SRE Building Replacement

Construct Access Road

White Mountain Airport Improvements

Construct apron

White Mountain SRE Upgrade

Construct Passenger Shelter

Widen TSA

Construct Taxiway

Wildlife Mitigation

Construct Tie-Downs

Construct Toilet Facilities

Demolish existing apron

Drainage Improvements

Equipment storage Building & Pad

Expand OFA

Expand RSA

Fuel Tank Upgrades

Improve GPS Approach

Install aircraft tie-downs

Install VGS1 (PAPI)

Lease lots

Lighted Supplemental Wind Cone

Relinquish land

WHITTIER (IEM)

Runways: 04/22 - 1,480

Surface: GRAVEL-F

Lighting:

Classification: Community On-Road

No Enplanements: 0

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility: PK - 12

FY18 Ops Cost: \$11,955.57

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 10/21/2015

Airfield Manager: PAUL BERTHOLL, 907-783-2232

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Airport master plan

Brush and clear runway and adjacent areas

Construct 1,820' Runway Extension

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install MIRL Runway Lighting

Install VGS (PAPI)

Secure runway

WILLOW (UUO)

Runways: 13/31 - 4,400

Surface: GRAVEL-G

Lighting: MED

Classification: Local NPIAS High

No Enplanements: 0

Borough: Matanuska-Susitna Borough

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$49,448.54

USPS Hub: No

School Facility: K - 12

FY18 Ops Cost: \$115,922.75

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date: 09/02/2015

Airfield Manager: RAY ADAMS, 907-495-6286

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB
3-02-0320-002-1999

NEEDS:

Aircraft Highway Crossing Improvement	NE Airport Lease Lots and Tiedowns
Construct 1-bay SREB	Obstruction Removal
Construct Gravel/Ski Strip	Obstruction Removal
Construct new lighted segmented circle	Perimeter fencing repairs/replacement
Construct Road and Helipad	Property Acquisition
Construct Toilet Facilities	Reassess Removing Displaced Threshold
Cut trees and remove hill by South Taxiway (M&O OR)	Reduce RSA
Expand SREB	Rehabilitation/extension of the existing access road
Expand Tie Down, Road Access, and Taxiway Connection near RW 31	Removal of Part 77 Obstructions
Gate repairs	Remove taxiway
Grader	Replace Runway Lighting System
Heliport RPZ	Resurface Runway
Improve Blind Corner on S. End of Runway	Shift taxiway 90' left
Install barrier fencing behind the floatplane leaseholds	Shot Gun Cove Rd expansion
Install Perimeter Fence	Ski Runway RSA, OFA, & OFZ
Install Perimeter Fence	Snow Blower
Lease Areas	SW Airport Tiedown Expansion
Loader	Taxiway, Road, and Lease Lot Expansion Near RW 13
Loader	Tree Clearing/Fencing/Signage
Minor Gravel Resurfacing & Dust Control	Vehicle gates with push button electric
Minor Gravel Resurfacing & Dust Control	Vehicle Parking

WILLOW (UUO)

Vehicle Parking

Willow Airport Improvements

Willow Automated Weather Observation System (AWOS)

Willow Haven Senior Center Access

WILLOW SPB (2X2)

Runways: 13W/31W - 3,600

Surface: WATER

Lighting:

Classification:

No Enplanements: 0

Borough:

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: RAY ADAMS, 907-495-6286

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Purchase Boat, Replace Buoys

Removal of island on Willow Lake

Transient Floatplane Parking and Dock

Water Level Maintenance Study

WISEMAN (WSM)

Runways: 02/20 - 2,000

Surface: GRAVEL-P

Lighting:

Classification: Local NPIAS Lower

No Enplanements: 0

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

Medical Facility: No

FY18 Revenue: \$0.00

USPS Hub: No

School Facility:

FY18 Ops Cost: \$0.00

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager: JEFF RUSSELL, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Airport master plan

Brushing, and tree clearing.

Develop ALP

Wiseman Airport Access Road Improvements

Wiseman Airport Rehabilitation

WRANGELL (WRG)

Runways: 10/28 - 6,000

Surface: ASPH-G

Lighting: HIGH

Classification: Regional

CY16 Enplanements: 41,363

Borough: City and Borough of Wrangell

Air Carrier Hub: No

Medical Facility: Yes

FY18 Revenue: \$74,152.06

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$433,182.59

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 12/12/2016

Airfield Manager: WILLIAM BLOOM, 907-874-3107

Hours of Operation:

ALL/ALL/0600-1700

Last Major Improvement: Rehabilitate TW & Apron
3-02-0323-014-2015

NEEDS:

Aeronautical Survey

WHA/WHMP Update

Apron Lease Lot Development

Chip seal apron

Construct Dry Storage Building

Construct Full Parallel Taxiway

Construct Parallel Taxiway

Construct Tie-Downs

Construct Toilet Facilities

Expand GA Apron

Install Light Timers and Repair Heater

Install MALSR on Runway 10

Pickup Truck

Rehabilitate Taxiway and Apron

Replace VASIs with PAPIs

RSA Compaction

Runway Broom

Runway Rehabilitation

Self Propelled Runway Broom

Tractor Mower

Tree Removal

Update ALP

YAKUTAT (YAK)

Runways: 02/20 - 6,475
11/29 - 7,732

Surface: CONC-G
ASPH-G

Lighting: HIGH
HIGH

Classification: Regional

CY16 Enplanements: 24,824

Borough: City and Borough of Yakutat

Air Carrier Hub: Yes

Medical Facility: Yes

FY18 Revenue: \$216,643.19

USPS Hub: Yes

School Facility: PK - 12

FY18 Ops Cost: \$718,373.53

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date: 06/30/2014

Airfield Manager: ROBERT LEKANOF, 907-784-3293

Hours of Operation:

ALL/ALL/1700-0400Z WINTER;

Last Major Improvement: RW 11/29 Rehabilitation Phase II
3-02-0327-021-2016

NEEDS:

Airport Perimeter Fence

Brush Cutting

Brush Cutting on RSA 11/29

Construct Full Parallel Taxiway

Construct Tie-Downs

Construct Toilet Facilities

Construct Ultimate Apron

Inspect Fire Extinguisher

Install Emergency Eye Wash Stations in ARFF Building

Install Placards and Signs at Fuel Tank

Obstruction Survey

Obstruction/Tree Removal on Runway 2/20

Pave Glide slope

Pavement repairs

Rehabilitate Runway 11/29

Repair Exterior Light

WHA/WHMP Update