| Site Number | Location | Damage | Status/Initial Action | | | | |
|----------------|--|--|-----------------------|--|--|--|--|
| REGIONAL | | | | | | | |
| SEWARD HIGHWAY | | | | | | | |
| 001 | Tudor to 36th | Rippled Asphalt | SB Fast lane Closed. | | | | |
| 002 | SB OFF RAMP @ DIMOND | WATER ACROSS ROADWAY | Open | | | | |
| 003 | Seward Hwy MP 104-116 | Rock Slide | Open | | | | |
| 004 | Seward - 6 Mile Bridge (615) | Cracking | Open | | | | |
| 005 | Seward Hwy at Dowling - NE Quadrant On Ramp | Asphalt crack | Open | | | | |
| 007 | Seward Hwy @McHugh Creek | Rock/Mud Slide | Open | | | | |
| 008 | RABBIT CREEK BRIDGE (1392) | EASTSIDE 3RD GIRDER CRACKED (LIGHT) | Open | | | | |
| 009 | DIMOND BRIDGE (1325) | BRIDGE CRACKED BOTH SIDES (LIGHT) | Open | | | | |
| 010 | TUDOR BRIDGE (1323) | ADBUTMENT CRACKED BOTH SIDES | Open | | | | |
| 011 | O'MALLEY BRIDGE (1380) | NORTH BASE END CRACKED (LIGHT) | Open | | | | |
| 057 | SB Rabbit Creek Off Ramp | Shoulder subsidence | Open | | | | |
| 060 | SB Dowling On Ramp - SW Quadrant | Horizontal cracks | Open | | | | |
| | G | LENN HIGHWAY | | | | | |
| 012 | Glenn SB Mirror Lake ON ramp | SLOPE FAILURE SIGNIFICANT CRACKING | Closed | | | | |
| 056 | Glenn SB Mirror Lake between OFF/ON ramps | Significant Cracking and speed limiting bump | Closed | | | | |
| 013 | Glenn SB Mirror Lake OFF ramp | Embankment Subsidence | Closed | | | | |

| 051 | Glenn HWY MP 55-58 | Multiple shoulder failures. | One lane is closed | | | | |
|---------------------------------------|---|--|--|--|--|--|--|
| 014 | Glenn HWY MP 58.7 | Longitudinal Shoulder Cracks and Roadway Damage | One lane is closed | | | | |
| 015 | Glenn Parks Interchange (2121, 2119SB, 2120NB) | Slope Failure on Fly over to Palmer. | Open one lane | | | | |
| 016 | NB Eagle River Bridge (2303) | Abutment Damage. Circular slope failure | Inside lane closed | | | | |
| 017 | SB EAGLE RIVER BRIDGE (1341) | DIP AT APPROACH. South edge has significant bump | Inside lane closed from bridge to Hiland | | | | |
| 048 | Near Glenn SB - Old Glenn @ Palmer WB Off Ramp | Slope subsidence. Longitudinal cracks along | Open | | | | |
| 018 | Moose River Bridge (0541) | Inspecting | Open | | | | |
| 019 | Kings River Bridge (0544) | Vertical displacement at joint | Open | | | | |
| 020 | Chickaloon Bridge (0545) | Cracking at headwall | Open | | | | |
| 021 | Purinton Creek Bridge (0546) | Small cracks | Open | | | | |
| 022 | MP 68.5 NB | Longitudinal cracks on shoulder and roadway | Open | | | | |
| 023 | Glenn South of Birchwood | Hightower Light Fixture Fell on road | Open | | | | |
| 024 | Bragaw Bridge (2209) | CRACKED RETAINING WALL | Open | | | | |
| 050 | SB N Peters Creek Off Ramp | Potential for Embankment Subsidence | Open | | | | |
| | P | ARKS HIGHWAY | | | | | |
| 043 | Seward Meridian Bridge (1989) | Cracks | Open | | | | |
| 054 | Parks Hwy NB Mile Point 52.4 | Asphalt Cracks | Open | | | | |
| STERLING HWY | | | | | | | |
| 025 | MP 82 Bridge (0672) | Cracking | Open | | | | |
| ANCHORAGE | | | | | | | |
| MINNESOTA & INTERNATIONAL INTERCHANGE | | | | | | | |

| 026 | SB Off / On Ramp | Slope Subsidence. MSE Wall sunk but stable | Open | | | | |
|-----------------------------------|--|---|--------------------|--|--|--|--|
| 027 | NB On Ramp | Slope Subsidence | Open | | | | |
| | | | | | | | |
| | MINNESOTA DR | | | | | | |
| 028 | Minnesota Bridge @ 100th (1603/1695) | Bridge Cracks | Open | | | | |
| 029 | Frontage Road from 100th to Dimond - Humphrey Road | Slope Subsidence | Open | | | | |
| | C STREET | | | | | | |
| 030 | SB @ Dowling Road | Pavement Cracks, 2" DEFLECTION & SPLIT | Turn lanes closed | | | | |
| 031 | C St Undercrossing at Campbell Creek (0971) | Longitudinal concrete wall cracking | Open | | | | |
| 055 | NB East Lane after Campbell Creek Crossing | Noticable Bump in roadway | Open | | | | |
| EAGLE RIVER LOOP ROAD | | | | | | | |
| 032 | BRIGGS BRIDGE PEDESTRIAN UNDER CROSSING (7020) | CULVERT STRUCTURE COMPROMISED BY WATER MAIN. 2nd main damaged | CLOSED | | | | |
| 033 | BRIGGS BRIDGE OVER EAGLE RIVER (1739) | SB EXPANSION JOINT BOTH SIDES. N Abutment | CLOSED | | | | |
| A & C Couplet Port Access Bridges | | | | | | | |
| 034 | GENERAL (455) | EXPANSION JOINT AND PILLAR CONCERNS | Open | | | | |
| GENERAL | | | | | | | |
| 035 | DOWLING WB ELMORE-LAKE OTIS | SLUMPING 12-18 inches | LANE CLOSED BY M&O | | | | |
| 064 | SB Old Glenn Hwy North of Fire Lake | Longitudinal cracks 2-3" wide | Open | | | | |
| 053 | 36th and Muldoon Road Pedestrian Overcrossing (1801) | Crack in brace and pathway pavement | Open | | | | |

| 058 | Jewel Lake Road south of Raspberry Road | Transverse and longitudinal cracking | Open | | | | |
|--------------------|---|---|----------|--|--|--|--|
| 059 | Jewel Lake Road east of airport runway | 1" vertical asphalt displacement | Open | | | | |
| 061 | Eagle River Road Near Prudhoe Bay Road | Backslope sloughing | Open | | | | |
| 062 | VFW Road Eagle River | Backslope sloughing and asphalt cracking | Open | | | | |
| 065 | Aircraft Drive and Vought Cir | Damaged taxiway pavement | Open | | | | |
| | MATSU | | | | | | |
| 036 | Clark-Wolverine Road MP 5.5 | Slope Subsidence | One Lane | | | | |
| 038 | Vine Road MP 2.5 | State Road OK | Closed | | | | |
| 039 | Buffalo Mine Road | Longitudinal Shoulder Cracks. Damaged guardrail. | Open | | | | |
| 040 | KGB Road MP-15.2 | Cracks in road. Sinking center and shoulder. | Open | | | | |
| 041 | KGB Road MP-14.7 | SUBSIDENCE 4" MAYBE CULVERT | Open | | | | |
| 042 | Fairview Loop @ Jackfish | Shoulder Separation 2-10" | Open | | | | |
| 044 | PITTMAN RD MP 0.7 | SUBSIDENCE/SINK HOLE | ONE LANE | | | | |
| 052 | Palmer-Wasilla Highway just E of Shenandoah Dr | 1" crack | OPEN | | | | |
| 063 | Willow-Fishhook Road MP 44 | Asphalt Cracking | OPEN | | | | |
| KENAI | | | | | | | |
| Kenai Spur Highway | | | | | | | |
| 045 | MP 19 | Settlement | Open | | | | |
| 046 | MP 35.1 | Settlement | Open | | | | |
| 047 | MP 35.7 | Settlement | Open | | | | |
| | • | | | | | | |