

APPENDIX A
PHOTOS



Photo 1: View north across Lake Harriet Hunt to the Harriet Hunt Ridge



Photo 2: View north across Wolf Valley to Wolf Lake.



Photo 3: View northeast across Wolf Valley. Wolf Mtn at center



Photo 4: Shallow alpine muskeg at the top of Harriet Hunt Ridge.




Photo 5: Shallow alpine muskeg deposits at the top of Harriet Hunt Ridge.



Photo 6: Probing deep muskeg deposits in Heckman Lake Valley



Photo 7: Deep muskeg terrain in Wolf Valley



Photo 8: Steep hillside with mixed bedrock and shallow colluvium along the north slope of Harriet Hunt Ridge.



Photo 9: High, steep colluvium slope above logging roads northeast of Leask Lakes.



Photo 10: Colluvium soils along the MHT logging roads northeast of Leask Lakes.



Photo 11: Severely weathered bedrock and residual soils along the MHT logging roads.



Photo 12: Poor quality slates exposed along the MHT logging roads.



Photo 13: Highly deformed and weak outcrop of slate along the MHT logging roads.



Photo 14: Typical pyrite occurrence in slates along the northeast area of MHT logging roads.



Photo 15: Slate outcrop in a steep sided creek on the north slope of Harriet Hunt Ridge.



Photo 16: Close up view of a clay seam in the outcrop shown in Photo 15.



Photo 17: Quarry along the MHT logging roads with higher quality greenstone bedrock.



Photo 18: Typical MHT logging roads being utilized as part of the Option 5 corridor.



Photo 19: Typical corduroy construction over soft ground.



Photo 20: Typical corduroy construction with drainage passing through the roadway.



Photo 21: Typical steep sided chasms found along the north slope of Harriet Hunt Ridge.



Photo 22: Leask Ck dividing the existing logging roads. Existing bridge just out of view at photo bottom.



Photo 23: View to the northwest of outlet for Lake 340 from the existing logging roads



Photo 24: Typical bench cut road above Lake 340.



Photo 25: Sidecast fills spilling down towards the shores of Lake 340.



Photo 26: Tributary creek draining towards Heckman Lake. Overflow channels and beaver ponds to photo left.



Photo 27: One of the small lakes with marshy fringe in the floor of Newt Valley.