

MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks Interna	ational Airport	Οι	ıtfall Site I.D.	1a
APDES Tracking No.	AKR_06R0AB76			mple Illection Date & ne	8/17/2021
Inspector Name(s)	Jeremy Lar	ngton			
Weather Conditions/Notes	Raining				
Discharge at Site? (Circle)	☐ Yes	■ No			
Type of Discharge (Check box)	Snowmelt Runoff	Rainfall Runoff			
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 3	Rainfall (Inches)		Time Since 8	Prior Rainfall Event (Days)
Reason if Sample Not Collected Within First 30 Min.	Not practica	ble.			
Additional Comments	None.				

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other			
	Sample taken in clea	an, clear contair	er?	□Yes	□No		
	Sample inspected in	a well-lit area?		□Yes	□No		
	Visual Assessment [Date and Time					
Р				Engineering A	Assistant		
S	ignature:	yter					



MSGP Quarterly Visual Assessment MSGP 6.2

Fairbanks Interna	ational Airport	Οι	utfall Site I.D.	3a
AKR_06R0AB76		Co	llection Date &	8/17/2021
Jeremy Lar	ngton			
Raining				
■ Yes	☐ No			
Snowmelt Runoff	X Rainfall Runoff			
Rainfall Duration (Days) 3	Rainfall (Inches) 1.31		Time Since 8	Prior Rainfall Event (Days)
Not practica	ble.			
None.				
	Jeremy Lar Raining Yes Snowmelt Runoff Rainfall Duration (Days) Not practica	Jeremy Langton Raining Yes No Snowmelt Rainfall Runoff Rainfall Quration (Days) 3 Not practicable.	AKR 06R0AB76 Sa Co Tir Jeremy Langton Raining Yes No Snowmelt Rainfall Runoff Rainfall Duration (Days) 3 Rainfalle. Not practicable.	AKR 06R0AB76 Sample Collection Date & Time Jeremy Langton Raining Yes No Snowmelt Rainfall Runoff Runoff Runoff Rainfall Ouration (Days) 3 Not practicable.

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	Clear	☐ Cloudy	☐ Dark	
Odor	■Absent	□Sewage	□Rotten Eggs	
Clarity	■ Clear	□Cloudy	□Dark	
Floating Solids	■Absent	□Present		
Settled Solids	■Absent	□Present		
Suspended Solids	■Absent	□Present		
Foam	■Absent	□Present		
Oil Sheen	■Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other			
	Sample taken in clea	an, clear contair	er?	■Yes	□No		
	Sample inspected in	a well-lit area?		■Yes	□No		
	Visual Assessment [Date and Time		8/17/21			
			Engineering A	Assistant	: :		
S	ignature: 🏻 💯	Juzten					



MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks Interna	ational Airport	Οι	utfall Site I.D.	4b	
APDES Tracking No.	AKR_06R0AB76		Co	imple bllection Date & ne	8/17/2021 0845	
Inspector Name(s)	Jeremy Lar	ngton				
Weather Conditions/Notes	Raining					
Discharge at Site? (Circle)	■ Yes	☐ No				
Type of Discharge (Check box)	Snowmelt Runoff	X Rainfall Runoff				
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 3	Rainfall (Inches)		Time Since 8	Prior Rainfall Event (Days)	
Reason if Sample Not Collected Within First 30 Min.	Not practicable.					
Additional Comments	None.					

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	Clear	☐ Cloudy	☐ Dark	
Odor	■Absent	□Sewage	□Rotten Eggs	
Clarity	■ Clear	□Cloudy	□Dark	
Floating Solids	■Absent	□Present		
Settled Solids	■ Absent	□Present		
Suspended Solids	■Absent	□Present		
Foam	■Absent	□Present		
Oil Sheen	■ Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other			
	Sample taken in clea	an, clear contair	er?	■Yes	□No		
	Sample inspected in	a well-lit area?		■Yes	□No		
	Visual Assessment [Date and Time		8/17/21 0845			
Ρ				Engineering A	Assistant		
S	ignature: 4 Jun	yter					



MSGP Quarterly Visual Assessment MSGP 6.2

Days <u>)</u>

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	Clear	☐ Cloudy	☐ Dark	
Odor	■Absent	□Sewage	□Rotten Eggs	
Clarity	■ Clear	□Cloudy	□Dark	
Floating Solids	■Absent	□Present		
Settled Solids	■ Absent	□Present		
Suspended Solids	■Absent	□Present		
Foam	■Absent	□Present		
Oil Sheen	■ Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other		
	Sample taken in clea	an, clear contair	er?	■Yes	□No	
	Sample inspected in	a well-lit area?		■Yes	□No	
	Visual Assessment [Date and Time		8/17/21 0930		
Printed Name: Jeremy Langton Ti			Title:	Engineering A	Assistant	
S	ignature: 🏻 🖟 🎢	ngter				



MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks International Airport			ıtfall Site I.D.	5b	
APDES Tracking No.	AKR_06R0AB76		Sample Collection Date & Time		8/17/2021 0948	
Inspector Name(s)	Jeremy Lar	ngton				
Weather Conditions/Notes	Raining					
Discharge at Site? (Circle)	■ Yes	☐ No				
Type of Discharge (Check box)	Snowmelt Rainfall Runoff Runoff					
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 3 Rainfall (Inches)			Time Since 8	Prior Rainfall Event (Days)	
Reason if Sample Not Collected Within First 30 Min.	Not practicable.					
Additional Comments	None.					

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	Clear	☐ Cloudy	☐ Dark	
Odor	■Absent	□Sewage	□Rotten Eggs	
Clarity	■ Clear	□Cloudy	□Dark	
Floating Solids	■Absent	□Present		
Settled Solids	■ Absent	□Present		
Suspended Solids	■Absent	□Present		
Foam	■Absent	□Present		
Oil Sheen	■Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other		
	Sample taken in clea	an, clear contair	er?	■Yes	□No	
	Sample inspected in	a well-lit area?		■Yes	□No	
	Visual Assessment [Date and Time		8/17/21 0948		
Ρ	rinted Name: Jeremy	Langton	Title: _	Engineering A	Assistant	_
S	ignature: 🏻 🛷 🎖	luzter				



MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks Interna	ational Airport	Οι	ıtfall Site I.D.	6a	
APDES Tracking No.	AKR_06R0AB76		Co	mple Illection Date & ne	8/17/2021 0918	
Inspector Name(s)	Jeremy Lar	ngton				
Weather Conditions/Notes	Raining					
Discharge at Site? (Circle)	☐ Yes	■ No				
Type of Discharge (Check box)	Snowmelt Rainfall Runoff Runoff					
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 3	Rainfall (Inches)		Time Since 8	Prior Rainfall Event (Days)	
Reason if Sample Not Collected Within First 30 Min.	Not practicable.					
Additional Comments	None.					

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other		
	Sample taken in clea	an, clear contair	er?	□Yes	□No	
	Sample inspected in	a well-lit area?		□Yes	□No	
	Visual Assessment [Date and Time				
Р	rinted Name: Jeremy	Langton	Title: <u> </u>	Engineering A	Assistant	
S	ignature: 4mg Jung	ter				



MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks Interna	ational Airport	Οι	ıtfall Site I.D.	7c
APDES Tracking No.	AKR_06R0AB76			mple Illection Date & ne	8/17/2021 0900
Inspector Name(s)	Jeremy Lar	ngton			
Weather Conditions/Notes	Raining				
Discharge at Site? (Circle)	☐ Yes	■ No			
Type of Discharge (Check box)	Snowmelt Rainfall Runoff Runoff				
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 3	Rainfall (Inches) 1.31		Time Since 8	Prior Rainfall Event (Days)
Reason if Sample Not Collected Within First 30 Min.	Not practica	ble.	<u>'</u>		
Additional Comments	None.				

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other		
	Sample taken in clea	an, clear contair	er?	□Yes	□No	
	Sample inspected in	a well-lit area?		□Yes	□No	
	Visual Assessment [Date and Time				
Р	rinted Name: Jeremy	Langton	Title: <u></u>	Engineering <i>F</i>	Assistant	_
S	ignature: 4 fm	y ten				



MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks Interna	ational Airport	Οι	utfall Site I.D.	9c
APDES Tracking No.	AKR_06R0AB76		Co	ample ollection Date & me	8/17/2021 0910
Inspector Name(s)	Jeremy Lan	gton			
Weather Conditions/Notes	Raining				
Discharge at Site? (Circle)	☐ Yes	■ No			
Type of Discharge (Check box)	Snowmelt Rainfall Runoff Runoff				
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 3	Rainfall (Inches)		Time Since 8	Prior Rainfall Event (Days)
Reason if Sample Not Collected Within First 30 Min.	Not practica	ble.			
Additional Comments	None.				

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other		
	Sample taken in clea	an, clear contain	er?	□Yes	□No	
	Sample inspected in	a well-lit area?		□Yes	□No	
	Visual Assessment [Date and Time				
Р	rinted Name: Jeremy		Title: <u></u>	Engineering <i>F</i>	Assistant	-
S	ignature:	yter				



MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks International Airport		Outfall Site I.D.		10		
APDES Tracking No.	AKR_06R0AB76			mple Illection Date & ne	8/17/2021 0905		
Inspector Name(s)	Jeremy Lar	ngton					
Weather Conditions/Notes	Raining						
Discharge at Site? (Circle)	☐ Yes	■ No					
Type of Discharge (Check box)	Snowmelt Runoff	☐ Rainfall Runoff					
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 3 Rainfall (Inches) 1.31			Time Since 8	Prior Rainfall Event (Days)		
Reason if Sample Not Collected Within First 30 Min.	Not practicable.						
Additional Comments	None.						

Observation	Description			Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other			
	Sample taken in clea	an, clear contair	er?	□Yes	□No		
	Sample inspected in	a well-lit area?		□Yes	□No		
	Visual Assessment [Date and Time					
Printed Name: Jeremy Langton Title: E				Engineering A	Assistant	: :	
S	ignature: 📗 💯 🎹	yten					



MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks International Airport		Outfall Site I.D.		11		
APDES Tracking No.	AKR_06R0AB76			mple Illection Date & ne	8/17/2021 0850		
Inspector Name(s)	Jeremy Lar	ngton					
Weather Conditions/Notes	Raining						
Discharge at Site? (Circle)	☐ Yes	■ No					
Type of Discharge (Check box)	Snowmelt Runoff	Rainfall Runoff					
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 3 Rainfall (Inches)			Time Since 8	Prior Rainfall Event (Days)		
Reason if Sample Not Collected Within First 30 Min.	Not practicable.						
Additional Comments	None.						

Observation	Description			Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other		
	Sample taken in clea	an, clear contair	er?	□Yes	□No	
	Sample inspected in	a well-lit area?		□Yes	□No	
	Visual Assessment [Date and Time				
Р	rinted Name: <u>Jerem</u> y	Engineering <i>F</i>	Assistant	_		
S	ignature: 4 fm	y ten				